

YI HENG MOTOR WORKSHOP

BLK 1, KAKI BUKIT AVENUE 6
#02-57, AUTOBAY@KAKI BUKIT, SINGAPORE 417883
TEL: 6 5090052 FAX: 6 7479402

24-05-2021

OUR REF NO. SLK 9767L

NKY SERVICES

BLK 539, HOUGANG ST 52,
#02-50,
SINGAPORE 530539

TPA16.

Xiao Chan.

KNAFZ411MH5696603

ESTIMATE BILL FOR VEHICLE NO. SLK 9767L MODEL : KIA CERATO FORTE K3 1.6A

LIST ITEM :

1) BOOT LID	Buckled.		\$ 1,556.40	1254
2) BOOT LID BADGE			\$ 86.00	✓
3) BOOT LID EMBLEM "CERATO"			\$ 64.00	✓
4) BOOT LID EMBLEM "FORTE"		✓	\$ 67.20	✓
5) BOOT LID EMBLEM "K3"		✓	\$ 58.50	✓
6) BOOT LID LOCK	Dand		\$ 211.00	✓
7) BOOT LID STRIKER	✓		\$ 49.00	✓
8) BOOT LID STOPPER (SMALL)		2PCS @\$18.00	\$ 36.00	✓
9) BOOT LID STOPPER (BIG)		2PCS @\$25.00	\$ 50.00	✓
10) BOOT LID LINING CLIPS		9PCS @\$6.50	\$ 58.50	✓
11) BOOT LID HINGE		2PCS @\$172.00	\$ 344.00	✓
12) BOOT LID WEATHERSTRIPE			\$ 286.00	✓
13) TAIL LAMP (LH)	✓		\$ 421.00	✓
14) TAIL LAMP CLIPS (LH)	✓	2PCS @\$10.00	\$ 20.00	✓
15) TAIL LAMP BASE (LH)	✓		\$ 186.00	✓
16) REAR BUMPER	✓		\$ 825.00	698
17) REAR BUMPER CLIPS	✓	8PCS @\$6.50	\$ 52.00	30
18) REAR BUMPER SIDE ATTACHMENT	✓	2PCS @\$67.00	\$ 134.00	67.
19) REAR BUMPER REINFORCEMENT	✓		\$ 438.00	344.
20) REAR BUMPER REINFORCEMENT BRACKET	✓	2PCS @\$122.00	\$ 244.00	122
21) REAR BUMPER REINFORCEMENT PLASTIC BRACKET	✓	4PCS @\$62.00	\$ 248.00	80.
22) REAR BUMPER LOWER DEFUSER	✓		\$ 457.00	347.
23) REAR BUMPER REFLECTOR (LH)	✓		\$ 128.00	✓

24) REAR BUMPER UNDER TRAY (LH) <i>torn</i>		\$ 142.00 ✓
25) REAR BUMPER UNDER TRAY CLIPS (LH) <i>new</i>	10PCS @\$6.50	\$ 65.00 ✓ 10
26) REAR BUMPER REVERSE SENSOR <i>Demd</i>	2PCS @\$286.00	\$ 572.00 ✓ 400
27) REVERSE SENSOR WIRING HARNESS <i>new</i>		\$ 422.00 ✓
28) REAR END PANEL <i>Repair</i>		\$ 586.00 ✓
29) REAR PANEL TOP TRIM <i>Delnd</i>		\$ 211.00 ✓
30) REAR PANEL TOP TRIM CLIPS <i>new</i>	3PCS @\$6.50	\$ 19.50 ✓
31) REAR CHASSIS MEMBER <i>Repair</i>		\$ 680.00 ✓
32) REAR FENDER INNER BOARD (LH) <i>new</i>		\$ 286.00 ✓
33) REAR FENDER INNER BOARD CLIPS (LH) <i>new</i>	5PCS @\$6.50	\$ 32.50 ✓
34) SPARE TYRE PANEL <i>Repair</i>	4959.20	\$ 866.00 ✓
35) SPARE TYRE BOARD <i>torn</i>	4463.28	\$ 324.00 ✓ 179
		\$ 10,225.60
LESS DISCOUNT - 10%		\$ 1,022.56
		\$ 9,203.04

SPECIAL NETT ITEM

1) BOOT LID EMBLEM "C.C" <i>new</i>	56.	\$ 56.00 ✓
2) SPARE TYRE INSULATOR CLOTH <i>new</i>		\$ 350.00 ✓
		\$ 406.00

LABOUR CHARGE

1) TO CHECK WIRING SYSTEM		\$ 50.00 30
2) TO APPLY UNDER SEALING ON AFFECTED AREAS		\$ 120.00 40
3) TO REMOVE & REFIX BOOT LID FIXING & REALIGNMENT		\$ 220.00 60
4) TO REMOVE & REFIX REVERSE SENSOR WITH WIRE HARNESS		\$ 120.00 50
5) TO REMOVE & REFIX PETROL TANK, PIPING SYSTEM, BRACKET & ETC		\$ 220.00 ✓
6) TO REMOVE CUSHION, FLOORBOARD, TRIMBOARD, ROOF LINING, GARNISH AND ETC		\$ 220.00 60
7) TO REMOVE & REFIX REAR EXHAUST SILENCER, PIPING, BRACKET, MOUNTING ETC		\$ 180.00 ✓
8) TO REPLACE NEW PARTS, CUT, WELD, KNOCK ETC	1440	\$ 1,540.00 600
9) TO RESPRAY ON AFFECTED AREAS		\$ 1,320.00 600
		\$ 3,990.00

GRAND TOTAL : \$ 13,599.04

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total: 5959.28
L/S: A7K w/s 25/05/21
05 Days.