



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Reg No : 1977014696

GST Reg No : MR-8500111-X

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /Ng Choon Huat (Huang Junfa) Reg No/Reg Date SLB5347P / 13/04/201 Date In/Mileage / 110811 Chassis No JMFXTGA2WFZC12804 Engine No 4B11RG7588 Make/Model MIT/ASX 2.0 CVT 2WD (N04) Colour/Trim P02 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Qty	Unit Price	Disc%	Amount
KAX00008	Credit	24/05/2021/ 16:30	BLE	261 / Edwin Caina	11325				
Description of Goods / Services						Qty	Unit Price	Disc%	Amount
E PNT88000						4 X 450			3200.00
RENEW FRT BUMPER, FRT SUPPORT & BONNET									1800
REPAIR LHF FENDER & RH FENDER									1750.00
E PNT98000						5 X 350			100.00
RESPRAY FRT BUMPER, BONNET, FRT SUPPORT, LHF FENDER & RH FENDER									100.00
E PNT88000						(phm)			80.00
REMOVE & REFIT AC CONDENSER & RADIATOR									80.00
A 25000001									30.00
TOP UP AIRCON GAS									30.00
A 54900099									120.00
CHECK WIRING ELECTRICAL SYSTEM									120.00
A 10028901									50.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST									50.00
USING HI-SCAN PRO TEST									50.00
M SUNDRY									
SUPPLY FRT NUMBER PLATE WITH CASING - BT									40 80.00
M SUNDRY									
APPLY ANTI CORROSION ON AFFECTED AREAS									40 80.00
M SUNDRY									
SUPPLY BODY PNL SEALANT									20 30.00
M SUNDRY									
Sundry									
M FACE, FR BUMPER / BR						1.00	1041.00	23.00	801.57
M GRILLE, RADIATOR / CUT BR (chrome)						1.00	266.00	23.00	204.82
M GARNISH, FR BUMPER, CTR / BR						1.00	845.00	23.00	650.65
M GARNISH, FR BUMPER, LH X N/A						1.00	27.00	23.00	20.79
M GARNISH, FR BUMPER, RH X N/A						1.00	27.00	23.00	20.79
M REINFORCEMENT, FR BUMPER / BT						1.00	53.00	23.00	40.81
M CORE, FR BUMPER / BR						1.00	12.00	23.00	9.24
M CORE, FR BUMPER / BR BT (Bumper to wheel)						1.00	14.00	23.00	10.78
M REINFORCEMENT, FR BUMPER / CR4 (top rim)						1.00	417.00	23.00	321.09
M COVER, FR BUMPER / CR4 (top rim)						1.00	66.00	23.00	50.82
M CLIP, ENG ROOM COVER X N/A						5.00	4.00	23.00	15.40

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /Ng Choon Huat (Huang Junfa) Reg No/Reg Date SLB5347P / 13/04/201 Date In/Mileage / 110811 Chassis No JMFXTGA2WFZC12804 Engine No 4B11RG7588 Make/Model MIT/ASX 2.0 CVT 2WD (N04) Colour/Trim P02 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	24/05/2021/ 16:30	BLE	261 / Edwin Caina	11325			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M COVER, HEADLAMP SUPT PANEL				BR	1.00	135.00	23.00	103.95
M GRILLE, FR BUMPER	BR	(1st gnt)			1.00	319.00	23.00	245.63
M HOOD	DO				1.00	822.00	23.00	632.94
M HINGE, HOOD, LH	BT				1.00	68.00	23.00	52.36
M HINGE, HOOD, RH	BT				1.00	68.00	23.00	52.36
M INSULATOR, HOOD	X NIM				1.00	127.00	23.00	97.79
M CLIP, HOOD INSULATOR	X NIM				8.00	3.00	23.00	18.48
M WEATHERSTRIP, HOOD SIDE	X NIM				2.00	19.00	23.00	29.26
M LATCH, HOOD	X NIM				1.00	76.00	23.00	58.52
M PNL, HEADLAMP SUPT, UPR LH	BT				1.00	78.00	23.00	60.06
M PNL, HEADLAMP SUPT, UPR RH	BT				1.00	78.00	23.00	60.06
M PANEL, HEADLAMP SUPPORT					1.00	368.00	23.00	283.36
M MOULDING, FR WHEEL ARCH, LH					1.00	132.00	23.00	101.64
M MOULDING, FR WHEEL ARCH, RH					1.00	132.00	23.00	101.64
M HEADLAMP ASSY, LH	BR				1.00	828.00	23.00	637.56
M HEADLAMP ASSY, RH	BR				1.00	828.00	23.00	637.56
M CONDENSER ASSY, A/C REFRIGE	BT				1.00	1140.00	23.00	877.80
M PIPE, A/C CONDENSER OUTLET	BT				1.00	202.00	23.00	155.54
M HOSE, A/C COMPR DISCHARGE	X NIM				1.00	197.00	23.00	151.69
M RADIATOR ASSY	BT				1.00	1157.00	23.00	890.89
M CAP ASSY, RADIATOR	X NIM				1.00	91.00	23.00	70.07
M FAN, COOLING LH	X NIM				1.00	74.00	23.00	56.98
M FAN, COOLING, RH	X NIM				1.00	70.00	23.00	53.90
M SHROUD, COOLING FAN	X NIM				1.00	274.00	23.00	210.98
M MOTOR, COOLING FAN LH	BT				1.00	474.00	23.00	364.98
M MOTOR, COOLING FAN, RH	X NIM				1.00	467.00	23.00	359.59
M DUCT, A/CLNR INTAKE	X NIM				1.00	227.00	23.00	174.79

Estimate

SURVEYOR NAME: Steve CLKK

SURVEYOR SIGNATURE: 25/5/21, 12.19pm

DATE: 00-M AL

REMARKS: Express -?

SURVEYOR NAME: Steve (LKK)

SURVEYOR SIGNATURE: 25/5/21, 12.17pm

DATE: 00-M AL

REMARKS: Express -?

Confirm & accepted by

Auto Consultant's hence notify
 Repairer of the following:
 resurvey before/after spray painting
 display damaged part(s) during resurvey
 prices are subject to confirmation

P/P, My B/L 5/1
 7 dgs

Nett 14,207.14
 7% GST on 14207.14 994.50
Total Payable 15,201.64

Authorized Signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
 Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include
 any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered
 after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a
 deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or
 cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing
 the rubber seal or other repair requiring the removal of the windscreen.