

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

CHNG ZHENG CHANG
BLK 207 BISHAN ST 23 #03-399
SINGAPORE 570207

Contact : 90629008, 86930683

TP SMART

Hui Zhen

ESTIMATE

Repair Code : CLM15248

Date in : 24/05/2021

Vehicle Num. : SKE5680Y

Model : TOYOTA VIOS E AUTO

Chassis/Eng# : MR053HY9305290419/1NZY469518

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR AXLE <i>the m</i>	1	2882.30	2,882.30 <i>+</i>
REAR BUMPER <i>torn</i>	1	561.80	561.80 <i>✓</i>
REAR BUMPER SIDE RETAINER L/R <i>RH m</i>	2	102.80	205.60 <i>102.80</i>
REAR RH DOOR <i>dent</i>	1	940.70	940.70 <i>✓</i>
REAR RH DOOR BLACK TAPE <i>the m</i>	1	43.80	43.80 <i>✓</i>
REAR RH DOOR GLASS REGULATOR <i>the m</i>	1	253.40	253.40 <i>+</i>
REAR RH DOOR HINGE (LOWER) <i>the m</i>	1	97.50	97.50 <i>+</i>
REAR RH DOOR HINGE (TOP) <i>the m</i>	1	97.50	97.50 <i>✓</i>
REAR RH DOOR INNER TRIM BOARD <i>the m</i>	1	580.90	580.90 <i>+</i>
REAR RH DOOR PROTECTOR <i>the m</i>	1	92.00	92.00 <i>✓</i>
REAR RH DOOR PROTECTOR CHROME MOULDING <i>the m</i>	1	25.10	25.10 <i>✓</i>
REAR RH DOOR WEATHER STRIP <i>the m</i>	1	180.70	180.70 <i>+</i>
REAR RH FENDER ARCH PANEL <i>Regis</i>	1	881.40	881.40 <i>+</i>
REAR RH FENDER INNER SHIELD <i>the m Deband</i>	1	98.70	98.70 <i>+</i>
REAR RH SHOCK ABSORBER <i>the m</i>	1	160.00	160.00 <i>+</i>
REAR RH TAILLAMP <i>the m</i>	1	342.80	342.80 <i>+</i>
REAR RH TAILLAMP INNER BLACK GASKET <i>the m</i>	1	35.70	35.70 <i>+</i>
REAR RH WHEEL BEARING <i>the m</i>	1	790.30	790.30 <i>+</i>

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

CHNG ZHENG CHANG
BLK 207 BISHAN ST 23 #03-399
SINGAPORE 570207

Contact : 90629008, 86930683

ESTIMATE

Repair Code : CLM15248

Date in : 24/05/2021

Vehicle Num. : SKE5680Y

Model : TOYOTA VIOS E AUTO

Chassis/Eng# : MR053HY9305290419/1NZY469518

		Subtotal before discount	1864.90	8,270.20
Percentage discount 25%			1398.67	2,067.55
		Sub-total 1		6,202.65
REAR BUMPER CLIPS - SET	Nec	1	80.00	30 80.00
REAR RH 185/60R15 TYRE	Nbe m	1	380.00	x 380.00
REAR RH DOOR INNER TRIM BOARD CLIPS - SET	Nbe Nec	1	50.00	x 50.00
REAR RH FENDER INNER SHIELD CLIPS - SET	Nec	1	40.00	20 40.00
REAR RH SPORT RIM	ct	1	700.00	400 700.00
REAR RH TAILLAMP CLIPS - SET	Nbe Nec	1	25.00	x 25.00
		Subtotal before discount		1,275.00
Percentage discount 0%				0.00
		Sub-total 2		1,275.00
		Parts-total		7,477.65

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.	80.00
To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knuckle arm, wheel bearing, bearing hub and etc.	x 300.00
To road test driving, check and resetting wheel alignments system.	80 120.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	x 100.00
To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.	50.00

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

CHNG ZHENG CHANG
BLK 207 BISHAN ST 23 #03-399
SINGAPORE 570207

Contact : 90629008, 86930683

ESTIMATE

Repair Code : CLM15248

Date in : 24/05/2021

Vehicle Num. : SKE5680Y

Model : TOYOTA VIOS E AUTO

Chassis/Eng# : MR053HY9305290419/1NZY469518

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total	2,630.00
Parts & Labour Total	10,107.65

1450 700 900.00
500 1,000.00
40 80.00

*** This is a computer-generated document which requires no signature.***

page 3

Adrian Li
L/s 25/05/21.

05 Days.

Total: 3298.67
L/s: 2.6K. ✓

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: