

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

ESTIMATE

GST Reg No : MR-8500111-X

: 197701469G Invoice Name & Address	Owner Name & Vehicle Info		
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892			

		Date/Time Printed	CSE	Operator		WIP No			
Account No	Terms	25/05/2021/ 11:39	QUK	289 / Patrick Lee		11354			
80000x4)	Credit	Description of Good		Walliamore D. M. Wolffer Machine San	Qty	Unit Price	Disc%	15231650	ount
				0	1,000,000			2025	3600.00
E PNT88000	ı	- INMED FOT DU CEN	DED DH FR	F REAR DOOR RH REA	R			2925	
REPLACE	HOOD, FR	H SIDE MIRROR ASSY &	AFFECTED A	AREAS	6-5 X 4	SO			00
				•	0 0 1	4-0			3150.00
PNT98000	INT HOOK	ON HOOD FRT BUMPER	FRT RH FI	ENDER, RH FRT & REAR				2530	
SPRAT PA	DEAD OUR	ARTER PANEL RH A-PI	LLAR, RH W	ING MIRROR COVER 7x 3	50 1 CA			· Contraction	
& FRT, B	NEAR QUA	MILK FINCES TO A	15000000000000000000000000000000000000	80 7XJ	70 1 10				120.00
SUNDRY	JUINTI								120.00
TO APPLY	BODY SEA	ALANT ON AFFECTED AR	EAS						240.00
DNITEROOD									F.17.75
TO TRANSI	ER RH FF	RT & REAR ATTACHMENT	S TO NEW P	ANEL	Π_{\sim}				30.00
				ima'	11/0	1			
CHECK ON	WIRING 8	CHASSIS ELECTRICAL	SYSTEM	1111110	1110	7			120.00
10020001		1 - 1	~//					1	
TO CARRY	OUT DIAG	GNOSTIC CHECK USING	HI-SCAN PR	J TEST					
USING HI	-SCAN PRO	0 IESI						49	160.00
SUNDRY	N DUCT I	DOCUCNTION						00	
	KM KUSI I	PREVENTION						20	50.00
SUNDRY									30.00
SUNDRIES SUNDRY									30.00
TO TRANS	FFR FRT I	LH RIM INCLUDING BAL	ANCING						120.00
WHEEL AL TG	NMENTRE								120,0
To Condu	ct Compu	terize Full Wheel Al	ignment		9 E				240.00
PNT88000	ž.			FACILITATE REPAIR (ahoto)				
TO REMOV	E AND IN	STALL REAR WINDSHIEL	D GLASS 10	FACILITATE REPAIR (A				80.00
4 SUNUKI								.00	전, 발설(1844)
TO APPLY	WINDSHI	ELD SEALANT						199	150.00
E PNT88000	F 4410 TH	CTALL DEAD SEAT COMP	ARTMENT TO	FACILITATE REPAIR	(bush)			120	150.00
TO REMOV	E AND IN	STALL KEAR SEAT COMP	and the same of the	HATANA THE PER	(161)			120	150.00
E PNT88000	E AND TN	STALL REAR BOOT COMP	ARTMENT TO	FACILITATE REPAIR	Ch. A)	707.00	23.00		567.49
	- 00°				1.00	/3/.00	23.00	10	307.73

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a after work has started and needed for repairs or replacement of the work. Payment for this may be made in cash, credit card or deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen. the rubber seal or other repair requiring the removal of the windscreen. Page 1 of 2



N- - 1077014696

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info		
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name Reg No/Reg Date Date In/Mileage Chassis No Engine No Make/Model Colour/Trim	/Cheng Geok Chin EU6008U / 23/03/201 24/05/2021/ 19925 MMBSTA13AJH001861 3A92UGS5312 MIT/18MY ATTRAGE 1.2 CVT P57 WINE RED PEARL / BK BLACK	

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No		
KAX00008	Credit	25/05/2021/ 11:39	QUK	289 / Patrick I	_ee	11354		
K. IACCCCO	0,00,0	Description of Good	s / Services		Qty	Unit Price		Amount
M FACE, FR	SUMPER	2 00	THE DESIGNATION OF THE SECOND		1.00		23.00	543.62
M GARNISH, F			190)		1.00		23.00	97.79
M HEADLAMP		- GR			1.00		23.00	510.51
M FENDER.FR	RH /	M			1.00		23.00	385.00
M SHIELD, FR	WHEELHO	DUSE, RH / CRY			1.00		23.00	75.46
GARNISH, F	R PILLAR	RH / MIS			1.00		23.00	23.10
M GARNISH, F		q			1.00		23.00	50.0
MIRROR AS		PH - CN7			1.00		23.00	493.5
COVER, DOO	R MIRROR	OTR RH / MIJ			1.00		23.00	87.0
PANEL ASS	Y,FR DOO	R,RH / 00			1.00	1001.00		770.7
		T LINE, RH LIZ BT	П		T1.00		23.00	57.7
W/STRIP,F		G,OTR RH	2551	11006	7 5 1.00		23.00	110.8
HANDLE, FR			7	111116	1.00		23.00	77.7
PANEL ASS			3) U.L		(1.00)		23.00	618.3
MLDG, R/DR		T LINE RH . "			1.00		23.00	50.8
W/STRIP,R					1.00		23.00	104.7
W/STRIP,R					1.00		23.00	42.3
HANDLE, FR					1.00		23.00	77.7
PANEL,QTR					1.00	767.00	23.00	590.5
WHEEL DISC		CUT (FM RH)			1.00	687.00	23.00	528.9
					1.00	29.00	23.00	22.3
					1.00	29.00	23.00	22.3
EMBLEM EC		NC 0			1.00	17.00	00.00	17.0
					1.00	1643.00	20.00	1314.4
M UNPAINTED BOD	DODTKI	· / ix		Steve	(LKK) 25/	5/21, 1.	apm	
				3 ,	ดูด-	N-1 A		
						eri - 1	_	
					PI	1	BIL SE	1
			122	17 day	Γ	, 10		J
Confirm & ac	cepted b	to hence notify following:		J.				
the Repa	iref of life	following:	1			NA.	tt	15,480.3
 lo resurv 	ey belorelall	er spray ponting	1		TU CCT	15480.		1083.6
▲ To displa	y damaged p	art(s) during resurvey	1		7% GST on	13400.	30	2000.0
Parts price Third price	es are subje	ct to confirmation in a "Without Prejudice" basis			.	tal Payab	le.	16,564.0
• Iniro par	ty survey is to	(s) is allowed	i		210	ital rayab	14.5	,,
- No mega	i modification	and company stamp						

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after world has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.