

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

MITSUBISHI

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info			
AIG Asia Pacific Insurance Pte.	Cust No/Name	/Cheng Geok Chin		
Ltd.	Reg No/Reg Date	EU6008U / 23/03/201		
MOTOR CLAIM DEPT	Date In/Mileage	24/05/2021/ 19925		
78 SHENTON WAY #09-16 AIG BUILDING	Chassis No	MMBSTA13AJH001861		
SINGAPORE 079120	Engine No	3A92UGS5312		
Contact No 6419 1892	Make/Model	MIT/18MY ATTRAGE 1.2 CVT		
	Colour/Trim	P57 WINE RED PEARL / BK BLACK		

Account No	Terms	Date/Time Pr	inted	CSE	Operator		WIP No		
KAX00008	Credit	25/05/2021/	11:39	QUK	289 / Patrick Lee		11354		
		Description	of Good	s / Service	S	Qty	Unit Price	Disc%	Amount
QUARTER E PNT98000 SPRAY PA DOOR, RH	PANEL, RE INT WORK REAR QUA	SIDE MIRROR	ASSY & BUMPER	AFFECTED, FRT RH I	RT & REAR DOOR, RH REA AREAS FENDER, RH FRT & REAR WING MIRROR COVER	AR			3600.00
& FRT B M SUNDRY		LANT ON AFFE	CTED AD	FAC					120.00
E PNT88000		RT & REAR ATT			PANFI	2000			240.00
A 54900099		CHASSIS ELE	/	245	Ilma'	176	9)		30.0
A 10028901	OUT DIAG	NOSTIC CHECK	7	2) [RE	9		120.0
M SUNDRY									160.0
M SUNDRY		PREVENTION							50.0
SUNDRIES M SUNDRY									30.0
TO TRANS A WHEELALIG		H RIM INCLUD	ING BAL	ANCING					120.0
E PNT88000		erize Full W							240.0
M SUNDRY			NDSHIEL	D GLASS TO	O FACILITATE REPAIR				80.0
E PNT88000		LD SEALANT							150.0
E PNT88000					O FACILITATE REPAIR				150.0
TO REMOV M HOOD	E AND INS	STALL REAR BO	OT COMP	ARTMENT TO	O FACILITATE REPAIR	1.00	737.00	23.00	567.4

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

MITSUBISHI MOTORS

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info			
AIG Asia Pacific Insurance Pte.	Cust No/Name	/Cheng Geok Chin		
Ltd.	Reg No/Reg Date	EU6008U / 23/03/201		
MOTOR CLAIM DEPT	Date In/Mileage	24/05/2021/ 19925		
78 SHENTON WAY #09-16 AIG BUILDING	Chassis No	MMBSTA13AJH001861		
SINGAPORE 079120	Engine No	3A92UGS5312		
Contact No 6419 1892	Make/Model	MIT/18MY ATTRAGE 1.2 CVT		
	Colour/Trim	P57 WINE RED PEARL / BK BLACK		

Account No	Terms	Date/Time Pr	inted	CSE	Oper	rator		WIP No		
KAX00008	Credit	25/05/2021/	11:39	QUK	289	/ Patrick	Lee	11354		
		Description	of Goods	s / Services			Qty	Unit Price	Disc%	Amount
M FACE, FR							1.00	706.00	23.00	543.6
M GARNISH,		R,RH					1.00	127.00	23.00	97.7
M HEADLAMP							1.00	663.00	23.00	510.5
M FENDER, FI	R RH						1.00	500.00	23.00	385.0
M SHIELD, FI	R WHEELHO	OUSE,RH					1.00		23.00	75.4
M GARNISH,	FR PILLAF	R,RH					1.00	30.00	23.00	23.1
M GARNISH,	FR FENDER	2					1.00		23.00	50.0
M MIRROR AS	SSY, DOOR,	RH					1.00	641.00		493.5
M COVER, DO	OR MIRROR	R,OTR RH					1.00	113.00		87.0
M PANEL ASS	SY, FR DOO	OR,RH					1.00	1001.00		770.7
				- F	1		1.00		23.00	57.75
M W/STRIP,		IG.OTR RH		sti	IT	M	1.00	144.00		110.8
M HANDLE, FI		ITSIDE RH	-	271	110	1015	1.00	101.00		77.7
M PANEL ASS		OR RH		D) [[11111	1 (4.60	7 803.00		618.3
		T LINE,RH				и и С	1.00		23.00	
M W/STRIP,							1.00		The second secon	50.8
M W/STRIP,								136.00		104.7
M HANDLE, FI							1.00		23.00	42.3
M PANEL,QTI		TISTUL, KII					1.00	101.00		77.7
M WHEEL, DIS							1.00	767.00		590.5
M TAPE, FR I		I DII					1.00	687.00		528.9
		•					1.00		23.00	22.3
M TAPE, RR I		1, KH					1.00		23.00	22.3
M EMBLEM E							1.00		00.00	17.0
M UNPAINTE) RODAKI	2					1.00	1643.00	20.00	1314.4
Confirm & a	ccepted b	у								
							7% GST on	Ne ⁻ 15480.:		15,480. 1083.
							T	otal Payab	le	16,564.
								I wyub		10,00410
Authorized	signatory	and company	stamp							

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.