

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21006133/APA3Q2
Date: 18/11/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700058845
Claimant Vehicle No :	FBE4149D	Insured Vehicle No :	SCU9818C
Date of Loss:	18/05/2021	Nature of Claim:	TP
		Claim No:	1095988913SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBE4149D		
Make & Model:	YAMAHA FINO 115, 114cc	Engine No:	4D0822781
Reg. Date:	16/04/2010 (Man. Year: 2009)	Chassis No:	4D0822781
Colour:	Brown	Odometer:	16401 km
Engine Capacity:	114 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	110/70 R12	Rear Tyre Size:	120/70 R12
Front Left Side:	IRE 6 mm	Rear Left Side:	IRE 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,655.00	1,774.10	880.90	33.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,190.00	650.00	540.00	45.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,845.00	2,424.10	1,420.90	36.95
Approved Total (Overridden) (S\$)		1,900.00		

(S\$)	3,845.00	1,900.00	1,945.00	50.59
+ GST 7.00/7.00% (S\$)	269.15	133.00	136.15	50.59
Nett Amount (S\$)	4,114.15	2,033.00	2,081.15	50.59
+ Loss of Use (4.0 x S\$30.00/day) (S\$)		120.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,160.45		
Global Sum Settlement (S\$)		2,150.00		

INSPECTION

Date of Assignment: 25/05/2021

Date Inspected: 25/05/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Kivile Enterprise (HQ)
 BLK 3007 UBI RD 1 #01-408
 Singapore 408701

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE BAR	Not Necessary	80.00 F	*- FL
2	1		*MIRROR	Missing	52.00 F	*52.00 FL
3	1		*BRAKE LEVER RH	Not Necessary	22.00 F	*- FL
4	1		*BRAKE LEVER LH	Broken	22.00 F	*22.00 FL
5	1		*BALANCER	Not Necessary	36.00 F	*- FL
6	1		*HEADLIGHT	Cracked	150.00 F	*150.00 FL
7	1		*FRONT FAIRING	Cracked	220.00 F	*220.00 FL
8	1		*FRONT FAIRING LOGO	Necessary	60.00 F	*60.00 FL
9	1		*FRONT MUDGUARD	Cut	80.00 F	*80.00 FL
10	1		*HANDLE GRIP	Not Necessary	40.00 F	*- FL
11	1		*RIM	Not Necessary	280.00 F	*- FL
12	1		*DISC	Not Necessary	180.00 F	*- FL
13	1		*FORK	Bent	360.00 F	*360.00 FL
14	1		*FORK LOWER BRACKET	Damaged	160.00 F	*160.00 FL
15	1		*STEERING CONE	Necessary	120.00 F	*120.00 FL
16	1		*FOOTREST PEDAL	Cut	85.00 F	*85.00 FL
17	1		*LOWER FAIRING	Cut	65.00 F	*65.00 FL
18	1		*FRONT FAIRING LOWER GARNISH	Cracked	65.00 F	*65.00 FL
19	1		*REAR FOOTREST RH	Cut	45.00 F	*45.00 FL
20	1		*SIDE COVER RH	Repair	68.00 F	*- FL
21	1		*FRONT POCKET COVER	Cracked	60.00 F	*60.00 FL
22	1		*FRONT POCKET GARNISH	Cracked	125.00 F	*125.00 FL
23	1		*FRONT FAIRING STAY	Bent	80.00 F	*80.00 FL
24	1		*FRONT NUMBER PLATE	Missing	20.00 FS	*20.00 FS
25	1		*IU	Cut	180.00 FS	*180.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,655.00	1,949.00
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	174.90
Total Parts (\$)	2,655.00	1,774.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	FRONT BODY FRAME REPAIR	New	380.00	200.00
2	FRONT BODY FRAME RESPRAY	New	280.00	200.00
3	LABOUR	New	480.00	200.00
4	TRANSPORT	New	50.00	50.00
Gross Labour Cost (\$\$)			1,190.00	650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >