

BLK 3007 UBI RD 1 #01-408, SINGAPORE 408701

TEL: 6748 8645 FAX: 6748 2533

EMAIL: kivilepc@gmail.com

ROC NO.: 53114844X GST REG NO.: M90370110N

TPAIG

Xiao Tony

FBE

Vehicle No.: FBD4149D yamaha fino 115

Handle Bar	7HP 115	80	✓
Mirror	missing	52	✓
Brake Lever RH	115	22	+
Brake Lever LH	Broken.	22	✓
Balance	115	36	+
Headlight	cracked	150	✓
Front Fairing	cracked	220	✓
Front Fairing Logo	115	60	✓
Front Mudguard	115	80	✓
Handle Grip	115	40	+
Rim	115	280	+
Disc		180	+
Fork	Bent	360	2
Fork Lower Bracket	115	160	2
Steering Cone	115	120	2
Footrest Pedal	115	85	✓
Lower Fairing	115	65	✓
Front Fairing Lower Garnish	cracked	65	✓
Rear Footrest RH	115	45	✓
Side Cover RH	Repair	68	+
Front Pocket Cover	cracked	60	✓
Front Pocket Garnish	cracked	125	✓
Front Fairing Stay	Bent	80	✓
Front Body Frame Repair		380	200
Front Body Frame Respray		280	200
Front Number Plate	Missing	20	✓ (SN)
IU	115	180	✓ (SN)
Labour		480	200
Transport		50	✓
Total		3795	

Parts: 1749

Len 16%: 1574.10

Special Net: 200 (Number Plate + 115)

Labour: 650

Total: 2424.10

L/S: 1.9K

Adrian Ly

96893735

L/S 25/05/21

04 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: