



Exceptional Journeys

Surveyor : STEVE LKK
Claim : AIG OD
DOA : 25.05.2021
Emailed : 05.07.2021, 11.50am
Date Survey : 25.05.2021

VEHICLE NO : SKU 7703 T
MODEL : KIA SPORTAGE 2.0
WIP : 33769

Material	:	\$	<u>2,077.60</u>
Labour	:	\$	<u>1,790.00</u>
Sub-Total	:	\$	<u>3,867.60</u>
	:	\$	<u>-</u>
Less Excess	:	\$	<u>600.00</u>
Total	:	\$	<u>3,267.60</u>
GST 7%	:	\$	<u>228.73</u>
Grand Total	:	\$	<u>3,496.33</u>
Finalise By/Date	:		<u>LOI / 05/07/2021</u>

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
+ 0 Days (0) Public Holiday
TOTAL DAYS REPAIR TOOK = 0

☐ TP claim _____

☐ Claim GIA / LTA fee _____

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others _____

☐ Third Party Report - _____

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 21/06/2021	Cust No/Name	/Huang Ying
	Reg No/Reg Date	SKU7703T / 17/08/2015
	Date In/Mileage	21/06/2021/ 101615
	Chassis/Package	KNAPC81AMF7779063 /#
	Engine No	G4NAFH826744
	Make/Model	KIA/SPORTAGE 2.0 A STANDARD
	Colour/Trim	E6S / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	05/07/2021/ 09:11	BLK	260 / AiTing	33769

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE RH FRONT, RH REAR DOOR, RH SKIRT, REPAIR ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME				✓ 680.00
E PNT98000 RESPRAY ON RH FRONT, RH REAR DOOR, AND ALL OTHER AFFECTED AREAS TO THE SAME				✓ 700.00
E PNT88000 TRANSFER RH FRONT & RH REAR ATTACHMENTS TO NEW PANEL				✓ 240.00
A 54900099 CHECK ON WIRING & CHASSIS ELECTRICAL SYSTEM				✓ 30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE				✓ 120.00
M SUNDRY SUNDRIES				✓ 20.00
X EXC INSURANCE EXCESS				-600.00
X PANEL ASSY-FRONT DOOR,RH	1.00	✓ 1115.00	20.00	892.00
X PANEL ASSY-REAR DOOR,RH	1.00	✓ 891.00	20.00	712.80
X TAPE-FR DR BLACK FRAME RR RH	1.00	✓ 26.00	20.00	20.80
X TAPE-RR DR BLACK FRAME FR,RH	1.00	✓ 25.00	20.00	20.00
X BLACK TAPE-FR DR FRAME UPR,RH	1.00	✓ 26.00	20.00	20.80
X BLACK TAPE-RR DR FRAME UPR,RH	1.00	✓ 22.00	20.00	17.60
X GARNISH ASSY-QTR SIDE,RH	1.00	✓ 125.00	20.00	100.00
X MOULDING ASSY-SIDE SILL,RH	1.00	✓ 320.00	20.00	256.00
X CLIP-SIDE GARNISH MTG	10.00	3.00	20.00	24.00
X FILM-RR DR ANTI CHIPPING,RH } Supp.	1.00	17.00	20.00	13.60
Z TEXT AIG OD CLAIM DOA : 25.05.21 SURVEYOR STEVE LKK 25.05.21 POLICY NO : 2100424779-05 REPAIR 04 DAYS				
Guarantee Your Warranty, Maintain with Cycle & Carriage!				

Parts	2,077.60	Nett	3,267.60
Labour	1,770.00	7% GST on	228.73
Standard Menu	0.00		
Specialist Job	0.00	Total Payable	3,496.33
Diagnostics Job	0.00		
Sundry/Others	-580.00		
Total(w/o GST)	3,267.60		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



Exceptional Journeys


INSURANCE CO. : AIG

Supplementary Parts For Registration No.: SKU 7703 T

<u>Materials</u>		<u>Cost (\$)</u>
1	Clips (x10) <i>hec</i>	30.00 ✓
2	Film-RR Dr anti chipping, RH <i>hec</i>	17.00 ✓
Total		47.00
Less 20% discount		9.40
Total after discount		37.60
7% GST		2.63
Grand total		<u>40.23</u>

Thank You.

Yours faithfully


LOI AI TING
SENIOR OFFICER - ADMIN
KIA SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240

CAR NO: SKU7703T

CAR NO: SKU7703T

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	RHR Door Film	? / SUPP		mc	7 Nov 22/8/21
2	clip 10 sill panel	? / SUPP		mc	
3		? / SUPP			
4		? / SUPP			
5		? / SUPP			
6		? / SUPP			
7		? / SUPP			
8		? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

	DATE	TAKEN BY
PHOTO BEFORE PAINT	12/16/23	Steve
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBOARD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: SPORTAGE 2.0 A

SURVEYOR: STEVE LKK



HOME

Online



SPORTAGE(SL)/2015/G 2.0 MPI..

VCI



Fault Code Searching

Rescan

Save



BCM



SJB



SMK

9/9

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ESP	No Current DTC	Good
AIRBAG	No Current DTC	Good
AIRCON	No Current DTC	Good
EPS	No Current DTC	Good

System	DTC	Description	State
--------	-----	-------------	-------

No Current DTC

S/W Ver.

M-E-K-01-00-0248

VCI Ver.

02.54

ECU Ver.

M-E-K-01-00-0189

OS Ver.

Android 10