



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /Huang Ying Reg No/Reg Date SKU7703T / 17/08/201 Date In/Mileage / 0 Chassis No KNAPC81AMF7779063 Engine No G4NAFH826744 Make/Model KIA/SPORTAGE 2.0 A STANDARD Colour/Trim E6S / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	25/05/2021/ 09:50	QUK	282 / Kevin Leong	33769			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE RH FRT & REAR DOOR, RH ROCKER PANEL & AFFECTED AREAS					1.5 days + 80 (RH strty)			680 1600.00
E PNT98000 SPRAY PAINT WORK ON RH FRT & REAR DOOR					2 X 350			700 1120.00
E PNT88000 TO TRANSFER RH FRT & REAR ATTACHMENTS TO NEW PANEL								240.00
M SUNDRY TO PERFORM RUST PREVENTION								80.00
A 54900099 CHECK ON WIRING & CHASSIS ELECTRICAL SYSTEM								30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								120.00
M SUNDRY SUNDRIES								20 50.00
M SUNDRY TO SUPPLY RH ANTI-FILM								25.00
M PANEL ASSY-FRONT DOOR, RH					1.00	1115.00	20.00	892.00
M PANEL ASSY-REAR DOOR, RH					1.00	891.00	20.00	712.80
M TAPE-FR DR BLACK FRAME RR RH					1.00	26.00	20.00	20.80
M TAPE-RR DR BLACK FRAME FR, RH					1.00	25.00	20.00	20.00
M BLACK TAPE-FR DR FRAME UPR, RH					1.00	26.00	20.00	20.80
M BLACK TAPE-RR DR FRAME UPR, RH					1.00	22.00	20.00	17.60
M GARNISH ASSY-QTR SIDE, RH					1.00	125.00	20.00	100.00
M MOULDING ASSY-SIDE SILL, RH					1.00	320.00	20.00	256.00
M GARNISH ASSY-RR DR RR FRAME, RH					1.00	116.00	20.00	92.80
M W/STRIP ASSY-FR DR BELT O/S RH					1.00	53.00	20.00	42.40

Estimate

Steve CLKK 25/5/21, 10-09am
4 days
00- Not PL
Ex circi - ?

Estimate

Steve CLKK 25/5/21, 10:09am

DD- Not AL

Ex car - ?

4 days

Confirm & accepted by
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis

Authorized signatory and company stamp

P/P, Py Bel SK
Nett 5,440.20
7% GST on 5440.20 380.81
Total Payable 5,821.01

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.