



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/Huang Ying
	Reg No/Reg Date	SKU7703T / 17/08/201
	Date In/Mileage	/ 0
	Chassis No	KNAPC81AMF7779063
	Engine No	G4NAFH826744
	Make/Model	KIA/SPORTAGE 2.0 A STANDARD
	Colour/Trim	E6S / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	25/05/2021/ 09:50	QUK	282 / Kevin Leong	33769		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE RH FRT & REAR DOOR, RH ROCKER PANEL & AFFECTED AREAS							1600.00
E PNT98000 SPRAY PAINT WORK ON RH FRT & REAR DOOR							1120.00
E PNT88000 TO TRANSFER RH FRT & REAR ATTACHMENTS TO NEW PANEL							240.00
M SUNDRY TO PERFORM RUST PREVENTION							80.00
A 54900099 CHECK ON WIRING & CHASSIS ELECTRICAL SYSTEM							30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							120.00
M SUNDRY SUNDRIES							50.00
M SUNDRY TO SUPPLY RH ANTI-FILM							25.00
M	PANEL ASSY-FRONT DOOR,RH			1.00	1115.00	20.00	892.00
M	PANEL ASSY-REAR DOOR,RH			1.00	891.00	20.00	712.80
M	TAPE-FR DR BLACK FRAME RR RH			1.00	26.00	20.00	20.80
M	TAPE-RR DR BLACK FRAME FR,RH			1.00	25.00	20.00	20.00
M	BLACK TAPE-FR DR FRAME UPR,RH			1.00	26.00	20.00	20.80
M	BLACK TAPE-RR DR FRAME UPR,RH			1.00	22.00	20.00	17.60
M	GARNISH ASSY-QTR SIDE,RH			1.00	125.00	20.00	100.00
M	MOULDING ASSY-SIDE SILL,RH			1.00	320.00	20.00	256.00
M	GARNISH ASSY-RR DR RR FRAME,RH			1.00	116.00	20.00	92.80
M	W/STRIP ASSY-FR DR BELT O/S RH			1.00	53.00	20.00	42.40

Confirm & accepted by

7% GST on	Nett 5440.20	5,440.20
		380.81
Total Payable		5,821.01

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.