



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorized Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR PC3863B

ComfortDelGro Bus Pte Ltd

205 Braddell Road
Singapore 579701
Attn: Mr. Jayson Khoo

65533838

WIP No
Reg No/Reg Date
Date In/Mileage
Chassis No
Engine No
Make/Model
Colour/Trim

Vehicle & Document Information

47815
PC3863B / 05/08/2015
WDB9066572P100351B
65195532615891
MBCV/516CD1/4325 (E)
914 Arctic White / NA NOT APPLICABLE

Account No	Terms	Date/Time Printed	CSE	Operator	Qty	Unit Price	Disc%	Amount
WC000021	Credit	25/05/2021/ 13:53		610 / Philip Cheong				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
A 00940101 To repair and knocking chassis cross member, floor panel, engine basket					1	1500.00		1500.00
A 00940101 To remove ad refit front bumper, front headlamp, support panel, fender, sealing door step blade auto.					1	2250.00		2250.00
A 00940101 To remove & refit engine unit and gear box					1	684.00		684.00
A 00940101 To remove & refit dashboard bracket and grill					1	528.00		528.00
A 00940101 To remove & refit air con blower/heater unit and air con condensor					1	450.00		450.00
A 00940101 To remove & refit wire harness and lighting wire					1	570.00		570.00
A 00940101 To remove & refit front radiator and inter cooler					1	750.00		750.00
A 00940101 To remove & refit drive seat inner carpet/passenger seat					1	684.00		684.00
A 00940101 To remove and refit front wheel, tower arm, anti low bar and steering					2.00	27.30	00.00	54.60
M SCREW					4.00	7.98	00.00	31.92
M SCREW					4.00	7.98	00.00	31.92
M SCREW					4.00	8.51	00.00	34.04
M SCREW					2.00	896.81	00.00	1793.62
M TRANSMISSION CARRIER					1.00	896.81	00.00	896.81
M TRANSMISSION CARRIER LH					1.00	665.35	00.00	665.35
M SHOCK-ABSORBER STRUT LH					1.00	55.54	00.00	55.54
M SPRING BEARING					1.00	76.12	00.00	76.12
M PLATE					2.00	10.74	00.00	21.48
M BRACKET					1.00	160.90	00.00	160.90
M BEARING					1.00	507.24	00.00	507.24
M TORSION BAR					2.00	39.55	00.00	79.10
M TORSION BAR MOUNT								

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6771 4389
Fax: 6775 6310
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorized Dealer
Company No. 196400167W
GST Reg No. MR-6500111-X

ESTIMATE FOR PC3863B

ComfortDelGro Bus Pte Ltd

205 Braddell Road
Singapore 579701
Attn: Mr. Jayson Khoo

65533838

Vehicle & Document Information

WIP No 47815
Reg No/Reg Date PC3863B / 05/08/2015
Date In/Mileage 20100000
Chassis No WDB9066672P100361 B
Engine No 65195532615891
Make/Model MBCV/516CD1/4325 (E)
Colour/Trim 914 Arctic White / NA NOT APPLICABLE

Account No	Terms	Date/Time Printed	CSE	Operator
WC000021	Credit	25/05/2021/ 13:53		610 / Philip Cheong
Description of Goods / Services				
	Qty	Unit Price	Disc%	Amount
M REAR SUBFRAME	2.00	398.86	00.00	797.72
M STEERING KNUCKLE	1.00	960.86	00.00	960.86
M TRANSV. CONTROL ARM	1.00	1052.81	00.00	1052.81
M AXLE SUBFRAME	1.00	2600.17	00.00	2600.17
M PLATE	1.00	232.40	00.00	232.40
M HEX. HEAD BOLT W FLANGE	4.00	13.23	00.00	52.92
M SPRING BEARING	1.00	55.54	00.00	55.54
M SPRING BEARING	1.00	26.42	00.00	26.42
M SPRING BEARING	1.00	29.65	00.00	29.65
M NUT	4.00	3.36	00.00	13.44
M NUT	4.00	4.15	00.00	16.60
M NUT	4.00	4.15	00.00	16.60
M NUT	2.00	4.15	00.00	8.30
M HEXAGON HEAD BOLT	2.00	7.04	00.00	14.08
M HEXAGON HEAD BOLT	2.00	18.16	00.00	36.32
M CAP BOLT	4.00	7.38	00.00	29.52
M SCREW	7.00	5.59	00.00	39.13
M HEXAGON HEAD BOLT	3.00	9.52	00.00	28.56
M *P NUT X	2.00	11.12	00.00	22.24

ESTIMATE

Taufik 97495749
Not Authorise, Revert.
27/5/21 @ 3pm
Ex: to be advise.
12 days

taufik@lkhanda.com

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirmed & accepted by

Nett 23,557.92
7% GST on 23557.92 1649.05

Total Payable 25,206.97

Authorized signatory and company stamp

Validity of this estimate is 16 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of removing the rubber seal or other repair requiring the removal of the windscreen.



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6771 4389
Fax: 6775 6310
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR PC3863B

ComfortDelGro Bus Pte Ltd

205 Braddell Road
Singapore 579701

Attn: Mr. Jason Khoo
Work: 65533838

Vehicle & Document Information

WIP No **47815**
Reg No/Reg Date **PC3863B / 05/08/2015**
Date In/Mileage **PC3863B**
Chassis No **WDB9066572B100351**
Engine No **65195532615891**
Make/Model **MBCV/516CDI/4325 (E)**
Colour/Trim **914 Arctic White / NA NOT APPLICABLE**

Account No	Terms	Date/Time Printed	CSE	Operator
CSC00003	Cash	10/06/2021/ 16:31		610 / Philip Cheong

Description of Goods / Services	Qty.	Unit Price	Disc%	Amount
A 72981501 ENTRY RAMP REPLACE M SUNDRIES TYRE 1 PC A 40000099 FRONT ALIGNMENT A 00940101 TO REPAIR AND RESPRAY FRONT BUMPER M RADIATOR ANTIFREEZE M BRAKE FLUID M POWER STEERING FLUID M EXPANSION RIVET M TRANSMISSION OIL R DISK WHEEL R WHEEL NUT COVER X ROD X CROSS MEMBER X PANELING X PANELING X HEADLAMP X BEAM				2040.00 300.00 240.00 960.00 60.74 51.38 48.22 26.70 547.68 360.32 51.46 156.25 893.92 50.67 47.03 842.53 281.78
ESTIMATE				240.00 192.00 960.00 60.74 51.38 48.22 26.70 547.68 360.32 51.46 156.25 893.92 50.67 47.03 842.53 281.78

Confirmed & accepted by

Authorized signatory and company stamp

Nett 6,958.68
7% GST on 6958.68 487.11

Total Payable 7,445.79

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
209 Pandan Gardens
Singapore 609339
Tel: (65) 67714389
Fax: (65) 67756310