

PRUDENT ADJUSTORS SERVICES

BLOCK 607 ELIAS ROAD #05-192

SINGAPORE (510607)

BUSINESS REGN. No. 53193457L

Hp 96699986

INVOICE

Mr Leong Guo Wei, Elwin
Block 671A Yishun Avenue 4 #12-604
Singapore 761671

Invoice No : PA/2103/0004/tpw
Our Ref : PA/FBN6370/0221/tpw
Date : 08 March 2021

Claim Type	Third Party	Date of Accident	27 January 2021
Vehicle No.	FBN 6370 U	Date of Inspection	04 February 2021
No	Description	Amount (S\$)	
1	Survey fees inclusive of Transportation and Photographs (66) copies	\$526.00	
	Total	\$526.00	
Singapore Dollar: Five Hundred And Twenty-Six Only			
All payments made payable to : Prudent Adjustors Services			


Prudent Adjustors Services
Bok Jee Tan

PRUDENT ADJUSTORS SERVICES

BLOCK 607 ELIAS ROAD #05-192
SINGAPORE 510607
BUSINESS REGN. No. 53193457L
HP: 96699986

VEHICLE DAMAGE INSPECTION REPORT

Mr Leong Guo Wei, Elwin
Block 671A Yishun Avenue 4 #12-604
Singapore 761671

Our Ref : PA/FBN6370/0221/tpw
Date : 08 March 2021

REFERENCES

Claim Type	: Third Party	Date of Accident	: 27 January 2021
Vehicle No.	: FBN 6370 U	Date of Assignment	: 04 February 2021
Make	: Honda	Date of Inspection	: 04 February 2021
Model	: CB150R Manual	Date of Re-inspection	: 24 February & 05 March 2021
Reg. Date	: 15 November 2018	COE Expiry	: 14 November 2028
Color	: Green	Chassis No	: MLHKC288XJ5028136
Odometer	: No Key	Engine No	: Blocked

TYRE CONDITION

	<u>Make</u>	<u>Size</u>	<u>Thread Balance</u>
Front	Dunlop	110/70-17	5mm
Rear	Dunlop	150/60-17	6mm

GENERAL DESCRIPTION OF DAMAGE (PHOTOGRAPHS ATTACHED)

The vehicle sustained damage at frontal and both sides.
Please refer to photographs and assessment of repairs for details
Enclosed (66) photographs depicting damages and after repaired

INSPECTION AND ADJUSTMENT

Original Quotation : \$7,853.39 Revised Assessment \$5,600.00 Lump sum

Survey conducted at E Motoring Pte Ltd

In accordance to your instruction, we have not authorized repairs.

In normal circumstances, repairs to the vehicle would take approximately
Eight (8) days to complete.

This survey was conducted on a "WITHOUT PREJUDICE" basis.

Note:

The workshop has agreed to undertake the repair on a lump sum basis, and or the use of ex-stock
Reconditioned parts whichever is possible

PRUDENT ADJUSTORS SERVICESVehicle No: **FBN 6370 U**

Our Ref : PA/FBN6370/0221/tpw

ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS

S/N	Description Material	Qty	Condition	Original Quotation	Revised Quotation
1	Handle bar	1 pc	Bent	110.00	110.00
2	Handle bar balancer	1 set	Cut	80.00	80.00
3	Throttle cable	1 set	Cut	55.00	55.00
4	Brake lever	1 pc	Bent/cut	52.80	52.80
5	Front brake master pump assy	1 pc	Cut	217.50	217.50
6	Clutch lever	1 pc	Bent	48.00	48.00
7	Mirror	1 set	Cut/bent	120.00	120.00
8	Headlight (LED)	1 pc	Cracked/grazed	658.00	658.00
9	Head light cover	1 pc	Grazed/cut	86.00	86.00
10	Front signal (LED) @ \$117/-	2 pcs	Grazed/cut RH	234.00	117.00
11	Front fork assy @ \$569.50/-	2 pcs	Bent	1,139.00	1,139.00
12	Stem steering	1 pc	Distorted	220.60	220.60
13	Front fender	1 pc	Cracked	98.30	98.30
14	Front wheel rim	1 pc	Cracked	533.80	533.80
15	Front wheel rim axle	1 pc	Bent	66.40	66.40
16	Front brake disc	1 pc	Warped	185.00	185.00
17	Fuel tank cover RH	1 pc	Cut	118.40	118.40
18	Front shroud RH	1 pc	Cracked/cut	105.50	105.50
19	Front shroud inner RH	1 pc	Serviceable	88.50	~
20	Radiator assy	1 pc	Dented	350.60	350.60
21	Lower cover RH	1 pc	Cut	78.80	78.80
22	Front footrest assy RH	1 pc	Broken	58.00	58.00
23	Front footrest bracket RH	1 pc	Bent	110.00	110.00
24	Brake pedal	1 pc	Cut / Bent	65.00	65.00
25	Exhaust muffler cover	1 pc	Cut	224.90	224.90
26	Rear footrest RH	1 pc	Cut	62.00	62.00
27	Rear footrest bracket RH	1 pc	Cut	101.00	101.00
28	Tail cover RH	1 pc	Serviceable	150.00	~
29	Rear wheel rim	1 pc	Cut	620.00	620.00
				6,037.10	5,681.60
List price less 10%				603.71	568.16
				5,433.39	5,113.44

PRUDENT ADJUSTORS SERVICES

Vehicle No: **FBN 6370 U**

Our Ref : PA/FBN6370/0221/tpw

Special nett item

30	Steering cone & bearing	1 set	Necessary	180.00	90.00
31	Front wheel rim bearing	1 pc	Necessary	60.00	40.00
32	Rear wheel rim bearing	1 pc	Necessary	80.00	60.00
33	Body sticker "CB150R"	1 set	Necessary	120.00	80.00
34	Front tyre (Dunlop 110/70-R17)	1 pc	Puncture	180.00	160.00
35	Rear tyre (Dunlop 150/60-R17)	1 pc	Puncture	250.00	220.00
				<hr/>	<hr/>
				870.00	650.00

Labours

Transportation (2 trips)	150.00	120.00
Body chassis repair & alignment	550.00	450.00
Swing arm repair & align	350.00	280.00
To repair, renew damaged parts	500.00	400.00
		<hr/>
		1,550.00 1,250.00

Total parts & labour concluded	<u>7,853.39</u>	<u>7,013.44</u>
--------------------------------	-----------------	-----------------

Lump sum repair adjustment		<u>5,600.00</u>
----------------------------	--	------------------------

The information contained in this document is privileged and confidential and is intended for the exclusive use of the addressee designation. If you are not the addressee; any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this document not meant for you, please contact us immediately to arrange for it to return.


Prudent Adjustors Services
Bok Jee Tan