

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21006144/NRA3Q2
Date: 24/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100462347-05
Claimant Vehicle No :	SHC3361C	Insured Vehicle No :	SLB8438R
Date of Loss:	25/05/2021	Nature of Claim:	TP
		Claim No:	8208147575SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC3361C		
Make & Model:	HYUNDAI AE IONIQ HEV DCT, 1.6 (A)	Engine No:	G4LEJU167738
Reg. Date:	01/02/2019 (Man. Year: 2018)	Chassis No:	KMHC851CVKU134061
Colour:	Blue	Odometer:	258900 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 4 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,112.96	1,777.60	2,335.36	56.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,760.00	1,230.00	530.00	30.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,872.96	3,007.60	2,865.36	48.79
+ GST 7.00/7.00% (S\$)	411.11	210.53	200.58	48.79

Nett Amount (S\$)	6,284.07	3,218.13	3,065.94	48.79
+ Loss of Use (5.0 x S\$50.00/day) (S\$)		250.00		
+ Car Rental (5.0 x S\$125.19/day) (S\$)		625.95		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,096.08		

INSPECTION

Date of Assignment: 27/05/2021

Date Inspected: 27/05/2021

Estimated Period of Repair: 3.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
 59 Loyang Drive
 Singapore 508969

Adjuster: Muhammad Nazril Bin Abdullah**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	459.40 FL	*459.40 FL
2	1		*REAR BUMPER REINFORCEMENT	Deformed	394.80 FL	*394.80 FL
3	2		*REAR BUMPER REINFORCEMENT BRACKET (LH/RH)	Deformed	276.20 FL	*276.20 FL
4	1		*REAR BUMPER CENTRE MOULDING ASSY	Deformed	451.25 FL	*451.25 FL
5	1		*REAR BUMPER LOWER CENTRE MOULDING ASSY	Deformed	155.00 FL	*155.00 FL
6	10		*REAR BUMPER COVER CLIPS	Necessary	22.00 FL	*22.00 FL
7	1		*REAR BUMPER TOW COVER	Serviceable	98.80 FL	*- FL
8	1		*REAR BUMPER FOG LAMP	Deformed	201.50 FL	*201.50 FL
9	1		*BOOT LID	Repair	2,480.40 FL	*- FL
10	1		*EMBLEM -HYBRID	Necessary	24.30 FL	*24.30 FL
11	1		*EMBLEM -LONIQ	Necessary	31.30 FL	*31.30 FL
12	1		*BOOT LID COMFORTDELGRO & 65521111 STICKERS	Necessary	70.00 FS	*70.00 FS
13	1		*BOOT LID COMFORT APPS STICKER	Necessary	40.00 FS	*40.00 FS
14	1		*REAR BUMPER REVERSE SENSOR	Serviceable	180.00 FS	*- FS
15	2		*REAR WINDSCREEN GLASSES SEALANT	Not Necessary	92.00 FS	*- FS
16	1		*REAR NO PLATE W/TRIM COVER	Necessary	55.00 FS	*55.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,031.95	2,180.75
- List Item Discount on L Items 20.00/20.00% (\$)	918.99	403.15
Total Parts (\$)	4,112.96	1,777.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	800.00	700.00
2	SPRAY PAINTING	New	600.00	500.00
3	R/I REVERSE SENSOR	New	120.00	30.00
4	R/I BOTH REAR WINDSCREEN GLASSES	New	200.00	0.00
5	CHECK ALL LIGHTINGS /WIRINGS	New	40.00	0.00
Gross Labour Cost (S\$)			1,760.00	1,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >