

ASS. REC. BY:

REF: C121

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$ 78k

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

Yr Regn: _____

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: _____

c.c. _____

Colour _____

A/C: _____

Insured / Std / NI / NA

Sp. Reading _____

T/Radio: _____

Insured / Std / NI / NA

Eng/No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: _____

F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. _____

mm

R/Bal. _____

mm

L/Bal. _____

mm

L/Bal. _____

mm

D.O.A. _____

D.O.I. _____

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: _____

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech Invs (\$ _____)

☐

: Weekend (\$ _____)

S - RS. SI

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	970Z
Vehicle Details	
Vehicle No.:	SLR2333P
Vehicle to be Exported:	Yes
Intended Deregistration Date:	25 May 2021
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8S CVT
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	2ZR6860386
Chassis No.:	ZVW506046773
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$27,401.00
Original Registration Date:	04 Aug 2017
First Registration Date:	04 Aug 2017
Transfer Count:	1
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 Aug 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	03 Aug 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,501.00
COE Rebate Amount:	\$29,407.00
Total Rebate Amount:	\$33,157.00

The information contained herein is correct as at 22 May 2021

OK

Merimen Submitted

Ding Auto Pte Ltd (Co.Reg.No:201311788Z)

176 Sin Ming Drive #04-06, Sin Ming Autocare
Singapore 575721

Tel: 64521208 Fax: 64520614 Email: ding@dingauto.sg;kenneth.ding@dingauto.sg

INSURER: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	DMHCSNA00004192100	Date of Loss:	18/05/2021
Vehicle Reg. No.:	SLR2333P	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	AUTOBAHN RENT A CAR PTE LTD		
Driver:	RICHARD GOH SIANG WEI		

Make/Model:	TOYOTA PRIUS HYBRID, 1.8 CVT (A)	Vehicle Reg. Date:	04/08/2017
Vehicle Colour:	Silver		
Engine No:	2ZR6860386	Chassis No:	ZVW506046773
Odometer:	0 KM		

Paint Type:
Total Loss? **NO**
Est. Duration of Repair (day) **15 / 10 days**

*Not with air
11Lm &
Penny After Paint
ex \$2000*

Present Location: **DING AUTO PTE LTD (HQ)**

COST OF CLAIMS

	Amount
Parts	
Miscellaneous Items	16,044.00
Labour	0.00
Paintwork Labour	982.80
Towing	558.22
	0.00
Gross Total (\$\$)	17,585.02
Nett Amount (\$\$)	18,815.97

This claim is handled by: **DING SING HUI, KENNETH**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 May 2021)
 Parts: 144 TOYOTA PRIUS HYBRID 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Ding Auto Pte Ltd/SLR2333P/25/05/2021 13:59
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1	NA	*AIR CHANNEL GUIDE	0.00	0.00	Dis *175.00 F	✓
2	1	NA	*BMC RESERVOIR CAP	0.00	0.00	mi *40.00 F	✓
3	1	NA	*BONNET	0.00	0.00	R *240.00 F	X
4	1	NA	*BONNET INSULATION	0.00	0.00	Sm *120.00 F	X
5	1	NA	*BONNET LOCK	0.00	0.00	R *60.00 F	X
6	1	NA	*CONDENSER	0.00	0.00	*575.00 F	?
7	1	NA	*FRONT BUMPER	0.00	0.00	Tn *185.00 F	✓
8	1	NA	*FRONT GRILLE	0.00	0.00	Sm *130.00 F	X
9	1	NA	*FRONT LWR AIR GRILLE	0.00	0.00	*65.00 F	?
10	1	NA	*FRONT LWR ENGINE CVR	0.00	0.00	Tn *105.00 F	✓
11	1	NA	*FRONT MANUFACT BADGE	0.00	0.00	Sm *35.00 F	✓
12	1	NA	*FRONT STABILISER	0.00	0.00	Ry *300.00 F	✓
13	1	NA	*FRT AXLE CARRIER	0.00	0.00	*850.00 F	?
14	1	NA	*FRT BUMPER ABSORBER	0.00	0.00	*275.00 F	?
15	1	NA	*FRT BUMPER REINF	0.00	0.00	R *215.00 F	X
16	1	NA	*FRT LWR BUMP ABSORB	0.00	0.00	CM *105.00 F	✓
17	1	NA	*L/DRIVE SHAFT CPL	0.00	0.00	R R *695.00 F	+
18	1	NA	*L/F AXLE JOINT	0.00	0.00	Ry *90.00 F	✓
19	1	NA	*L/F BUMPER COVER	0.00	0.00	Sm *12.00 F	X
20	1	NA	*L/F BUMPER COVER	0.00	0.00	n/p *48.00 F	+
21	1	NA	*L/F BUMP REINF BRKT	0.00	0.00	Ry *58.00 F	✓
22	1	NA	*L/F CPL SPRING STRUT	0.00	0.00	Sm Ry *185.00 F	+
23	1	NA	*L/F HINGE	0.00	0.00	R *30.00 F	X
24	1	NA	*L/F LWR AXLE ARM	0.00	0.00	Sm Ry *175.00 F	+
25	1	NA	*L/F STABI ROD	0.00	0.00	Ry *50.00 F	✓
26	1	NA	*LOWER ENGINE PROTECT	0.00	0.00	CBT *220.00 F	✓
27	1	NA	*LOWER SUMP	0.00	0.00	*225.00 F	?
28	1	NA	*R/A-PILLAR COVER	0.00	0.00	*48.00 F	?
29	1	NA	*R/AXLE BEAM BRACKET	0.00	0.00	*120.00 F	?
30	1	NA	*R/DAMPER PLATE	0.00	0.00	Sm *90.00 F	X
31	1	NA	*R/DRIVE SHAFT CPL	0.00	0.00	Ry *660.00 F	✓
32	1	NA	*R/F AXLE JOINT	0.00	0.00	*90.00 F	?
33	1	NA	*R/F BRAKE BACK PLATE	0.00	0.00	*58.00 F	?
34	1	NA	*R/F BRAKE DISC	0.00	0.00	*168.00 F	?
35	1	NA	*R/F BRAKE HOSE	0.00	0.00	*55.00 F	?
36	1	NA	*R/F BUMPER BRACKET	0.00	0.00	mi *35.00 F	✓
37	1	NA	*R/F BUMPER COVER	0.00	0.00	mi *12.00 F	✓
38	1	NA	*R/F BUMPER COVER	0.00	0.00	n/p *48.00 F	X
39	1	NA	*R/F BUMP REINF BRKT	0.00	0.00	Ry *58.00 F	✓
40	1	NA	*R/F COIL SPRING	0.00	0.00	Sm *95.00 F	X
41	1	NA	*R/F CONTROL ARM FRT	0.00	0.00	BT *85.00 F	✓
42	1	NA	*R/F CPL SPRING STRUT	0.00	0.00	Ry *185.00 F	✓
43	1	NA	*R/F HINGE	0.00	0.00	R *30.00 F	X
44	1	NA	*R/F INDICATOR BULB	0.00	0.00	mi *10.00 F	✓
45	1	NA	*R/F INDIC BULB HOLD	0.00	0.00	mi *20.00 F	✓
46	1	NA	*R/F INN W-HOUSE EXT	0.00	0.00	R *360.00 F	X
47	1	NA	*R/F LOWER AXLE ARM	0.00	0.00	Ry *175.00 F	✓

48	1	NA	*R/FR TYRE	0.00	0.00	Pu	*250.00 F	60912
49	1	NA	*R/FR WHEEL	0.00	0.00	De	*600.00 F	✓
50	1	NA	*R/F S-ABSORB BOOT	0.00	0.00	Ry	*80.00 F	✓
51	1	NA	*R/F STABI ROD	0.00	0.00	Ry	*50.00 F	✓
52	1	NA	*R/F STEERING KNUCKLE	0.00	0.00	Ry	*400.00 F	✓
53	1	NA	*R/F STRUT BEARING	0.00	0.00	nk	*78.00 F	✓
54	1	NA	*R/F UPP DAMPING RING	0.00	0.00		*120.00 F	?
55	1	NA	*R/F WHEELHOUSE COVER	0.00	0.00	nir	*100.00 F	✓
56	1	NA	*R/F WHEEL HUB	0.00	0.00	Ry	*215.00 F	✓
57	1	NA	*R/F WING	0.00	0.00	Ry	*230.00 F	✓
58	1	NA	*R/F WING BADGE	0.00	0.00	Pu	*35.00 F	✓
59	1	NA	*R/F WING BRACKET	0.00	0.00	Ry	*45.00 F	✓
60	1	NA	*R/F WING INSULATOR	0.00	0.00	nir	*85.00 F	✓
61	1	NA	*R/R AXLE STEERING	0.00	0.00		*210.00 F	?
62	1	NA	*R/R LWR CONTROL ARM	0.00	0.00	Ry	*245.00 F	✓
63	1	NA	*R/R RR AXLE SUPPORT	0.00	0.00		*450.00 F	?
64	1	NA	*R/RR TYRE	0.00	0.00	Pu	*250.00 F	60912
65	1	NA	*R/RR WHEEL	0.00	0.00	De	*600.00 F	✓
66	1	NA	*R/R SPRING LEG	0.00	0.00		*165.00 F	?
67	1	NA	*R/R UPP CONTROL ARM	0.00	0.00	nir	*185.00 F	✓
68	1	NA	*R/R WHEEL HUB CPL	0.00	0.00	Ry	*220.00 F	✓
69	1	NA	*R/S-ABSORB BOOT	0.00	0.00		*35.00 F	?
70	1	NA	*R/SILL PANELLING	0.00	0.00	CM	*290.00 F	✓
71	1	NA	*R/TIE ROD BALL JOINT	0.00	0.00	Ry	*48.00 F	✓
72	1	NA	*RADIATOR CPL	0.00	0.00		*575.00 F	?
73	1	NA	*RADIATOR SHROUD	0.00	0.00		*95.00 F	?
74	1	NA	*RIGHT BONNET STOP	0.00	0.00	Ln	*10.00 F	X
75	1	NA	*RIGHT FRONT DOOR	0.00	0.00	Ry	*650.00 F	✓
76	1	NA	*RIGHT HEADLAMP ASSY	0.00	0.00	Br	*720.00 F	✓
77	1	NA	*STEERING GEAR CPL	0.00	0.00	H/Tm	*600.00 F	✓
78	1	NA	*UPP FRT PNL C-MEMBER	0.00	0.00		*360.00 F	?
79	1	NA	*UPP RADIATOR COVER	0.00	0.00		*110.00 F	?
80	1	NA	*WASHER CONTAINER	0.00	0.00	nir	*78.00 F	✓
81	1	NA	*WASHER PUMP	0.00	0.00	CM	*150.00 F	✓
82	1	NA	*WASH RESERVOIR TUBE	0.00	0.00	Ln	*45.00 F	X
83	1	NA	*SUNDRY PARTS	0.00	0.00		*- F	

F=Franchise part.

Total Parts (S\$)

16,044.00

Ding Auto Pte Ltd/SLR2333P/25/05/2021 13:59. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Code	Description	WU	Price SGD
		1.0	4.20
431151)	DETACH + REFIT R/FRONT SUSPENSION STRUT	1.0	4.20
431101)	RENEW RIGHT FRONT COIL SPRING	1.0	4.20
431601)	R + R FRONT STABILIZER	4.0	16.80
NO NUMBER	R + R FRONT AXLE CARRIER	2.0	8.40
431011)	R + R LEFT FRONT LOWER CONTROL ARM	2.0	8.40
431011)	R + R RIGHT FRONT LOWER CONTROL ARM	1.0	4.20
434601)	R + R COMPLETE L/F AXLE SHAFT	1.0	4.20
434601)	R + R R/F AXLE SHAFT	4.0	16.80
434211)	R + R R/F STEERING KNUCKLE	3.0	12.60
004466)	BLEED HYDRAULIC BRAKE SYSTEM	3.0	12.60
004466)	VENT FRONT BRAKE SYSTEM	1.0	4.20
420018)	R + R LEFT REAR WHEEL	1.0	4.20
420018)	R + R RIGHT REAR WHEEL	2.0	8.40
420091A)	R + R RIGHT REAR TYRE/WHEEL	4.0	16.80
420091)	BALANCE WHEEL/S	2.0	8.40
421041A)	R + R REAR WHEEL HUB	1.0	4.20
482071)	R + R R/R UPPER CONTROL ARM	3.0	12.60
NO NUMBER	R + R R/R AXLE CARRIER REAR	4.0	16.80
48201A)	DETACH + REFIT REAR BRAKE CALIPER	4.0	16.80
482201)	R + R REAR SHOCK ABSORBER STRUTS	2.0	8.40
482151)	R + R LEFT REAR COIL SPRING	3.0	12.60
482041)	DETACH + REFIT REAR LOWER CONTROL ARM	5.0	21.00
NO NUMBER	R + R REAR AXLE CARRIER	4.0	16.80
002359N)	ELECTRIC AXLE GEARBOX OIL DRAIN /REFILL		

Labour Cost	Hrs	WU	
Panel / Mechanical Labour	23.40	234.0	982.80
Total of Labour			982.80

Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/h
Code	Description	WU Price SGD
	BONNET NEW PART PAINTING	18.0
	R/F WING NEW PART PAINTING	10.0
	UPP FRT PNL C-MEMBER SURFACE PAINT	4.0
	R/F INN W-HOUSE EXT SURFACE PAINT	4.0
	RIGHT FRONT DOOR NEW PART PAINTING	15.0
	L/F BUMPER COVER NEW PART PAINT K1R	3.0
	R/F BUMPER COVER NEW PART PAINT K1R	3.0
	FRONT BUMPER NEW PART PAINT K1R	11.0
	R/SILL PANELLING NEW PART PAINT K1R	7.0

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	45.14
0742	R/F WING NEW PART PAINTING	16.93
1017	UPP FRT PNL C-MEMBER SURFACE PAINT	2.46
1186	R/F INN W-HOUSE EXT SURFACE PAINT	0.53
1482	RIGHT FRONT DOOR NEW PART PAINTING	35.06
0277	L/F BUMPER COVER NEW PART PAINT K1R	0.35
0278	R/F BUMPER COVER NEW PART PAINT K1R	0.35

Labour

Time Base 10 WU/h

Price = 42.00 SGD/h
WU Price SGD

Code	Description		
043233D	ADJUST FRONT CAMBER (ADD/WORK)	2.0	8.40
043233)	ALIGN VEHICLE FRONT	5.0	21.00
043233)	ALIGN VEHICLE REAR	7.0	29.40
B020	RENEW FRONT BUMPER INCLUDES: R + R FRONT BUMPER, RADIATOR GRILLE AND NECESSARY ATTACHED PARTS	15.0	63.00
B040)	R + R LEFT HEADLAMP (BUMPER REMOVED) DOES NOT INCLUDE: ADJUST HEADLAMP	1.0	4.20
B040)	RENEW RIGHT HEADLAMP ASSY (BUMPER REMOVED) NOT INCLUDED: ADJUST HEADLAMPS	2.0	8.40
NO NUMBER	ADJUST HEADLAMPS	2.0	8.40
B110	RENEW R/F WING (BUMPER AND HEADLAMP REMOVED) INCLUDES: R + R WING, CONVERT ATTACHED PARTS	7.0	29.40
B100	R + R LEFT FRONT WING (BUMPER AND HEADLAMP REMOVED) INCLUDES: WHEELHOUSE LINER AND REQUIRED ATTACHED PARTS R + R	5.0	21.00
B125	RENEW UPPER FRONT PANEL CROSSMEMBER	4.0	16.80
B010)	R + R FRONT BUMPER REINFORCEMENT	3.0	12.60
B010)	R + R FRONT BUMPER LOWER REINFORCEMENT	2.0	8.40
B161)	RENEW R/F WHEELHOUSE EXTENSION	13.0	54.60
B070	RENEW BONNET INCLUDES: R + R BONNET, ATTACH PARTS ASSEMBLE AND IF NEC RENEW	5.0	21.00
B080	R + R BONNET HINGE/S	1.0	4.20
851091)	R + R WINDSCREEN WASHER TANK	1.0	4.20
B085)	R + R WATER BOX CLOSING PANEL	3.0	12.60
B085	R + R COWL TRIM GRILLE INCLUDES: R + R BOTH WIPER ARMS	2.0	8.40
M250	R + R BOOT FLOOR PANEL COVER	1.0	4.20
F210	RENEW R/F DOOR	30.0	126.00
L210	R + R RIGHT FRONT DOOR WINDOW FRAME SEAL	2.0	8.40
M010)	R + R CONDENSER	8.0	33.60
NO NUMBER	R + R LEVELLING SYSTEM SENSOR	1.0	4.20
B100	R + R L/SILL TRIM	3.0	12.60
B100	R + R R/SILL TRIM	3.0	12.60
M020	RENEW RADIATOR	19.0	79.80
112111)	R + R OIL PAN	14.0	58.80
M240	R + R REAR EXHAUST TUBE	2.0	8.40
NO NUMBER	SWIVEL JOINT DETACH + REFILL	1.0	4.20
451011)	R + R POWER STEERING RACK	2.0	8.40
451011)	RENEW POWER STEERING GEAR (REMOVED)	2.0	8.40
420091A)	R + R R/F WHEEL/TYRE	2.0	8.40
473101)	DETACH + REFIT FRONT BRAKE CALIPER	1.0	4.20
431151)	R + R L/F STRUT	1.0	4.20
431151)	R + R R/F STRUT	1.0	4.20
431011)	DETACH + REFIT L/F LOWER SUSPENSION ARM	1.0	4.20
431151)	DETACH + REFIT L/FRONT SUSPENSION STRUT	1.0	4.20

Paint Material Per Part

Code	Description	Price SGD
0283	FRONT BUMPER NEW PART PAINT K1R	48.16
2186	R/SILL PANELLING NEW PART PAINT K1R	20.94

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor	42.00 SGD/h		
Time Paint		75.0	
Preparation Main Work Metal	0.80	8.0	33.60
Preparation Comp. Work Plastic	0.30	3.0	12.60
Total	10 WU/h	86.0	361.20

Material Cost - Paint

	Price SGD
New Part Painting	97.13
New Part Painting - Plastic K1R	69.80
Surface-/Blend Paint	2.99
Material-constant Metal	18.10
Material-constant Plastic	9.00
Total	197.02

Spare Parts

Code	Description	Part Number	Part Source	prices as at 2015-06-01/01	Price SGD
1015	AIR CHANNEL GUIDE	16592 37020	Original		175.00
7517	BMC RESERVOIR CAP	47230 47090	Original		40.00
0471	BONNET	53301 47110	Original		240.00
0481	BONNET INSULATION	53341 47041	Original		120.00
0493	BONNET LOCK	53510 47130	Original		60.00
4465	CONDENSER	88460 10320	Original		575.00
0283	FRONT BUMPER	52119 47962	Original		185.00
0410	FRONT GRILLE	53101 47081	Original		130.00
0253	FRONT LWR AIR GRILLE	53112 47240	Original		65.00
8784	FRONT LWR ENGINE CVR	51420 47030	Original		105.00
71	FRONT MANUFACT	75310 47060	Original		35.00
	BADGE				
7261	FRONT STABILISER	48811 47080	Original		300.00
7011	FRT AXLE CARRIER	51201 47071	Original		850.00
0346	FRT BUMPER ABSORBER	52611 47140	Original		275.00
0340	FRT BUMPER REINF	52021 47110	Original		215.00
0349	FRT LWR BUMP ABSORB	52618 47090	Original		105.00
7035	L/DRIVE SHAFT CPL	43420 47040	Original		695.00
7083	L/F AXLE JOINT	43330 19115	Original		90.00
0277	L/F BUMPER COVER	52128 47906	Original		12.00
0343	L/F BUMPER COVER	52113 47060	Original		48.00
0341	L/F BUMP REINF BRKT	52103 47010	Original		58.00
7077	L/F CPL SPRING STRUT	48520 80490	Original		185.00
0475	L/F HINGE	53420 47130	Original		30.00
7053	L/F LWR AXLE ARM	48069 47060	Original		175.00
7271	L/F STABI ROD	48820 47040	Original		50.00
8783	LOWER ENGINE	51410 47020	Original		220.00
	PROTECT				

Code	Description	Part Number	Part Source	Price SGD
1439	WASH RESERVOIR TUBE	85319 47160	Original	45.00

f: OEM Parts
n: Non-OEM Parts
u: Used parts

Savings	0.00
Subtotal	16,044.00
Total	16,044.00

Final Calculation

	SGD	SGD
Parts		
Total Parts	16,044.00	16,044.00
Labour Time Base 10 WU/h		
Total 234.0 WU X 42.00 SGD/h	982.80	
Total of Labour		982.80
Paint Work Time Base 10 WU/h		
Labour Cost 86.0 WU X 42.00 SGD/h	361.20	
Material Cost	197.02	
Total Paint Including Material		558.22
Repair Cost Excludes GST		17,585.02
GST (+7.0%)		1,230.95
Repair Cost Included GST		18,815.97

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 22/05/2021 14:08 (SGT)
Date of Accident 18/05/2021 11:55 (SGT)
Exact Location of Accident Punggol Rd, Singapore
Additional Location Information -
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLR2333P

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner AUTOBAHN RENT A CAR PTE LTD
Company Reg No 2XXXXXX970Z
Email Address LUSIONT96@GMAIL.COM
Mobile Phone No (Phone) +65-68354800
Alternative Phone No (Office) +65-68354800

VEHICLE PARTICULARS

Manufacturer Toyota
Model Prius
Variant -
Exact purpose for which vehicle was being used at time of accident Private hire
Are you claiming under your own insurance policy for repair to your vehicle? Yes
Vehicle Category Private hire
Transmission Auto
CC 1798

INSURANCE COMPANY

Name of Insurance Company China Taiping Insurance (Singapore) Pte. Ltd.
Type of Coverage Comprehensive
Fleet Policy No
Policy Number DMHCSNA00004192100
Cover Note Number -

DRIVER