Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909 From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

: 4

Attn: Alfred Toh Date: 16 Dec 2021

Preliminary Advice

Insured Vehicle No : GZ7547Z

TP Vehicle No : SJA7391B Accident Date : 22/05/2021
Make : MITSUBISHI COLT Assignment Date : 26/05/2021

Date of Inspection : 27/05/2021 Est. Duration of Repair

Inspection At : 1ST AUTO PRO PTE LTD (HQ)

15 KAKI BUKIT ROAD 4, #01-53

SINGAPORE 417808

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	24,440.20
Revised Amount	:S\$	5,502.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,502.00
Lump Sum Repair	:S\$	4,400.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly
		let us have your authorisation.

(The vehicle is uneconomical	≀to l	be repaired	. vou are advise	ď	to invite	e tend	ler f	or t	he wrec	:k
١	. ,			bo ropanoa	, you alo aavioo	ч		COLIC		0, ,	110 11100	

⁽ X) Other comments :Please note that the preliminary advice amount (Revised) stated are subject to consistency check, part prices and labour cost.