



Borneo Motors



TOYOTA

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611. Tel no. 6631 1188

Denise

\$35221.

ESTIMATE

Account Details			Account No.		Customer Details				
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept			S1000003 / ICCI1		Mr Chua Tee Yeong Eldwin (Cai Zhiyong)				
			Document No. 0		21 Angullia Park #20-01 Singapore 239974				
			Document Date 25/05/2021		Mobile: 96668806				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2018	ACR50R	GFXSK E1	24/08/2018	SMF0333D	0	20982	67/OD/SMF0333D		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
JTEGD56M007161736		2AZ1A70488	60	Sam San Joi	25/05/2021 16.00		--/--/----		
L	Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES OD CLAIM POLICY NO.:DMPCSNW00088052000 ACC DATE:24/05/2021 TOW IN:24/05/2021 EXCESS:\$1000 DATE-IN:25/05/2021 DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:							30.00
2	B	BP-LAB2	DRILL HOLE & INSTALL FRT PARKING SENSOR						180.00
3	B	BP-LAB2	CHECK LIGHTING & WIRING SYSTEM						122.40
4	B	BP-LAB2	REMOVE & INSTALL AIRCON CONDENSER ASSY A ND CHARGE UP GAS						360.00
5	Z	BP-SLANT	SUPPLY SEALANT (NETT)- BONNET, FRT SUPPO RT PANEL						60 120.00
6	S	BP-SUBLET	RH FRT TYRE <i>inclined.</i>						450 580.00
7	B	BP-LAB2	REPLACE SPORT RIM AND CONDUCT WHEEL BALA NCING						72.00
8	B	BP-MECH2	REPLACE RH FRT SUSPENSION SYSTEM ASSY						720.00
9	B	BP-MECH2	CONDUCT FULL WHEEL ALIGNMENT						180.00
10	B	BP-ECU2	TO RESET ECU AND REPROGRAMME						180.00
11	B	BP-LAB2	REPLACE RH FRT ACCIDENT DAMAHED PARTS STRAIGHTEN & ALIGN RH FRT ACCIDENT AFFECTED AREAS						2160 5040.00
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total		
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less		
							Amount Due		

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no. : 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details	
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICCI1	Mr Chua Tee Yeong Eldwin (Cai Zhiyong)	
		Document No. 0	21 Angullia Park #20-01 Singapore 239974	
		Document Date 25/05/2021	Mobile: 96668806	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	ACR50R	GFXSK E1	24/08/2018	SMF0333D	0	20982	67/OD/SMF0333D

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTEGD56M007161736	2AZ1A70488	60	Sam San Joi	25/05/2021 16.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
12	B	BP-RES2 RESPRAY JOB ON RH FRT ACCIDENT AFFECTED AREAS			✓	2360 4130.00
13	1	T52119-2R905 COVER, FR BUMPER <i>Distorted</i>	1.00	622.10		✓ 622.10
14	2	T52115-28260 SUPPORT, FR BUMPER <i>Damaged</i>	1.00	73.60		✓ 73.60
15	3	T52112-28130 EXTENSION, FR <i>Distorted</i>	1.00	22.70		✓ 22.70
16	4	T53152-28080 GUIDE, RADIATOR <i>Distorted</i>	1.00	129.10		✓ 129.10
17	5	T52611-28130 ABSORBER, FR BUMPER <i>Not new</i>	1.00	79.60		✓ x 79.60
18	6	T52021-28280 REINFORCEMENT <i>Bent</i>	1.00	431.20		✓ 431.20
19	7	T52545-28080 SEAL, FR BUMPER <i>Not new</i>	1.00	33.10		✓ 33.10
20	8	T53141-28030 GARNISH, RADIATOR <i>Not new</i>	1.00	508.20		✓ x 508.20
21	9	T53112-28290 GRILLE, RADIATOR <i>Not new</i>	1.00	199.90		✓ 199.90
22	0	T52127-28530 COVER, FR BUMPER <i>Distorted</i>	1.00	32.50		✓ 32.50
23	1	T53115-28100 BRACKET, RADIATOR <i>Not new</i>	1.00	129.10		✓ x 129.10
24	2	T53101-28580 GRILLE SUB-ASSY, <i>Not new</i>	1.00	589.90		✓ x 589.90
25	3	T75311-28340 EMBLEM, RADIATOR <i>Not new</i>	1.00	348.80		✓ 348.80
26	4	T75361-28010 PLATE, FR FENDER <i>Distorted</i>	1.00	45.50		✓ 45.50
27	5	T53301-28180 HOOD SUB-ASSY <i>Distorted</i>	1.00	924.70		✓ 924.70
28	6	T53381-28090 FRONT BONNET SEAL, <i>Not new</i>	1.00	37.50		✓ 37.50
29	7	T53341-28100 INSULATOR, HOOD <i>Not new</i>	1.00	280.10		✓ 280.10
30	8	T90467-09050 CLIP(HOOD INSULATOR) <i>Not new</i>	5.00	2.90		✓ 14.50

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



incocap

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no. 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details						
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICCI1	Mr Chua Tee Yeong Eldwin (Cai Zhiyong)						
		Document No. 0	21 Angullia Park #20-01 Singapore 239974						
		Document Date 25/05/2021	Mobile: 96668806						
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2018	ACR50R	GFXSK E1	24/08/2018	SMF0333D	0	20982	67/OD/SMF0333D		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
JTEGD56M007161736		2AZ1A70488	60	Sam San Joi	25/05/2021 16.00		--/--/---- 0.00		
L	Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount
31	9	T53811-28220 PANEL, FR FENDER, RH <i>Distorted</i>				1.00	860.90		✓ 860.90
32	0	T53866-28010 SEAL,FR FENDER T <i>Dang</i>				1.00	22.40		✓ 22.40
33	1	T53805-28110 SHIELD SUB-ASSY, <i>torn</i>				1.00	222.80		✓ 222.80
34	2	T90467-07166 CLIP <i>Neu</i>				10.00	2.80		✓ 28.00
35	3	T53827-28150 PROTECTOR, FR FENDER <i>Del d</i>				1.00	129.10		✓ 129.10
36	4	T53420-28130 L/FRT BONNET HINGE, <i>Neu</i>				1.00	54.30		x? 54.30
37	5	T53410-28130 R/FRT BONNET HINGE, <i>Best</i>				1.00	54.30		✓ 54.30
38	6	T53510-28220 LOCK ASSY, HOOD <i>Neu</i>				1.00	93.90		+ 93.90
39	7	T53209-28080 BRACE SUB-ASSY, HOOD <i>Neu</i>				1.00	121.90		+ 121.90
40	8	T53205-28210 SUPPORT SUB-ASSY, <i>Smashed Neu</i>				1.00	343.60		+ 343.60
41	9	T53028-28050 F/LWR RADIATOR SUPPORT, <i>Neu</i>				1.00	277.30		+ 277.30
42	0	T53203-28140 SUPPORT SUB-ASSY, <i>Neu</i>				1.00	311.40		+ 311.40
43	1	T53202-28140 SUPPORT SUB-ASSY, <i>Buckd Neu</i>				1.00	311.40		+ 311.40
44	2	T53292-28100 SEAL, RADIATOR <i>Neu xnn</i>				1.00	195.90		✓ 195.90
45	3	T55346-47010 CLIP, INSTRUMENT <i>Neu</i>				8.00	3.60		x 28.80
46	4	T53701-28850 APRON SUB-ASSY, FR <i>Neu</i>				1.00	889.80		✓ 889.80
47	5	T53707-28100 APRON SUB-ASSY, <i>Neu</i>				1.00	178.00		+ 178.00
48	6	T55708-28230 LOUVER SUB-ASSY, <i>Neu Neu</i>				1.00	645.00		x 645.00
49	7	T67001-28240 PANEL SUB-ASSY, FR <i>Neu</i>				1.00	1718.70		✓ 1718.70
50	8	T81105-28G21 HOUSING SUB-ASSY, <i>Smashed</i>				1.00	3959.70		✓ 3959.70
For & on behalf of		Customer's Signature		Charge Summary		Total			
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle		Parts		Less			
				Labour					
				Sublet					
				Lubrication/Fluid					
				Others		Amount Due			

Customer Copy



Borneo Motors



TOYOTA

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no. 6631 1188

ESTIMATE

Table with Account Details, Account No. (S1000003 / ICCI1), Customer Details (Mr Chua Tee Yeong Eldwin), Document No. (0), and Document Date (25/05/2021).

Table with columns: Year (2018), Model (ACR50R), Variant (GFXSK E1), Reg. Date (24/08/2018), Reg. No. (SMF0333D), Kilometers (0), Wip No. (20982), Order No. / Remarks (67/OD/SMF0333D).

Table with columns: Chassis No (JTEGD56M007161736), Engine No. (2AZ1A70488), Terms (60), SA / Counter (Sam San Joi), Vehicle In (25/05/2021 16.00), Collected On (0.00).

Main items table with columns: L, Cd, Job/Parts Description, Qty, Unit Price, Disc %, Amount. Includes handwritten notes like 'Not Rec', 'Missing', and 'BENT'.

Summary table with columns: For & on behalf of (Borneo Motors), Customer's Signature, Charge Summary (Parts, Labour, Sublet, Lubrication/Fluid, Others), Total, Less, Amount Due.

Customer Copy



Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details	
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn. Motor Claims Dept		S1000003 / ICC11	Mr Chua Tee Yeong Eldwin (Cai Zhiyong)	
		Document No. 0	21 Angullia Park #20-01 Singapore 239974	
		Document Date 25/05/2021	Mobile: 96668806	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	ACR50R	GFXSK E1	24/08/2018	SMF0333D	0	20982	67/OD/SMF0333D
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTEGD56M007161736	2AZ1A70488	60	Sam San Joi	25/05/2021	16.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
71	9	T43330-49215 JOINT ASSY, LWR BALL <i>Best</i>	1.00	264.00		264.00
72	0	T43211-78010 KNUCKLE, STEERING, <i>Damaged</i>	1.00	734.30		734.30
73	1	T43550-28010 HUB & BEARING ASSY, <i>Damaged</i>	1.00	670.30		670.30
74	2	T90177-22001 NUT LOCK <i>NCC</i>	1.00	7.30		7.30
75	3	T43410-42141 SHAFT ASSY, FR <i>Damaged</i>	1.00	1507.40		1507.40
76	4	T45510-28161 GEAR ASSY, STEERING <i>NCC</i>	1.00	1948.50		1948.50
77	5	T45046-29515 END SUB-ASSY, TIE <i>NCC</i>	1.00	204.60		204.60
78	6	S08889-80102 COOLANT, SLIC&& <i>NCC</i>	1.00	79.50	79.60	79.50
79	7	T57104-12270 F/LOWER CROSS-MEMBER, <i>NCC</i>	1.00	985.30		985.30
80	8	T51201-28281 CROSSMEMBER <i>NCC</i>	1.00	2704.90		2704.90
81	9	T51107-28020 R/F SUSPENSION MEMBER, <i>NCC</i>	1.00	229.90		229.90
82	0	T52241-28010 CUSHION, CAB RR <i>NCC</i>	4.00	8.20		32.80
83	1	T52211-28040 CUSHION, BODY <i>NCC</i>	2.00	74.10		148.20
84	2	T51403-28070 BRACE SUB-ASSY, FR <i>NCC</i>	2.00	148.20		296.40

Adrian Lim - P/P 27/05/21. Not Authorised. Excess \$1000. 9 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

For & on behalf of Borneo Motors (Singapore) Pte Ltd <small>(Singapore) Pte Ltd a "Without Prejudice" basis</small>	Customer's Signature	Charge Summary	Total	48,196.90
	Please acknowledge receipt of vehicle	Parts 36,482.50 Labour 11,134.40 Sublet 580.00 Lubrication/Fluid 0.00 Others 0.00	GST 7.00%	3,373.70
			Less	0.00
			Amount Due	51,570.60