



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

TAX INVOICE

Account Details	Account No.	Customer Details
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	Mr Chua Tee Yeong Eldwin (Cai Zhiyong) 21 Angullia Park #20-01 Singapore 239974
	Document No. 39011903	
	Document Date 16/07/2021	Mobile: 96668806

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	ACR50R	GFXSK E1	24/08/2018	SMF0333D	25634	20982	67/OD/SMF0333D

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTEGD56M007161736	2AZ1A70488	60	Sam San Joi	25/05/2021 15.57	07/07/2021 14.31

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES OD CLAIM POLICY NO.:DMPCSNW00088052000 ACC DATE:24/05/2021 TOW IN:24/05/2021 EXCESS:\$1000 DATE-IN:25/05/2021 DATE SURVEY:27/05/2021 NO OF REPAIR DAYS:9 DAYS BY:ADRIAN(LKK) AUTHORISED ON:28/05/2021				30.00
2	B	BP-LAB2 DRILL HOLE & INSTALL FRT PARKING SENSOR	*			180.00
3	B	BP-LAB2 CHECK LIGHTING & WIRING SYSTEM	*			122.40
4	Z	BP-SLANT SUPPLY SEALANT (NETT)- BONNET	*			60.00
5	B	BP-MECH2 REPLACE RH FRT SUSPENSION SYSTEM ASSY	*			720.00
6	B	BP-LAB2 REPLACE RH FRT ACCIDENT DAMAHED PARTS STRAIGHTEN & ALIGN RH FRT ACCIDENT AFFECTED AREAS	*			2160.00
7	B	BP-RES2 RESPRAY JOB ON RH FRT ACCIDENT AFFECTED AREAS	*			2360.00
8	B	BP-LAB2 RH FRT TYRE	*			450.00
9	S	BP-SUBLET REMOVE & INSTALL DASHBOARD AND COMPARTME NTTO REPLACE WIRE HARNESS	0742			(A) 1440.00
10	V	EXC Excess element of insurance repair to be paidby the insured party	8888			-1000.00
11	S	BP-SUBLET CONDUCT FULL WHEEL ALIGNMENT	0742			180.00

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
_____	_____		Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

TAX INVOICE

Account Details		Account No.	Customer Details	
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICCI1	Mr Chua Tee Yeong Eldwin (Cai Zhiyong)	
		Document No. 39011903	21 Angullia Park #20-01 Singapore 239974	
		Document Date 16/07/2021	Mobile: 96668806	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	ACR50R	GFXSK E1	24/08/2018	SMF0333D	25634	20982	67/OD/SMF0333D

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTEGD56M007161736	2AZ1A70488	60	Sam San Joi	25/05/2021 15.57	07/07/2021 14.31

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
12	S	BP-SUBLET TO RESET ECU AND REPROGRAMME	0742			180.00
13	S	BP-SUBLET REMOVE & INSTALL AIRCON CONDENSER ASSY A ND CHARGE UP GAS	0742			✓ (A) 360.00
14	S	BP-SUBLET REPLACE SPORT RIM AND CONDUCT WHEEL BALA NCING	0239			72.00
15	1	T52119-2R905 COVER, FR BUMPER AERAS	1.00	622.10		622.10
16	2	T52115-28260 SUPPORT, FR BUMPER	1.00	73.60		73.60
17	3	T52112-28130 EXTENSION, FR	1.00	22.70		22.70
18	4	T53152-28080 GUIDE, RADIATOR	1.00	129.10		129.10
19	5	T52021-28280 REINFORCEMENT	1.00	431.20		431.20
20	6	T52545-28080 SEAL, FR BUMPER	1.00	33.10		33.10
21	7	T52127-28530 COVER, FR BUMPER	1.00	32.50		32.50
22	8	T75361-28010 PLATE	1.00	45.50		45.50
23	9	T53301-28180 HOOD SUB-ASSY AERAS	1.00	924.70		924.70
24	0	T53811-28220 PANEL, FR FENDER, RH AERAS	1.00	860.90		860.90
25	1	T53866-28010 SEAL,FR FENDER TO	1.00	22.40		22.40
26	2	T53805-28110 SHIELD SUB-ASSY,	1.00	222.80		222.80
27	3	T90467-07166 CLIP	10.00	2.80		28.00
28	4	T53827-28150 PROTECTOR, FR FENDER	1.00	129.10		129.10
29	5	T53410-28130 HINGE ASSY,HOOD RH	1.00	54.30		54.30

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Customer Copy



TAX INVOICE

Account Details	Account No.	Customer Details
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	Mr Chua Tee Yeong Eldwin (Cai Zhiyong) 21 Angullia Park #20-01 Singapore 239974 Mobile: 96668806
	Document No. 39011903	
	Document Date 16/07/2021	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	ACR50R	GFXSK E1	24/08/2018	SMF0333D	25634	20982	67/OD/SMF0333D

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTEGD56M007161736	2AZ1A70488	60	Sam San Joi	25/05/2021 15.57	07/07/2021 14.31

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
30	6	T53202-28140 SUPPORT SUB-ASSY,AERAS	1.00	311.40		311.40
31	7	T81105-28G21 HOUSING SUB-ASSY,AERAS	1.00	3959.70		3959.70
32	8	T81193-28240 RETAINER, HEADLAMP	1.00	32.00		32.00
33	9	T812A0-28010 LAMP ASSY, LED AERAS	1.00	1039.10		1039.10
34	0	T89341-42060 B1 SENSOR, ULTRASONIC,	1.00	392.80		392.80
35	1	T85315-28240 JAR ASSY,WINDSHIELD	1.00	218.40		218.40
36	2	T42611-28A20 WHEEL, DISC	1.00	2190.40		2190.40
37	3	T48820-42030 LINK ASSY, FR	1.00	165.20		165.20
38	4	T48510-80810 ABSORBER ASSY,FR RH	1.00	472.30		472.30
39	5	T48068-28140 ARM SUSPENSION RH	1.00	815.40		815.40
40	6	T43330-49215 JOINT ASSY, LWR BALL	1.00	264.00		264.00
41	7	L43211-78010 KNUCKLE, STEERING RH	1.00	734.30		734.30
42	8	T43550-28010 HUB SUB-ASSY,AXLE	1.00	670.30		670.30
43	9	T90177-22001 NUT, LOCK	1.00	7.30		7.30
44	0	T43410-42141 SHAFT ASSY,DRIVE RH	1.00	1507.40		1507.40
45	1	T82111-28T00 WIRE, ENGINE ROOM Snapped	1.00	5603.50		(A)5603.50
46	2	T52611-28130 ABSORBER, FR BUMPER	1.00	79.60		79.60
47	3	T53141-28030 GARNISH, RADIATOR cracked	1.00	508.20		(A)508.20
48	4	T53205-28210 SUPPORT SUB-ASSY,AERAS Buckled	1.00	343.60		(A)343.60
49	5	T81106-28G21 UNIT ASSY,H/LAMP LH AERAS Cracked	1.00	3959.70		(A)3959.70

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			34,221.00
	Please acknowledge receipt of vehicle	Parts 26,906.60	GST 7.00% 2,395.47
		Labour 6,082.40	Less 0.00
		Sublet 2,232.00	
		Lubrication/Fluid 0.00	
		Others 0.00	Amount Due 36,616.47