

Mon 28/06 @ 9.30am
SKR

SKG 6193U

W Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 58512
Date Estimated : 25/05/2021
Prepared By : Han Kwan Yong

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Celina Kow Sow Leng
29 Lorong Pisang Asam

- ACCOUNT - 40000
Cash Sales - Service
Singapore

Singapore 597974

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKG6193U	WBA2D920X05E91212	07/08/2017	216i G TOURER	60335

DESCRIPTION

To replace rear bumper, boot lid including to knock out dented area caused by the accident

850 x 2

1700 2,550.00

To respray rear bumper and boot lid

1826 1,923.00

To carry out body cavity preservation.
(Per panel).

112 118.00

To remove and install rear windscreen glass to transfer from old to new boot lid

545 574.00

To conduct water leak tests.

71 75.00

To transfer lock mechanism from old to new bootlid including conduct check on new bootlid central locking system for proper function.

504 531.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.

168 177.00

To check electrical wiring system and lighting at the rear section for proper function.

168 177.00

Sundries.

80 150.00

Total Labour 1: 6,275.00

DESCRIPTION

BOOTLID
REAR BUMPER CARRIER
SUPPORT
REAR BUMPER PANEL PRIMED (PD
GROMMET

QTY	PRIC
1	1,216.40
1	460.40
1	45.75
1	1,050.65
2	0.80

VALUE
1,216.40
460.40
45.75
1,050.65
1.60

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 58512
Date Estimated : 25/05/2021
Prepared By : Han Kwan Yong

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKG6193U	WBA2D920X05E91212	07/08/2017	216i G TOURER	60335

DESCRIPTION	QTY	PRIC	VALUE
PLAQUE 74MM / <i>APC</i>	1	71.95	71.95
REAR WINDOW (ESG) <i>X AN</i>	1	657.60	657.60
HOOK AND LOOP FASTENER <i>X APC AN</i>	6	2.20	13.20
(DG) CLEANER R1 (100ML) <i>APC</i>	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) <i>APC</i>	2	131.55	263.10
(DG/SL)ADHESIVE PRIMER VP 206 (30ML) <i>APC</i>	1	27.85	27.85

Total Parts : 3,834.65

Steve (LKK)
28/6/21, 10.00am
83228813

WM PL
5 dys
Ng BL sy
P/P

OD / 3rd Party / Uninsured losses / Direct Settlement

Report No.	Claim No.
Date & Time	Excess \$
Surveyor's Name	Sign
Surveyor's Tel	Authorized Yes/No
Authorized Date	Time
PARTS PHOTO BY SURVEYOR Yes/No <i>APC</i> Yes/No	
Email	
Recommend	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Labour 1	:	6,275.00
Parts	:	3,834.65
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	707.68
Grand Total	:	10,817.33

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **