



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKG 6193U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BOOTLID (SN)	DENTED	1,216.40	1,216.40
1	REAR BUMPER CARRIER (SN)	NOT NECESSARY	460.40	-
1	SUPPORT (SN)	NOT NECESSARY	45.75	-
1	REAR BUMPER PANEL PRIMED (PD)(SN)	DENTED	1,050.65	1,050.65
2	GROMMET (SN)	NECESSARY	1.60	1.60
1	PLAQUE 74MM (SN)	NECESSARY	71.95	71.95
1	REAR WINDOW (ESG)(SN)	NOT NECESSARY	657.60	-
6	HOOK AND LOOP FASTENER (SN)	NOT NECESSARY	13.20	-
1	(DG) CLEANER R1 (100ML)(SN)	NECESSARY	26.15	26.15
2	(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)(SN)	NECESSARY	263.10	263.10
1	(DG/SL) ADHESIVE PRIMER VP 206 (30ML)(SN)	NECESSARY	27.85	27.85
1	SUNDRIES (SN)	NECESSARY	150.00	80.00
10	BUMP STOP (SN)(ADDITIONAL)	NECESSARY	32.00	32.00
			4,016.65	2,769.70
	<u>LABOUR</u>			
	TO REPLACE REAR BUMPER,BOOT LID INCLUDING TO KNOCK OUT DENTED AREA CAUSED BY THE ACCIDENT.		2,550.00	1,700.00
	TO RESPRAY REAR BUMPER AND BOOT LID.		1,923.00	1,826.00
	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL).		118.00	112.00
	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO TRANSFER FROM OLD TO NEW BOOT LID.		574.00	545.00
	TO CONDUCT WATER LEAK TESTS.		75.00	71.00
	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOTLID INCLUDING CONDUCT CHECK ON NEW BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION.		531.00	504.00
	TO REMOVE OLD PDC ASSEMBLY,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION.		177.00	168.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION.		177.00	168.00
			6,125.00	5,094.00
GRAND TOTAL			10,141.65	7,863.70
RECOMMENDED COST OF REPAIRS				7,863.70

Report Ref No. CS/SMR21006157/Euf3n2

CHEN TSUE YEE

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.