



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21006157/Euf3n2	
			Date: 26/07/2021	
			Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SMB 5014M	Veh. Inspected	SKG 6193U	
Policy No.		Coverage (\$)	0.00	
Claim No.	BUS/05/21/5046	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	27/05/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	BMW 216I GT	c.c	1499	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WBA2D920X05E91212	Colour	BLACK	
Odometer	64616 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	PIRELLI	4 mm	
L/H Front Tyre	205/60 R16	PIRELLI	4 mm	
R/H Rear Tyre	205/60 R16	PIRELLI	4 mm	
L/H Rear Tyre	205/60 R16	PIRELLI	4 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	24/05/2021	Inspection Date	28/06/2021	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>5 Working Days</b>	