

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 58512**
Date Estimated : **25/05/2021**
Prepared By : **Han Kwan Yong**

- ESTIMATE REPAIR FOR -
Celina Kow Sow Leng
29 Lorong Pisang Asam

- ACCOUNT - 49635
Smrt Buses Ltd
60 Woodlands Industrial Park E4

Singapore 757705

Singapore 597974

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKG6193U	WBA2D920X05E91212	07/08/2017	216i G TOURER	60335

DESCRIPTION	ORIGINAL PRICE	NETT
To replace rear bumper and attachments, bootlid including knock out dented area caused by the accident.	1,700.00	1,700.00
To respray rear bumper and bootlid.	1,826.00	1,826.00
To carry out body cavity preservation. (Per panel).	112.00	112.00
To remove and install rear windscreen glass to transfer from old to new boot lid	545.00	545.00
To conduct water leak tests.	71.00	71.00
To transfer lock mechanism from old to new bootlid including conduct check on new bootlid central locking system for proper function.	504.00	504.00
To remove old PDC assembly and reconnect to new bumper including conduct check for proper function.	168.00	168.00
To check electrical wiring system and lighting at the rear section for proper function.	168.00	168.00
Sundries.	80.00	80.00

DESCRIPTION	UNIT PRICE	QTY	NETT
BOOTLID	1,216.40	1.00	1,216.40
REAR BUMPER PANEL PRIMED (PDC)	1,050.65	1.00	1,050.65
GROMMET	0.80	2.00	1.60
PLAQUE 74MM	71.95	1.00	71.95
# BUMP STOP	3.20	10.00	32.00
(DG) CLEANER R1 (100ML)	26.15	1.00	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	131.55	2.00	263.10
(DG/SL)ADHESIVE PRIMER VP 206 (30ML)	27.85	1.00	27.85

SUPPLEMENTARY ITEMS

Total Labour :	5,174.00
Total Parts :	2,689.70
Total Labour & Parts :	7,863.70
Deduction for Excess :	0.00
Total Repair Costs less Excess:	7,863.70
GST @7%:	550.46
Grand Total :	8,414.16

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : **b1 58512**
Date Estimated : **25/05/2021**
Prepared By : **Han Kwan Yong**

- ESTIMATE REPAIR FOR -
Celina Kow Sow Leng
29 Lorong Pisang Asam

- ACCOUNT - 49635
Smrt Buses Ltd
60 Woodlands Industrial Park E4
Singapore 757705

Singapore 597974

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKG6193U	WBA2D920X05E91212	07/08/2017	216i G TOURER	60335

DESCRIPTION	ORIGINAL PRICE	NETT
-------------	----------------	------

DESCRIPTION	UNIT PRICE	QTY	NETT
# BUMP STOP	3.20	10.00	32.00

✓ nec

SUPPLEMENTARY ITEMS

Total Labour :	0.00
Total Parts :	32.00
Total Labour & Parts :	32.00