

LCRF PTE LTD
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms China Taiping Insurance (Singapore) Pte Ltd

Date 25/05/2021

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. SLG2887R

CHASSIS NO: GP71041042

MAKE / MODEL : Honda Shuttle Hybrid 1.5 Auto

DATE OF ACCIDENT: 21/05/2021

YOUR INSURED VEHICLE NUMBER: GBK9788U

MILEAGE : 329843 km

	<u>PARTS DESCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	Rear tailgate <i>h/</i>	1PC	\$1,850.00	\$1,850.00 <i>1200</i>
2	Rear tailgate lock <i>X SVL</i>	1PC	\$550.00	\$550.00 <i>X</i>
3	Rear tailgate windscreen moulding <i>ne /</i>	1PC	\$195.00	\$195.00 <i>151</i>
4	Rear tailgate weatherstrip <i>ne /</i>	1PC	\$255.00	\$255.00 <i>197</i>
5	R/R tail lamp <i>X nn</i>	1PC	\$850.00	\$850.00 <i>X</i>
6	R/L tail lamp <i>f nn</i>	1PC	\$850.00	\$850.00 <i>X</i>
7	Rear taigate Honda emblem <i>X nn</i>	1PC	\$81.30	\$81.30 <i>X</i>
8	Rear tailgate Hybrid emblem <i>ne /</i>	1PC	\$88.40	\$88.40 <i>/</i>
9	Rear tailgate shuttle emblem <i>ne /</i>	1PC	\$88.40	\$88.40 <i>/</i>
10	Rear bumper <i>de /</i>	1PC	\$1,350.00	\$1,350.00 <i>965</i>
11	Rear bumper RH side retainer <i>X SVL</i>	1PC	\$128.00	\$128.00 <i>X</i>
12	Rear bumper LH side retainer <i>X SVL</i>	1PC	\$128.00	\$128.00 <i>X</i>
13	Rear end panel <i>repair</i>	1PC	\$950.00	\$950.00 <i>X</i>
14	Rear end panel top cover/garnish <i>? X SVL</i>	1PC	\$180.00	\$180.00 <i>X</i>
15	Rear spare tyre panel <i>X SVL</i>	1PC	\$1,500.00	\$1,500.00 <i>X</i>
16	Rear spare tyre box <i>X SVL</i>	1PC	\$580.00	\$580.00 <i>X</i>
LIST TOTAL S\$:				\$9,624.10
20.00% DISCOUNT S\$:				\$1,924.82
				\$7,699.28

2689.80
20%
2151.84

SPECIAL NETT

1	Reverse sensor <i>? nn /</i>	1 SET	\$260.00 <i>200</i>
2	Windscreen sealant <i>ne /</i>	1 SET	\$120.00 <i>60</i>
3	Body Sealant <i>X nn</i>	1 SET	\$250.00 <i>X</i>
4	Rear Bumper clips <i>ne /</i>	1 SET	\$80.00 <i>40</i>
5	Rear end panel top garnish clips <i>ne /</i>	1 SET	\$80.00 <i>40</i>
Special Nett Total S\$:			\$790.00

340

LABOUR CHARGES

- 1 TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN PANEL WHERE STRAIGHTEN.
- 2 TO PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER)
- 3 TO REMOVE & INSTALL REAR WINDSCREEN
- 4 TO APPLY RUSTPROOFING / TUFFCOATING TREATMENT TO REPLACED PARTS.
- 7 TO CONDUCT A STANDARD OF OPEARTING PROCEDURES POST REPAIRS DIAGNOSTIC SCAN TEST AS A REQUIREMENT FOR HYBRID CARS UPON COMPLETION OF COLLISION REPAIRS
- TO LABOUR CHARGE FOR REMOVING REAR
- 8 SEATS & GARNISH OUT TO FACILITATE REPAIRS AND REPLACEMENT OF PARTS
- 9 TO TRANSFER TAILGATE MECHANISM

~~\$1,000.00~~ ~~450~~ 450

~~\$1,000.00~~ 660

~~\$120.00~~

~~\$100.00~~ 40

~~\$300.00~~ 120

~~\$200.00~~ 60 X 14

~~\$100.00~~ 60

1450

LABOUR TOTAL S\$: \$2,820.00

TOTAL S\$: \$11,309.28

7% GST \$791.65

GRAND TOTAL S\$: \$12,100.93

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rene

Hy 900 1006 8

5 days

4/5

28/05/21 @ 1555

Ready after repair

2151.84

340.00

1450.00

3941.84

20%

3153.47

4/5-3,150

5 days