Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909 From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Tan Kah Leong Date: 31 May 2021

Preliminary Advice

Insured Vehicle No : GBK9788U

TP Vehicle No : SLG2887R Accident Date : 21/05/2021

Make : HONDA SHUTTLE HYBRID Assignment Date : 27/05/2021

Date of Inspection : 28/05/2021 Est. Duration of Repair : 5

Inspection At : LION CITY RENTALS PTE LTD (HQ)

60 JALAN LAM HUAT, #04-35/36 CARROS CENTRE

SINGAPORE 737569

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,309.28
Revised Amount	:S\$	4,651.44
Check Items (Estimated)	:S\$	404.00
Total	:S\$	5,055.44

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$
Pre-Accident Value :S\$
COE / PARF Rebate :S\$
Salvage Value :S\$
Margin for Repair :S\$

Remarks

)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
)	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
)	Other comments: