



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2104924

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 13/07/2021
Reference CC3/CTI21006163/Kea3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHF 585C
Insured Veh. SJT 7130M
Claim No. SNM21D203007/C02
Policy No. DMPCSNW00014702100
Accident Date 22/05/2021
Inspection Date 25/05/2021

| Description | Total |
|--------------------------------|---------------|
| Third Party Express Settlement | 400.00 |
| Subtotal | 400.00 |
| GST (7%) | 28.00 |
| Grand Total | 428.00 |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|--|-----------------|--|--|
| CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909 | | | Ref: CC3/CTI21006163/Kea3q2 Date: 13/07/2021 Code: CTI | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | SJT 7130M | Veh. Inspected | SHF 585C | |
| Policy No. | DMPCSNW00014702100 | Coverage (\$) | 0.00 | |
| Claim No. | SNM21D203007/C02 | Excess (\$) | 0.00 | |
| Assign From | | Assign Date | 25/05/2021 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | TOYOTA PRIUS (A) | c.c | 1798 | |
| Engine No. | HIDDEN | Year of Reg. | 2020 | |
| Chassis No. | JTDKB3FU903092707 | Colour | M . P. WHITE / RED | |
| Odometer | 42081 KM | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | STANDARD ALLOY RIM | |
| General | GOOD | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 195/65 R15 | DUNLOP | 4 mm | |
| L/H Front Tyre | 195/65 R15 | DUNLOP | 4 mm | |
| R/H Rear Tyre | 195/65 R15 | DUNLOP | 4 mm | |
| L/H Rear Tyre | 195/65 R15 | DUNLOP | 4 mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. | | | | |
| 5. General Information | | | | |
| Accident Date | 22/05/2021 | Inspection Date | 25/05/2021 | |
| Survey held at | TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111 | | | |
| 5a. Remarks | | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | | 1.500 Working Days | |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 585C

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|--|----------------------|---------------------------|-------------------|
| <u>REPLACEMENT OF PARTS</u> | | | | |
| 1 | COVER ,REAR BUMPER | TO REPAIR SEE LABOUR | 485.60 | - |
| 1 | REINFORCEMENT SUB-ASSY ,REAR BUMPER | BENT | 332.70 | 332.70 |
| 1 | GUARD ,REAR BUMPER ,CENTER | DENTED / CUT | 374.50 | 374.50 |
| 1 | GUARD ,REAR BUMPER ,LOWER | SERVICEABLE | 22.00 | - |
| 1 | RETAINER ,REAR BUMPER SIDE ,LH | SERVICEABLE | 132.60 | - |
| 1 | RETAINER ,REAR BUMPER SIDE ,RH | SERVICEABLE | 132.60 | - |
| 1 | PANEL SUB-ASSY, BODY LOWER BACK | TO REPAIR SEE LABOUR | 651.00 | - |
| 1 | COVER ,DECK TRIM ,REAR | SERVICEABLE | 126.70 | - |
| 1 | COVER ,FLOOR UNDER NO.2 (RH) | SERVICEABLE | 241.90 | - |
| 1 | COVER ,FLOOR UNDER NO.1 (RH) | SERVICEABLE | 175.10 | - |
| 1 | COVER ,REAR FLOOR (CTR) | SERVICEABLE | 229.90 | - |
| | LESS 25% DISCOUNT | | -726.15 | -176.80 |
| | | | 2,178.45 | 530.40 |
| <u>SPECIAL NETT ITEMS</u> | | | | |
| 1 | SET PARKING AID (SN) | SERVICEABLE | 700.00 | - |
| 1 | SET REAR BUMPER CLIP (SN) | NOT NECESSARY | 85.00 | - |
| 1 | REAR FLOOR UNDERCOVER CLIP (SN) | NOT NECESSARY | 180.00 | - |
| 1 | REAR SPOILER CLIP (SN) | NOT NECESSARY | 70.00 | - |
| 1 | BUMPER CENTRE GUARD CLIP (SN) | NOT NECESSARY | 80.00 | - |
| 1 | REAR BUMPER PROTECTOR (SN) | NOT NECESSARY | 180.00 | - |
| 1 | REAR BUMPER RETAINER CLIP (SN) | NOT NECESSARY | 75.00 | - |
| | | | 1,370.00 | - |
| <u>LABOUR</u> | | | | |
| | TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS . | NOT NECESSARY | 240.00 | - |
| | TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR. | NOT NECESSARY | 380.00 | - |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|---|---------------|---------------------------|-------------------|
| | PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF COVER ,REAR BUMPER AND PANEL SUB-ASSY, BODY LOWER BACK. | | 1,600.00 | 150.00 |
| | TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENT TO FACILITATE BODYWORK REPAIR . | NOT NECESSARY | 380.00 | - |
| | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION . | | 1,600.00 | 220.00 |
| | TO REMOVE AND REFIT REAR BIG & SMALL W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR . | NOT NECESSARY | 300.00 | - |
| | TO REINSTALL REAR BUMPER PARKING SENSOR . | NOT NECESSARY | 170.00 | - |
| | TO CHECK ELECTRICAL LIGHTING CONCERNED. | NOT NECESSARY | 170.00 | - |
| | | | 4,840.00 | 370.00 |
| GRAND TOTAL | | | 8,388.45 | 900.40 |
| RECOMMENDED COST OF REPAIRS | | | | 900.40 |

Report Ref No. CC3/CTI21006163/Kea3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHF 585C

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHF 585C

RE-INSPECTION

