

ASS. REC. BY:

REF:

C72/210061631ke

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 1 1/2 days Res.: Yes or NoLum Sum: 1.8.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHF 585C Yr Regn: 11.20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Prius c.c. 1798Colour M.P. white A/C: Insured / Std / NI / NASp. Reading 42081 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKB31F0903092707Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal. 4 mmL/Bal. 4 mmD.O.A. 22/5/21

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 Got BT

2415 8900-40 Carbur

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF585C**AAD2105-105**

Not Whited
Recovery B4 pain
@ 900.40

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

25 MAY 2021**SHF585C**

JTDKB3FU903092707

TOYOTA

PRIUS **GEN 4**

22/05/2021

Chin

13/11/2020

PART

- 1 COVER, REAR BUMPER
- 1 REINFORCEMENT SUB-ASSY, REAR BUMPER
- 1 GUARD, REAR BUMPER, CENTER
- 1 COVER, REAR BUMPER, LOWER
- 1 RETAINER, REAR BUMPER SIDE, LH
- 1 RETAINER, REAR BUMPER SIDE, RH
- 1 PANEL SUB-ASSY, BODY LOWER BACK
- 1 COVER, DECK TRIM, REAR
- 1 COVER, FLOOR UNDER, NO.2 (RH)
- 1 COVER, FLOOR UNDER, NO.1 (LH)
- 1 COVER, REAR FLOOR (CTR)

LIST

\$	<i>R</i>	485.60	X
\$	<i>B</i>	332.70	<i>✓</i>
\$	<i>not for</i>	374.50	<i>✓</i>
\$	<i>Sn</i>	22.00	X
\$	<i>Sn</i>	132.60	X
\$	<i>Sn</i>	132.60	X
\$	<i>R</i>	651.00	X
\$	<i>Sn</i>	126.70	X
\$	<i>Sn</i>	241.90	X
\$	<i>Sn</i>	175.10	X
\$	<i>Sn</i>	229.90	X

TOTAL \$ 2,904.60**25% \$ 726.15****\$ 2,178.45****Special Nett**

1SET PARKING AID

1SET REAR BUMPER CLIP

1 REAR FLOOR UNDERCOVER CLIP

1 REAR SPOILER CLIP

1 BUMPER CENTRE GUARD CLIP

1 REAR BUMPER PROTECTOR

1 REAR BUMPER RETAINER CLIP

\$	<i>Sn</i>	700.00	X
\$	<i>nn</i>	85.00	X
\$	<i>nn</i>	180.00	X
\$	<i>nn</i>	70.00	X
\$	<i>nn</i>	80.00	X
\$	<i>nn</i>	180.00	X
\$	<i>nn</i>	75.00	X

TOTAL \$ 1,370.00

Trans-cab Auto Services Pte Ltd

AAD2105-105

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF585C

TOTAL PARTS	\$	3,548.45
--------------------	-----------	-----------------

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	nn 240.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,600.00	150/
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	nn 380.00	X
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	220/
To Remove And Refit Rear Big & Small W/Screen Glass To Facilitate Bodywork Repair.	\$	nn 300.00	X
To reinstall rear bumper parking sensor.	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	nn 170.00	X

TOTAL	\$	4,840.00
--------------	-----------	-----------------

Over All Total	\$	8,388.45
-----------------------	-----------	-----------------

(PART-BY-PART) Repair Days~~10 Days~~

1 1/2 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: