

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5652A**AAD2105-106***Not Authorized**Returning B4 pain**81634.60*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

25 MAY 2021**SHC5652A**

JTDKB3FUX03092103

TOYOTA

PRIUS GEN 4

22/05/2021

AEI
30/09/2020**PART****LIST**

| | | | |
|---------------------------------------|----|------------------|----------|
| 1 COVER, REAR BUMPER | \$ | <i>Bu</i> 485.60 | <i>✓</i> |
| 1 REINFORCEMENT SUB-ASSY, REAR BUMPER | \$ | <i>Bu</i> 332.70 | <i>✓</i> |
| 1 GUARD, REAR BUMPER, CENTER | \$ | <i>Bu</i> 374.50 | <i>✓</i> |
| 1 COVER, REAR BUMPER, LOWER | \$ | <i>Sn</i> 22.00 | <i>X</i> |
| 1 RETAINER, REAR BUMPER SIDE, LH | \$ | <i>Sn</i> 132.60 | |
| 1 RETAINER, REAR BUMPER SIDE, RH | \$ | <i>Sn</i> 132.60 | |
| 1 REFLECTOR ASSY, REFLEX, LH | \$ | <i>Sn</i> 39.00 | |
| 1 REFLECTOR ASSY, REFLEX, RH | \$ | <i>Sn</i> 39.00 | |
| 1 PANEL SUB-ASSY, BODY LOWER BACK | \$ | <i>N</i> 651.00 | |
| 1 COVER, DECK TRIM, REAR | \$ | <i>Sn</i> 126.70 | |
| 1 COVER, FLOOR UNDER, NO.2 (RH) | \$ | <i>Sn</i> 241.90 | |
| 1 COVER, FLOOR UNDER, NO.1 (LH) | \$ | <i>Sn</i> 175.10 | |
| 1 COVER, REAR FLOOR (CTR) | \$ | <i>Sn</i> 229.90 | |

TOTAL \$ 2,982.60**25% \$ 745.65****\$ 2,236.95****Special Nett**

1SET PARKING AID

1SET REAR BUMPER CLIP

1 REAR FLOOR UNDERCOVER CLIP

1 REAR SPOILER CLIP

1 BUMPER CENTRE GUARD CLIP

1 REAR BUMPER PROTECTOR

1 REAR BUMPER RETAINER CLIP

| | | |
|----|------------------|---------------|
| \$ | <i>Nu</i> 700.00 | <i>220000</i> |
| \$ | <i>Nu</i> 85.00 | <i>50500</i> |
| \$ | <i>Nu</i> 180.00 | <i>X</i> |
| \$ | <i>Nu</i> 70.00 | <i>X</i> |
| \$ | <i>Nu</i> 80.00 | <i>X</i> |
| \$ | <i>Nu</i> 180.00 | <i>X</i> |
| \$ | <i>Nu</i> 75.00 | <i>X</i> |

Trans-cab Auto Services Pte Ltd

AAD2105-106

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5652A

TOTAL \$ 1,370.00**TOTAL PARTS** \$ 3,606.95**LABOUR**

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ *nn* 240.00 *X*

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ *nn* 380.00 *X*

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 1,600.00 *2000*

To transfer of rear end panel fittings, attachment to facilitate bodywork repair.

\$ *nn* 380.00 *X*

Putty And Spray Painting Of The Affected Portion.

\$ 1,600.00 *2200*

To Remove And Refit Rear Big & Small W/Screen Glass To Facilitate Bodywork Repair.

\$ *nn* 300.00 *X*

To reinstall rear bumper parking sensor.

\$ 170.00 *500*

To Check Electrical Lighting Concerned.

\$ *nn* 170.00 *X***TOTAL** \$ 4,840.00**Over All Total** \$ 8,446.95**(PART-BY-PART) Repair Days**~~10 Days~~*2 day***LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: