

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/ASM21006166/U9C**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 5JY8206Xat Workshop m/s Imperium

of _____

Insured: SMC 9576B

Policy No. _____

Claims No. S1M03AOJ

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$28k.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS 368h

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: 5JY8206XYr Regn: 05/10/10

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or/

Make: Mit Lancer Mivec c.c. 1499Colour: white A/C: Insured / Std / NI / NASp. Reading: 104404 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JMYSRCY2AA4001853

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 225/45ZR17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6Rear 6

R/Bal. _____ mm

R/Bal. _____ mm

L/Bal. _____ mm

L/Bal. _____ mm

D.O.A. 28/5/11D.O.I. 28/5/11

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction _____

coe until 04-10-2015 LTA \$15310
hyper POI1/6/11 L/S \$3700 confirmed with shown. (Red \$3417.40, 48%)

15/06/21@10.27am revised to Chen Xin You via Smart Claims.

Date/Time, File Pass to?

☐

: Preli. Report

1) 15/06 Typist

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5Resurvey No. of Trip: 2

Survey Fee:

Transportation:

) ___ S + RS, ___ SI

) Photos

) Others

TOTAL

Report Format : SMART CLAIMS- TP

Lump Sum ~~4.8k~~ (\$ 3700)Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

IMPERIUM AUTOMOTIVE

25 Kaki Bukit Road 4 #01-49 Synergy @ KB Singapore 417800
Tel: 9748 9940 Fax: 6346 7213

Vehicle No.: SJY 8206X

Model: Mitsubishi Lancer

not Authorized
28/5/21
2/5 @ 3700/
5 days
Whe phl. After rep in

QTY

List Price:

1	Boot Lip	2
1	Boot Lid Logo	nee
1	Boot Lid "C&C" Emblem	nee 45
1	Rear Bumper	7.5
2	Rear Bumper Reflector @ 58.00	0.5 each
1	Rear Bumper Top Beam	2
1	Rear Bumper Reinforcement	nee
2	Rear Bumper Side Retainer @ 145.00	nee 0.5 each 45
6	Rear Bumper Clip @ 4.50	nee
1	Rear Bumper Tow Hook Cover	70.11
2	Rear License Plate Lamp @ 48.00	11
1	Rear End Panel	10
1	Rear Smart Keyless Room Antenna	11
1	Rear Exhaust Pipe	nee/twi
1	Rear Taillamp (R)	11

Prices \$

695.00	X
48.00	✓
58.00	✓
732.00	✓
116.00	1pc
115.00	X
375.00	✓
90.00	1pc
27.00	✓
28.00	✓
96.00	X
435.00	✓
186.00	X
543.00	✓
342.00	X
3886.00	
-388.6	

Subtotal 3497.40

Special Nett Items

1	Rear License Plate W Holder	one
1 set	Rear Sensor	one
1 set	Rear Bumper Lower Spoiler	DIS
1	Rear Boot Lid Sticker	11

50.00	40
300.00	200
850.00	✓
80.00	X

Subtotal 1280.00

Labour Charges:

To remove, replaced damaged lamps and check up rear wiring.
To remove, refit rear reverse sensor
To apply undercoating
Panel Beating
To respray painting on affected areas

120.00	30
100.00	50
120.00	30
1000.00	600
1000.00	900

Subtotal 2340.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL

\$ 7117.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: Page 1

p-2173
107
p-1955.70
s.w-1090.00
L-1610.00
4655.7
3724