

# Assessment Details

- General & Workshop Details
  - Vehicle & Driver Details
  - Vehicle Condition
  - Taxes & Ratio
  - Parts & Labour
  - Miscellaneous
- Summary

## General Details

Involving	TPVD MITSUBISHI (SJY8206X)
Date of Loss	25 May 2021
Time of Loss	19:10
Loss Description	SMC9576B (INSD) C/W SJY8206X
Comment	<input type="text"/>

## Workshop Details

Total Rebate Amount	<input type="text" value="0"/>
Nett Loss Amount	-\$15,310.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (TP)
Days of work completion *	<input type="text" value="20"/>

# Assessment Details

General & Workshop Details **Vehicle & Driver Details** Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

## Vehicle & Driver Details

Vehicle Registration#	SJY8206X	Purchase Date	<input type="text" value="DD/MM/YYYY"/> 
Registration State	<input type="text" value="SINGAPORE"/>	Registration Date *	<input type="text" value="05/10/2010"/> 
Mileage	<input type="text" value="104404"/>	Age of Vehicle	10

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year		<input type="text" value="2010"/>

### Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Make	TPVD	MITSUBISHI
Model	MITSUBISHI	LANCER 1.5 MIVEC GL
Type		
Type of Paint		
Chassis No		JMYSRCY2AAU001853
Engine No		4A910170886
Engine Capacity		1499
Sum Insured		0

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	MUHAMAD ZULKARNAIN BIN MOHAMED NOOR	
Date of Birth	26 July 1971	DD/MM/YYYY 
Age	49	
Occupation	Unknown	
Education Qualification	Other	
Driving Experience	0	
Driver License #		
License Type		

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Market Value		<input type="text" value="0"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
License Issue Date		<input type="text" value="DD/MM/YY"/> 
License Expiration Date		<input type="text" value="DD/MM/YY"/> 
Address	Singapore	<input type="text"/>
Address type	Personal Correspondence	<input type="text" value="v"/>
Gender	Male	<input type="text" value="v"/>
Marital status	Unknown	<input type="text" value="v"/>
Identification #	S7126368A	<input type="text"/>

# Assessment Details

- General & Workshop Details
  - Vehicle & Driver Details
  - Vehicle Condition**
  - Taxes & Ratio
  - Parts & Labour
  - Miscellaneous
- Summary

## Detailed Assessment

Inspection Date \*  

Total Loss

Towing Charges

Voluntary Excess

Compulsory Excess

Young/Inexperienced/ Unnamed Driver Excess

## Condition of Vehicle at time of survey

General condition  

Steering (Serviceable)

Footbrake (Serviceable)

Handbrake (Serviceable)

Engine Modification

Pre-accident condition  

Other Excess

### Tyre Condition

---

Age of Tyres

Front Tyre Size

Front left side

Front right side

Spare wheel

Rear Tyre Size

Rear left side

Rear right side

# Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio**
- Parts & Labour
- Miscellaneous
- Summary

## Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%	<input type="text" value="0"/>	Salvage%	<input type="text" value="0"/>
Discount%	<input type="text" value="10"/>	Settlement%	<input type="text" value="100"/>

## Paint Labour/Material Ratio

Paint Labour Ratio	<input type="text" value="20"/>	Cash Loss	<input type="button" value="Yes"/> <input checked="" type="button" value="No"/>
Paint Material Ratio	<input type="text" value="80"/>	Part Supplied by AXA	<input type="button" value="Yes"/> <input type="button" value="No"/>



Service Requests

Messages

Claims

<< Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio **Parts & Labour** Miscellaneous Summary

Parts

<div style="display: flex; justify-content: space-around; border: 1px solid green; padding: 2px;"> <span>Add</span> <span>Approve</span> <span>Deny</span> <span>Submit All</span> </div>													
EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		BOOT LID	Repair	0	0	No	0	0	0	0	0
	0	1		BOOT LID LOGO	Necessary	0	48	No	0	10	0	0	43.2
	0	1		BOOT LID "C&C" EMBLEM	Necessary	0	45	No	0	10	0	0	40.5
	0	1		REAR BUMPER	Damaged	0	732	No	0	10	0	0	658.8
	0	1		REAR BUMPER REFLECTOR O/S	Cracked	0	37	No	0	10	0	0	33.3
	0	1		REAR BUMPER REFLECTOR N/S	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR BUMPER TOP BEAM	Repair	0	0	No	0	0	0	0	0
	0	1		REAR BUMPER REINFORCEMENT	Bent	0	233	No	0	10	0	0	209.7

EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		REAR BUMPER SIDE RETAINER O/S	Bent	0	45	No	0	10	0	0	40.5
	0	1		REAR BUMPER SIDE RETAINER N/S	Serviceable	0	0	No	0	0	0	0	0
	0	6		REAR BUMPER CLIP	Necessary	0	4.5	No	0	10	0	0	24.3
	0	1		REAR BUMPER TOW HOOK COVER	Damaged	0	28	No	0	10	0	0	25.2
	0	2		REAR LICENSE PLATE LAMP	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR END PANEL	Dented	0	435	No	0	10	0	0	391.5
	0	1		REAR SMART KEYLESS ROOM ANTENNA	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR EXHAUST PIPE	Twisted	0	543	No	0	10	0	0	488.7
	0	1		REAR TAILLAMP (R)	Serviceable	0	0	No	0	0	0	0	0

Labour

Add	Approve	Deny	Submit All
-----	---------	------	------------

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
------	-------	-------------------------	-----------	------------------------	------------------------	-----------------------	-----------------------	-----------------	---------	--------

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0		TO REMOVE, REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING	0	30	0	0	Reviewing		
	0		TO REMOVE, REFIT REAR REVERSE SENSOR	0	50	0	0	Reviewing		
	0		TO APPLY UNDERCOATING	0	30	0	0	Reviewing		
	0		PANEL BEATING	0	600	0	0	Reviewing		
	0		TO RESPRAY PAINTING ON AFFECTED AREAS	0	900	0	0	Reviewing		

## Assessment Details

### Summary

Add		Approve		Deny		Submit All	
EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	DAYS OF REPAIR : 5 DAYS	Reviewing	0	0		
	0	REAR LICENSE PLATE W HOLDER	Reviewing	0	40	CRACKED	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	1 SET REAR SENSOR	Reviewing	0	200	CRACKED	
	0	1 SET REAR BUMPER LOWER SPOILER	Reviewing	0	850	DISTORTED	
	0	REAR BOOT LID STICKER	Deny	0	0	NOT NECESSARY	

# Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

## Summary

Estimated Claim Amount	\$0.00	Adjusted Claim Amount	\$4,655.70
------------------------	--------	-----------------------	------------

CATEGORY	ESTIMATE	ADJUSTED
Spare Parts	\$0.00	\$1,955.70
Labour	\$0.00	\$1,610.00
Miscellaneous	\$0.00	\$1,090.00

Submit for Review

# Assessment Details

## Summary

Add		Approve		Deny		Submit All	
EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	FINAL LUMP SUM	Reviewing	0	3700		

## Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

### Summary

Estimated Claim Amount	\$0.00	Adjusted Claim Amount	\$3,700.00
------------------------	--------	-----------------------	------------

CATEGORY	ESTIMATE	ADJUSTED
Miscellaneous	\$0.00	\$3,700.00

Submit for Review