

TPMS19.
Xiao Chan.

SJY9945P . 2010 Oct.

Volkswagen New Golf. 1390CC

WVWZZZ1KZAW396240

Front Number Plate	2 NP	30(SW) X
Front Number Plate Holder	MR	30(SW) X
Front Bumper	Defend	969 /
Front Bumper Clips.	MR	50(SW) 30(SW)
Front Bumper Side Holder x 02	NP MR	58 x 2 = 116 X.
Front Bumper Sponge x 02	LH MR	91 x 2 = 182 - 91
Front Bumper Reinforcement.	Defend	597 /
Front Bumper Lower Grille.	NP	207 +
Front Bumper Fog Lamp LH.	MR	310. +
Front Bumper Fog Lamp Grille LH	MR	78 X.
Front Grille	MR	317. /
Front Grille Clips.	MR	20(SW) /
Front Grille Logo.	MR	78 /

SJY9945P.

Headlamp LH ~~could~~ 931. ✓

Headlamp Top Panel LH. Buckled 165 ✓

Headlamp lower Bracket LH. ~~could~~ 48 ✓

Front Support Panel. ~~could~~ 840 ✓

Air Con Condenser Best 685 ✓

Radiator New 587 ✓

Bonnet Buckled 839. ✓

Bonnet lock. New 75 X.

Coolant. New ~~60(SN)~~ 40(SN)

Air Filter. New ~~180(SN)~~ X 120(SN)

SS60 SN: 90

SS04

Panel Beating
Spray Painting,

1350

~~1400~~ 200
~~800~~ 500

~~100~~ 30

Wiring.

~~100~~ 60

L/S 5.1K To remove condenser and
O/R up to top up air con gas }

To remove radiator and
to top up coolant. }

~~100~~ 60

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
- is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

5.1K