

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date : 26/05/2021

28/05/2021

TP Ergo-
Veron.

Estimated repair cost for vehicle no: SBM9590LV TOYOTA CAMRY 2.0 AUTO ABS AIRBAG
CHASSIS: MR053BK4107046720 (2009)

S/N	Qty	Items	U/price	Amount
1	1	FRONT BUMPER <i>Replaced</i>	\$789.00	<i>565</i> \$789.00
2	1	FRONT BUMPER SIDE RETAINER LH <i>new</i>	\$54.90	\$54.90 ✓
3	1	FRONT BUMPER CHROME MOULDING LH <i>new</i>	\$164.90	<i>110</i> \$164.90 ✓
4	1	FRONT BUMPER FOG LAMP OUTER GARNISH LH <i>Replaced</i>	\$244.60	<i>101.40</i> \$244.60 ✓
5	1	FRONT BUMPER FOG LAMP LH <i>new</i>	\$387.60	\$387.60 ✓
6	1	FRONT BUMPER REINFORCEMENT <i>new</i>	\$684.10	<i>465</i> \$684.10 ✓
7	1	FRONT BUMPER SPONGE <i>new</i>	\$237.50	\$237.50 ✓
8	1	FRONT BUMPER LOWER GRILLE <i>new</i>	\$197.40	\$197.40 +
9	1	FRONT BUMPER UNDER COVER <i>new</i>	\$194.10	\$194.10 +
10	1	LH FRONT HEADLAMP <i>new</i>	\$1,658.10	<i>1385</i> \$1,658.10 ✓
11	1	LH FRONT HEADLAMP LOWER BRACKET <i>new</i>	\$114.60	\$114.60 +
12	1	LH FRONT FENDER <i>Replaced</i>	\$589.30	\$589.30 ✓
13	1	LH FRONT FENDER EMBLEM <i>new</i>	\$115.40	\$115.40 -
14	1	LH FRONT FENDER INNER SHIELD	\$182.60	\$182.60 +
15	1	LH FRONT WHEEL BEARING	\$256.30	\$256.30 +
16	1	LH FRONT WHEEL BEARING HUB	\$167.40	\$167.40 +
17	1	LH FRONT LOWER ARM	\$562.30	\$562.30 +
18	1	LH FRONT KUNCKLER ARM	\$639.80	\$639.80 +
19	1	LH FRONT SHOCK ABSORBER	\$470.50	\$470.50 +
20	1	FRONT SUPPORT PANEL <i>new</i>	\$431.20	\$431.20 +

3905.70

2929.27

TOTAL : \$8,141.60
LESS 25 % \$2,035.40
SUB-TOTAL : \$6,106.20

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	FRONT BUMPER CLIPS <i>mu</i>	\$60.00	\$60.00 30
2	1	FRONT FENDER INNER SHIELD CLIPS <i>mu</i>	\$60.00	\$60.00 +
3	1	RADIATOR COOLANT <i>mu</i>	\$80.00	\$80.00 +
4	1	FRONT BUMPER UNDER COVER CLIPS <i>mu</i>	\$60.00	\$60.00 +

30

TOTAL: \$260.00

TOTAL PARTS: \$6,366.20

Labour charges

1	LABOUR FOR PANEL BEATING	400	\$1,200.00
2	LABOUR FOR SPRAYPAINTING	400	\$1,000.00
3	WIRING CHECK	30	\$120.00
4	TO APPLY RUST PROOF / TUF RF COAST ON ACCIDENT AREAS	40	\$300.00
5	LABOUR FOR REMOVE & RENEW LH FRONT UNDERCARRIAGE	x	\$300.00
6	LABOUR FOR PRESS OUT & RENEW LH FRONT WHEEL BEARING	x	\$120.00
7	TO CONDUCT WHEEL ALIGNMENT	870	\$150.00
8	LABOUR FOR REMOVE & REFIX AIR CON CONDENSER TO FACILITATE REPAIR VACUUM & TOP AIR CON GAS	x	\$150.00
9	LABOUR FOR REMOVE & REFIX RADIATOR TO FACILITATE REPAIR TOP UP RADIATOR COOLANT / CONDUCT RADIATOR PRESSURE TEST	x	\$200.00

Subtotal :- \$3,540.00

Total:- \$9,906.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Calculated: 382927

H/S 3K

Adrian Li
w/s 01/06/24

3K

04 days