

Your Ref : S0M02YB0

Date: 29<sup>th</sup> June 2021

Our Ref : CS4/ASM21006178/Nvce2

**M/s Axa Insurance Pte Ltd**

8 Shenton Way #24-01

Axa Tower

Singapore 068811

(The Motor Claims Department)

Attn : Chan Kian Chuan

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SLX 1888E  
ACCIDENT ON 06/12/2020**

Instruction was received to inspect the vehicle Reg. No. SLX 1888E. The inspection was conducted on 31/05/2021 at the premises of M/s Comfortdelgro Engineering Pte Ltd, 205 Braddell Road, Blk C, 3RD Floor, Singapore 579701.

The following vehicle information was recorded:

Registration Number	: SLX 1888E
Make/Model	: Audi S4 Sedan 3.0 TFSI QU TIP (SR) (R/S/ABAG)
Year of Registration	: 2017
Body Colour	: Blue
Chassis Number	: WAUZZZF48HA164062
Engine Capacity	: 2995 cc
Speedometer Reading	: Not Available

The following are our comments:-

- (a) The vehicle caught fire. The cause of fire probably due to electrical short circuit.  
(Details see photographs enclosed)
- (b) In view of this, we are of the opinion that it would be **unsafe** to proceed with the repairs due to extensive damages on the chassis under the category of **the section 2 of THE ROAD TRAFFIC ACT on THE MOTOR VEHICLES (CONSTRUCTION AND USE) (AMENDMENT NO.2) RULES 1989**, that:  
*no vehicle shall be fitted with a replacement chassis or any body part where the chassis is an integral part of the vehicle.*  
and we therefore recommend it to be written off as **“Total Loss”**

Market Value S\$ 160,000.00 (est)

Less: LTA Reimbursement Value (RV) (S\$ 102,116.00)

Nett Liability S\$ 57,884.00  
=====

Vehicle Inspected By:



MUHD NAZRIL (NAZ)

Technical Investigator  
LL.B. (Hons) London



K.K.LAU

MSc(Eng M), B Eng(Hons), Peng(UK),  
MASME(USA), B Bus(Aust), MBA(UK),  
IEng(UK), MIIE(mech), MinstAEA, MFIEA,  
MIRTE, MIMI, MSAE, MCIARD, AM, NIJAAR(USA),  
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),  
Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.