

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0438/2021/GW
DATE : 22-May-21
WIP :

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 31/3/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR LEVENT TAVSANCI
ADDRESS : 60 WEST COAST ROAD
#04-74
SINGAPORE 126834
TELEPHONE : HP +65 98204102
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800107487-02
VEHICLE NO : **SJQ 1952 M**
MODEL CODE : AUDI A6 1.8 TFSI
MODEL YEAR : 17/9/2018
ENGINE NO : CYG024083
CHASSIS NO : WAUZZZ4G8JN051479
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 18-May-21
PLACE OF ACCIDENT : 60 WEST COAST ROAD , SINGAPORE 126834

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJQ 1952 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	250 ✓
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR, RADIATOR. CHECK ELECTRICALS FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,400.00	x.
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER AND LHS HEADLIGHT. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 5,600.00	1500 ✓
5	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, LHS FRONT FENDER AND BONNET.	\$ 5,200.00	1650 ✓
6	TO CARRY OUT CALIBRATION FOR FRONT BUMPER RADAR SENSOR.	S/N \$ 480.00	x.
7	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00	192 ✓
TOTAL LABOUR CHARGES		: \$ 13,944.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJQ 1952 M

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS		
1	FRONT BUMPER <i>Distorted</i>	1	\$ 3,268.00	✓	2614.40	
2	FRONT BUMPER FIXING PARTS <i>New</i>	1	\$ 543.00	+		
3	FRONT BUMPER LOWER GRILLE - CENTER <i>New</i>	1	\$ 128.00	x		
4	FRONT BUMPER LOCKING CLIP <i>New</i>	14	\$ 55.00	+		
5	FRONT BUMPER ADAPTER	1	\$ 38.00	+		
6	FRONT BUMPER CLOSING ELEMENT <i>New torn</i>	1	\$ 219.00	+	174.80	
7	FRONT BUMPER LOWER SPOILER <i>New</i>	1	\$ 249.00	+		
8	FRONT BUMPER SHORT SPOILER <i>Distorted</i> <i>RH New</i>	1	\$ 945.00	?x		
9	FRONT RADIATOR GRILLE <i>New</i>	1	\$ 1,934.00	+		
10	FRONT RADIATOR GRILLE COVER <i>New</i>	1	\$ 36.00	+		
11	FRONT RADIATOR GRILLE SUPPORT SENSOR-LH/RH <i>New</i>	2	\$ 132.00	+		
12	FRONT AIR GUIDE GRILLE-LH <i>cut</i>	1	\$ 572.00	✓	457.60	
13	FRONT AIR GUIDE GRILLER INNER COVER-LH <i>New</i>	1	\$ 51.00	+		
14	FRONT WHEEL SPOILER-LH <i>New</i>	1	\$ 264.00	+	211.20	damaged
15	FRONT HEADLIGHT WASHER CAP-LH <i>New</i>	1	\$ 58.00	+		
16	FRONT FOAM FILLER PIECE <i>New</i>	1	\$ 237.00	+		
17	FRONT REINFORCEMENT BEAM <i>New</i>	1	\$ 872.00	+		
18	FRONT REINFORCEMENT BEAM COVER <i>New</i>	1	\$ 123.00	+		
19	FRONT FENDER BRACE -LH <i>New</i>	1	\$ 30.00	+		
20	FRONT BUMPER GUIDE PIECE-LH <i>New</i>	1	\$ 38.00	+		
SUB TOTAL SPARE PARTS			\$ 9,792.00			

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJQ 1952 M

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	STICKER FO AIR CONDITIONER <i>3 new</i>	1	\$ 20.00	+
22	STICKER FOR SIGN ' CAUTION ' <i>3 new</i>	1	\$ 14.00	+
23	FRONT SIGNAL HORN-LOW TONE <i>3 new</i>	1	\$ 201.00	XX
24	FRONT SIGNAL HORN BRACKET-LH <i>3 new</i>	1	\$ 47.00	XX
25	FRONT SENSOR OUTER <i>new</i>	1	TBC	+
26	FRONT SENSOR SEAL RING <i>Not n</i>	4	\$ 6.00	+
27	FRONT FENDER-LH <i>Backend</i>	1	\$ 1,391.00	✓ 1112.80
28	FRONT FENDER ATTACHMENT PARTS <i>new</i>	1	\$ 102.00	+
29	FRONT STONE GUARD FILM-LH <i>3 new</i>	1	\$ 121.00	+
30	FRONT FENDER BRACE-LH <i>Best.</i>	1	\$ 96.00	? 76.42
31	BONNET <i>Dented</i>	1	\$ 5,436.00	✓ 4348.80
32	BONNET ATTACHMENT PARTS <i>new</i>	1	\$ 178.00	+
33	BONNET CATCH HOOK <i>2</i>	1	\$ 140.00	+
34	BONNET LOCK STRIKER PLATE <i>1 new</i>	2	\$ 100.00	+
35	BONNET LATCH	1	\$ 18.00	+
36	BONNET LID LOCK WITH MICRO SWITCH -LH/RH <i>Not n</i>	2	\$ 427.00	+
37	BONNET LOCK COVER <i>Not n</i>	1	\$ 4.00	+
38	LED HEADLIGHT MOUNTING-LH <i>are new</i>	1	\$ 118.00	?
39	LED HEADLIGHT-LH <i>cancel</i>	1	\$ 9,540.00	✓ 7632
40	FAN FOR HED HEADLIGHT-LH <i>Not n</i>	1	\$ 398.00	+
SUB TOTAL SPARE PARTS			\$ 18,357.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.
BL-04/05/21

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJQ 1952 M

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
40	LED HEADLIGHT POWER MODULE FOR DAY DRIVING -LH <i>Not new</i>	1	\$ 553.00	+
41	LED HEADLIGHT CONTROL MODULE-LH <i>Not new</i>	1	\$ 557.00	+
42	LED HEADLIGHT HOUSING-LH <i>Not new</i>	1	\$ 34.00	+
43	LIFT CYLINDER FOR HEADLIGHT WASHER SYSTEM -LH <i>Not new</i>	1	\$ 236.00	+
44	HOSE FOR HEADLIGHT WASHER SYSTEM-LH <i>Not new</i>	1	\$ 488.00	+
45	FRONT LOCK CARRIER <i>Not new</i>	1	\$ 1,248.00	+
46	FRONT SUPPORT FOR COOLANT REGULATOR <i>Not new</i>	1	\$ 37.00	+
47	RADIATOR COOLANT <i>Not new</i>	6	\$ 142.00	+
48	RADIATOR AIR GUIDE-LH <i>Not new</i>	1	\$ 29.00	+
49	RADIATOR AIR GUIDE UPPER CENTRE-LH <i>Not new</i>	1	\$ 29.00	+
50	RADAR SENSOR-LH <i>Not new</i>	1	\$ 5,892.00	+
51	RADAR SENSOR COVER-LH <i>Not new</i>	1	\$ 13.00	+
52	SUNDRIES <i>Not new</i>	1	\$ 300.00	✓ 56.24
53	FRONT NO. PLATE <i>Not new</i>	S/N	\$ 60.00	+
TOTAL SPARE PARTS			\$ 37,767.00	
TOTAL LABOUR CHARGES			\$ 13,944.00	
GRAND TOTAL			\$ 51,711.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-04/05/21

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Ly*
SURVEYED DATE : *25/05/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 06 Days.*
H.S.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT