

OUR REF:BUS/05/21/5038(AIG) - ACCIDENT ON 19/05/21 INVOLVING SMB350A AND SGG7988J ALONG CHOA CHU KANG AVENUE 4 (BS:44499, BLK 429A CP)

Ong Hua Yen (Auto Svcs/FM&SuppSvcs/Claims & IA/Claims & IA)

<OngHuaYen@smrt.com.sg>

Tue 22/6/2021 5:47 PM

To: Admin A <admin-a@lkkauto.com>;CS A Team <cs-a@lkkauto.com>

Cc: Chong Fei Yuan (Auto Svcs/FM&SuppSvcs/Claims & IA) <FeiYuan@smrt.com.sg>;Balqish Binte Abdul Halil (Auto Svcs/FM&SuppSvcs/Claims & IA/Claims & IA) <BalqishBAH@smrt.com.sg>;Tan Wei Teck (Auto Svcs/FM&SuppSvcs/Claims & IA/Claims & IA) <TanWeiTeck@smrt.com.sg>;Karen Chan Siau Chin (Auto Svcs/FM&SuppSvcs/Claims & IA/Claims & IA) <ChanSiauChin@smrt.com.sg>;Foo Chit Yan (Auto Svcs/FM&SuppSvcs/Claims & IA/Claims & IA) <FooChitYan@smrt.com.sg>

 3 attachments (299 KB)

BUS 05 21 5038 INV.pdf; BUS 05 21 5038 LTA.pdf; BUS 05 21 5038 SAS.pdf;

Dear Sirs,

We claim on behalf of SMRT Buses Ltd, owner of the vehicle registration number SMB350A. Your client's negligent driving has caused the above accident. As a result, my client has suffered the following losses,

Cost of Repair	\$789.00
Loss of Use	\$962.50 (3.5 days x \$275.00)
LTA search fee	\$7.00
Total	\$1,758.50

We enclose the following documents,

- 1) 1) Repair Invoice
- 2) 2) GIA report
- 3) LTA Search Fee

We look forward to your confirmation to settle our claims within 15 days from the date of this email. Payment by cheque shall be crossed and made payable to SMRT Buses Ltd.

Thanks & Regards
Hua Yen