



23 FEB 2022

Your Ref : SKQ4245P
Our Ref : TP/11730/FBQ8056Z/SKQ4245P

BY EMAIL

AIG Pacific Insurance Pte Ltd
Chartis Building
78 Shenton Way
#07-16
Singapore 79120

ATTN: Motor Claims Dept

Dear Sir/Madam,

Accident Involving FBQ8056Z & SKQ4245P on 22/01/2021

We refer to the above-mentioned matter.

As instructed by our client, we proceed to quantify our claim as itemized below:

1. Cost of Repair (Inc 7% GST)	\$1,701.19
2. Loss of Use (4days x \$20)	\$ 80.00
	<u>\$1,781.19</u>
On 50% Liability	\$ 890.60
3. GIA Vehicle Insurance Search Fee	\$ 2.00
TOTAL	<u>\$ 892.60</u>

We attached our Tax Invoice and GIA Search Invoice for your perusal.

Please acknowledge receipt.

If you require any further clarification, please do not hesitate to contact Mr Raymond at 6281 6520 ext. 220

Thank you.

BAN HOCK HIN CO PTE LTD

.....
Raymond Tan
Manager/Insurance Dept





BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATION | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

TAX INVOICE

Customer :

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120
MOTOR CLAIMS DEPT

GST Reg No. : M2-0010542-7

Invoice No. : **DLCR40109703-I11730**
Invoice Date : 22/02/2022
Payment Due Date : 24/03/2022

CLAIM NO. : 11730
POLICY NO. : V0107670
VEHICLE NO. : FBQ8056Z
MAKE/MODEL : KYMCO / SUPER JOCKEY150

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	REPAIR REAR FIBER BOX	Repair	1	\$168.00	\$168.00
2	SPRAY PAINT ON REAR FIBRE BOX	Spray	1	\$220.00	\$220.00
3	STICKER (SINGAPORE POST) BOX REAR	REPLACE	1	\$47.00	\$47.00
4	TRANSPORT CHARGES	Supply/Install	1	\$35.00	\$35.00
5	LABOUR		1	\$300.00	\$300.00
6	BRACKET BELLY PAN	REPLACE	4	\$7.00	\$25.20
				Disc %: 10%	
7	COLLAR MAINSTAND	REPLACE	2	\$7.00	\$12.60
				Disc %: 10%	
8	COVER FRONT (BLACK)	REPLACE	1	\$147.00	\$132.30
				Disc %: 10%	
9	COVER LH SIDE	REPLACE	1	\$129.00	\$116.10
				Disc %: 10%	
10	COVER RH B BODY	REPLACE	1	\$41.00	\$36.90
				Disc %: 10%	
11	COVER RH SIDE	REPLACE	1	\$129.00	\$116.10
				Disc %: 10%	
12	COVER TRANSMISSION	REPLACE	1	\$196.00	\$176.40
				Disc %: 10%	
13	GASKET COVER AUTOCLUTCH	REPLACE	1	\$40.00	\$36.00
				Disc %: 10%	
14	LEVER BRAKE RH	REPLACE	1	\$17.00	\$15.30
				Disc %: 10%	
15	RUBBER SOFT ROUND TYPE	REPLACE	84	\$0.75	\$56.70
				Disc %: 10%	
16	STAND MAIN	REPLACE	1	\$107.00	\$96.30
				Disc %: 10%	





bizSAFE₃



<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
		SUB TOTAL			\$1,589.90
		GST @ 7 %			\$111.29
		GRAND TOTAL (SGD)			<u>\$1,701.19</u>

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Printed by : RAYMOND

bizSAFE₃

INSURER ENQUIRY

Find insurer

Vehicle reg. no.

SKQ4245P

Date of Accident

22/01/2021



Reset

% RESULT & RECEIPT

TP Insurer Enquiry

Insurance **AIG Asia Pacific Insurance Pte....**

Period of Insurance **27/11/2020 - 26/11/2021**

Requested By **Hasrianah Bte Hassan (Ban Ho...**

Requested Date **14/05/2021 09:50**

Payment details

Request Amount: **S\$1.87**

GST Amount: **S\$0.13**

Total Amount Due (GST Inclusive): **S\$2**

General Insurance Association

Records Management Centre

GST Registration No: **M400017735**