



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

Blk 1 Kaki Bukit Ave 6

24/05/2021

01-43

Singapore 417883

Accident date : 14/04/2021

Estimated repair cost for vehicle no: SMX9325Z NISSAN FAIRLADY 370Z 3.7L MT ABS D/AB

HID 2WD 2DR

CHASSIS:JN1GAAZ34Z0600310 (2009)

S/N	Qty	Items	U/price	Amount
1	1	FRONT BUMPER <i>Head torn</i>	\$978.90	\$978.90
2	1	FRONT BUMPER SIDE RETAINER LH <i>new</i>	\$61.50	\$61.50
3	1	LH FRONT FENDER <i>Dented</i>	\$860.40	\$860.40
4	1	LH FRONT FENDER EMBLEM <i>new</i>	\$105.80	\$105.80
5	1	LH FRONT FENDER INNER SHIELD <i>new</i>	\$134.60	\$134.60
6	1	LH FRONT DOOR <i>Dented</i>	\$1,986.30	\$1,986.30
7	1	LH FRONT WINDMIRROR <i>Damaged</i>	\$558.30	\$558.30
8	2	LH FRONT DOOR HING <i>new</i>	\$65.10	\$130.20
9	1	LH FRONT DOOR CHECKER <i>3 pieces</i>	\$48.00	\$48.00
10	1	LH FRONT WEATHER STRIPE	\$164.00	\$164.00

TOTAL : \$5,028.00
LESS 10 % \$502.80
SUB-TOTAL : \$4,525.20

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	ALL SPORT RIM (1 SET) <i>cut</i>	\$3,600.00	\$3,600.00
2	1	LH FRONT TYRE <i>new</i>	\$320.00	\$320.00
3	1	FRONT BUMPER CLIPS <i>new</i>	\$80.00	\$80.00
4	1	LH FRONT FEDNER INEER SHIELD CLIPS <i>new</i>	\$60.00	\$60.00
5	1	LH ROCKER PANEL GARNISH CLIPS <i>2</i>	\$50.00	\$50.00
6	1	LH ROCKER PANEL GARNISH SEAL <i>new</i>	\$120.00	\$120.00
7	1	LH ROCKER PANEL GARNISH <i>Repairs included</i>	\$1,200.00	\$1,200.00

TOTAL: \$5,430.00

TOTAL PARTS \$9,955.20

Labour charges

- 1 LABOUR FOR PANEL BEATING
- 2 LABOUR FOR SPRAYPAINTING
- 3 WIRING CHECK
- 4 TO APPLY RUST / TUFF COAT PROOF ON ACCIDENT AREAS
- 5 TO CONDUCT ALL WHEEL ALIGNMENT
- 6 LABOUR FOR REMOVE & TRANSFER LH FRONT DOOR FITTING
- 7 TO CONDUCT WATER CHECK LEAKAGE

500 ~~\$1,600.00~~

900 ~~\$2,200.00~~

1690

30 ~~\$80.00~~

80 ~~\$200.00~~

80 ~~\$250.00~~

100 ~~\$400.00~~

X ~~\$120.00~~

Subtotal :- \$4,850.00

Total:- \$14,805.20

Adrian
4/3 25/05/21

05 Days

Wheel: 6873.25

L/S: SSK

SSK

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: