LKK Auto Consultants #01-25 Paya Ubi Industrial Park, 51 Ubi Avenue 1 408933

Insurer Reference: DM21H000595-JG

Repairer Reference:

Date calculated: 05/07/2021 4:57 PM

Full Report Registration: SMX9325Z

Printed: 05/07/2021 4:59 PM

14/04/21

Summary Information

Claim

Location: Singapore (SG)

Printed by: KK LAU
Claim Reference: DM21H000595-JG

Estimated Repair Time: Actual Repair Days: Work Provider: EQ Insurance Pte Ltd Currency: SGD

Date of Incident: Hire Car Start: Hire Car End:

Vehicle Details

Vehicle

Manufacturer: NISSAN
Model: 370Z (Z34)
Sub Model: BASE MODEL
Model Sheet Number: 71 AJ 01
Registration: SMX9325Z

VIN number: JN1GAAZ34Z0600310

Odometer: **Model Specs**

2-DOOR (ROADSTER)


Vehicle Condition

Vehicle Status

Pre-Accident Damage: Date of Inspection:

Damage Areas

All
Underbody



Labour

Time Base 10 WU/h

Price = 60.00 SGD/h

Code	Description		wu	Price SGD
NO NUMBER	JOB ALLOWANCE		5.0	30.00
1000A2	RENEW L/FRT WING (BUMPER REMOVED) INCLUDE: WHEELHOUSE LINER AND REQUIRED ATTACHED PARTS IN REPAIR AREA R + R		15.0	90.00
2990A2	ADJUST HEADLAMPS		2.0	12.00
3000A2	RENEW LEFT FRONT DOOR INCLUDES: R + R DOOR, CONVERT ALL ATTACHED PARTS, ADJUST DOOR, APPLY RUST PROOFING WAX		25.0	150.00
1737	L/DOOR MIRROR REMOVE AND REFIT	1	5.0*	90.00
1005	ROCKER PANEL GARNISH REMOVE&REFIT	2	0.0*	120.00
1006	WHEEL ALIGNMENT LABOUR		5.0*	90.00
1007	APPLY RUST/TUFF COAT LABOUR		5.0*	90.00
1008	WIRING CHECK LABOUR		5.0*	30.00
	Labour Cost	Hrs	WU	
	Panel / Mechanical Labour	11.70 1	17.0	702.00
	Total of Labour			702.00
Paint				

Paint Work	SYSTEM AZT	Time Basis 10 WU/h	
Code	Description	WU Price SGD	
	L/F WING NEW PART PAINTING	11.0	
	LEFT DOOR NEW PART PAINTING	15.0	
	SPRAY PAINTING NEW PART PAINTING	50.0*	

Paint Material Per Part

Code	Description	Price SGD
0741	L/F WING NEW PART PAINTING	19.75
1481	LEFT DOOR NEW PART PAINTING	34.66

Labour Cost - Paint		Hrs	WU	Price SGD
Factor	60.00 SGD/h			
Time Paint			76.0	
Preparation Main Work Metal		0.70	7.0	42.00
Total	10 WU/h	8.30	83.0	498.00

Material Cost - Paint	Price SGD
New Part Painting	54.41
Material-constant Metal	18.10
Total	72.51

Spare Parts

				prices as at 2015-06-01/01
Code	Description	Part Number	Part Source	Price SGD

Code	Description	Part Number	Part Source	Price SGD
0741	L/F WING	F3101 1EAMA	Original	860.40
1481	LEFT DOOR	H010A 1ETMA	Original	1,650.00
1000	L/F WING EMBLEM	EMBLEM	Original	105.80
1001	LEFT DOOR MIRROR	MIRROR	Original	558.30
f: OEM Parts n: Non-OEM Parts u: Used parts	Savings Subtotal Subtotal Discount(-	+10.00%)		0.00 3,174.50 -317.45
	Total			2,857.05
Eveluac				

Extras

Code	Description	Price SGD
1002	SPORT RIM RIM	650.00*
1004	ROCKER PANEL GARNISH GARNISH	650.00*
	Total Extras	1,300.00

Final Calculation

	SGD	SGD
Parts	3,174.50	
Total Discount(+10.00%)	-317.45	
Total Parts		2,857.05
Labour Time Base 10 WU/h		
Total 117.0 WU X 60.00 SGD/h	702.00	
Total of Labour		702.00
Total Of Extras		1,300.00
Paint Work Time Base 10 WU/h		
Labour Cost 83.0 WU X 60.00 SGD/h	498.00	
Material Cost	72.51	
Total Paint Including Material		570.51
Repair Cost Excludes GST		5,429.56
GST (+7.0%)		380.07
Repair Cost Included GST		5,809.63

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.