

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0445/2021/GW
DATE : 25-May-21
WIP :

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MDM LOW YIN LENG
ADDRESS : 1 TREVOSE PLACE
SINGAPORE 297985
TELEPHONE : HP +65 96191720
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100216570-10
VEHICLE NO : **SCM 9200 B**
MODEL CODE : AUDI A4 1.8 TFSI MU
MODEL YEAR : 25/6/2009
ENGINE NO : CDH 051315
CHASSIS NO : WAUZZZ8K79A235653
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
DATE OF ACCIDENT : 10-May-21
PLACE OF LOCATION : BUKIT TIMAH RD, JUNCTION OF BALMAROL RD

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SCM 9200 B

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS , OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 700.00	250
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,200.00	X
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, RHS FRONT FENDER AND BOTH HEADLIGHT. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,900.00	500
5	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, HINGES AND BONNET.	\$ 3,200.00	1100
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 10,552.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCM 9200 B

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Rehnd</i>	1	\$ 2,560.00	✓
2	FRONT BUMPER FIXING PARTS <i>Ne n</i>	1	\$ 259.00	+
3	FRONT BUMPER SUPPORT-LH/RH <i>ne n</i>	2	\$ 186.00	+
4	FRONT BUMPER GUIDE SECTION-LH/RH <i>Ne n</i>	2	\$ 88.00	+
5	FRONT BUMPER COVER <i>crushed.</i>	1	\$ 127.00	✓
6	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE <i>Ne n</i>	1	\$ 176.00	+
7	FRONT FOAM FILLIER PIECE ?	1	\$ 124.00	?
8	FRONT AIR GUIDE GRILLE-LH/RH <i>ne n</i>	2	\$ 344.00	+
9	FRONT BUMPER COVER SPACER PANEL <i>ne n</i>	1	\$ 98.00	+
10	FRONT BUMPER BRACKET-LH/RH ?	2	\$ 456.00	?
11	FRONT REINFORCEMENT BEAM <i>dentad</i>	1	\$ 926.00	✓
12	STICKER FOR 'SIGN CAUTION' <i>3 ne</i>	1	\$ 14.00	✓
13	STICKER FOR AIR CONDITIONER	1	\$ 30.00	✓
14	RADIATOR GRILLE <i>crushed</i>	1	\$ 706.00	✓
15	RADIATOR GRILLE COVER ?	1	\$ 58.00	?
16	SIGNAL HORN-LH/RH <i>3 ne</i>	2	\$ 402.00	+
18	SIGNAL HORN BRACKET-LH/RH	2	\$ 50.00	+
19	BONNET <i>Repair</i>	1	\$ 2,274.00	+
20	BONNET ATTACHMENT PARTS <i>Ne n</i>	1	\$ 168.00	+
SUB TOTAL SPARE PARTS		:	\$ 9,046.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCM 9200 B

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	BONNET LID HINGE-LH/RH <i>new</i>	2	\$ 148.00	+
22	BONNET CATCH HOOK <i>new</i>	1	\$ 140.00	✓
23	BONNET EDGE PROTECTION <i>new</i>	1	\$ 28.00	✓
24	BONNET LID LOCK WITH MICRO SWITCH <i>new</i>	1	\$ 214.00	+
25	BONNET LOCK COVER <i>new</i>	1	\$ 23.00	+
26	FRONT FENDER-RH <i>Regis</i>	1	\$ 990.00	+
27	FRONT FENDER ATTACHMENT PARTS-RH <i>new</i>	1	\$ 57.00	+
28	FRONT FENDER BRACE-RH LOWER	1	\$ 118.00	+
29	FRONT FENDER BRACKET-RH FRONT	1	\$ 53.00	+
30	FRONT FENDER BRACKET-RH REAR	1	\$ 49.00	+
31	FRONT WHEEL HOUSING LINER-RH	1	\$ 240.00	+
32	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	1	\$ 45.00	+
33	HEADLIGHT MOUNTING-LH/RH ?	2	\$ 236.00	?
34	HEADLIGHT BRACKET-LH/RH ?	2	\$ 156.00	?
35	FRONT LOCK CARRIER <i>new</i>	1	\$ 1,016.00	?
36	RADIATOR SUPPORT BRACKET-LH/RH <i>new</i>	2	\$ 90.00	?
37	A/C CONDENSER <i>new</i>	1	\$ 743.00	+
38	A/C CONDENSER O-RING <i>Not</i>	1	\$ 10.00	+
39	A/C CONDENSER SEAL RING <i>Nec</i>	1	\$ 7.00	+
40	A/C REFRIGERANT LINE O-RING	1	\$ 10.00	+
SUB TOTAL SPARE PARTS		:	\$ 4,373.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCM 9200 B

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	FRONT TEMPERATURE SENSOR BRACKET ?		\$ 19.00 ?	
42	RADIATOR AIR GUIDE-LH/RH ?	2	\$ 56.00 ?	
43	SEALING STRIP <i>new</i>		\$ 23.00 X	
44	HEADLIAMP-LH/RH <i>RH ut</i>	2	\$ 4,334.00 2167 2167	
45	FRONT NO. PLATE <i>Dented</i>	S/N	\$ 60.00	
46	SUNDRIES ?		\$ 300.00 ?	
TOTAL SPARE PARTS		:	\$ 18,211.00	
TOTAL LABOUR CHARGES		:	\$ 10,552.00	
GRAND TOTAL		:	\$ 28,763.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian L*
SURVEYED DATE : *27/05/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 04 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT