

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Veron.

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SCM 9200 B

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 700.00	250
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,200.00	X
* 4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, (RHS FRONT FENDER) AND BOTH HEADLIGHT. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,900.00	750. H.S.
* 5	TO RESPRAY FRONT BUMPER, (RHS FRONT FENDER) HINGES AND BONNET.	\$ 3,200.00	1100 1650. H.S.
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓ H.S.
TOTAL LABOUR CHARGES		\$ 10,552.00	

+ 1 working days

H.S.


Car-in

15/6/21.

WIP: 29118

PREMIUM AUTOMOBILES

KIAM



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCM 9200 B

AIB - Admin

- 4 day

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Rehnd</i>	1	\$ 2,560.00	✓
2	FRONT BUMPER FIXING PARTS <i>Neu</i>	1	\$ 259.00	+
3	FRONT BUMPER SUPPORT-LH/RH <i>Neu</i>	2	\$ 186.00	+
4	FRONT BUMPER GUIDE SECTION-LH/RH <i>Neu</i>	2	\$ 88.00	+
5	FRONT BUMPER COVER <i>crushed</i>	1	\$ 127.00	✓
6	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE <i>Neu</i>	1	\$ 176.00	+
7	FRONT FOAM FILLER PIECE ?	1	\$ 124.00	?
8	FRONT AIR GUIDE GRILLE-LH/RH <i>Neu</i>	2	\$ 344.00	+
9	FRONT BUMPER COVER SPACER PANEL <i>more damaged</i>	1	\$ 98.00	✓
10	FRONT BUMPER BRACKET-LH/RH ?	2	\$ 456.00	?
11	FRONT REINFORCEMENT BEAM <i>crushed</i>	1	\$ 926.00	✓
12	STICKER FOR 'SIGN CAUTION' ?	1	\$ 14.00	✓
13	STICKER FOR AIR CONDITIONER ?	1	\$ 30.00	✓
14	RADIATOR GRILLE <i>crushed</i>	1	\$ 706.00	✓
15	RADIATOR GRILLE COVER ?	1	\$ 58.00	?
16	SIGNAL HORN-LH/RH ?	2	\$ 402.00	+
18	SIGNAL HORN BRACKET-LH/RH ?	2	\$ 50.00	+
19	BONNET <i>Repair</i>	1	\$ 2,274.00	+
20	BONNET ATTACHMENT PARTS <i>Neu</i>	1	\$ 168.00	+
SUB TOTAL SPARE PARTS		:	\$ 9,046.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCM 9200 B

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	BONNET LID HINGE-LH/RH <i>new</i>	2	\$ 148.00	+	
22	BONNET CATCH HOOK	1	\$ 140.00	✓	
23	BONNET EDGE PROTECTION <i>new</i>	1	\$ 28.00	✓	
24	BONNET LID LOCK WITH MICRO SWITCH <i>new</i>	1	\$ 214.00	+	
25	BONNET LOCK COVER <i>new</i>	1	\$ 23.00	+	
26	FRONT FENDER-RH <i>Repair</i>	1	\$ 990.00	+	
27	FRONT FENDER ATTACHMENT PARTS-RH	1	\$ 57.00	+	
28	FRONT FENDER BRACE-RH LOWER	1	\$ 118.00	+	
29	FRONT FENDER BRACKET-RH FRONT	1	\$ 53.00	+	
30	FRONT FENDER BRACKET-RH REAR	1	\$ 49.00	+	
31	FRONT WHEEL HOUSING LINER-RH	1	\$ 240.00	+	
32	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 45.00	+	
33	HEADLIGHT MOUNTING-LH/RH <i>RH could</i>	2	\$ 236.00	?	118.
34	HEADLIGHT BRACKET-LH/RH	2	\$ 156.00	?	
35	FRONT LOCK CARRIER <i>new</i>	1	\$ 1,016.00	?	
36	RADIATOR SUPPORT BRACKET-LH/RH <i>new</i>	2	\$ 90.00	?	
37	A/C CONDENSER	1	\$ 743.00	+	
38	A/C CONDENSER O-RING	1	\$ 10.00	+	
39	A/C CONDENSER SEAL RING	1	\$ 7.00	+	
40	A/C REFRIGERANT LINE O-RING	1	\$ 10.00	+	
SUB TOTAL SPARE PARTS			\$ 4,373.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCM 9200 B

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	FRONT TEMPERATURE SENSOR BRACKET <i>Dmgd</i>	\$	19.00	<i>✓</i>
42	RADIATOR AIR GUIDE-LH/RH <i>?</i>	2 \$	56.00	<i>?</i>
43	SEALING STRIP <i>new</i>	\$	23.00	<i>X</i>
44	HEADLAMP-LH/RH <i>RH out</i>	2 \$	4,334.00	<i>2167</i>
45	FRONT NO. PLATE <i>Dented</i>	S/N \$	60.00	<i>✓</i>
46	SUNDRIES <i>?</i>	\$	300.00	<i>?</i>
TOTAL SPARE PARTS		:	\$ 18,211.00	
TOTAL LABOUR CHARGES		:	\$ 10,552.00	
GRAND TOTAL		:	\$ 28,763.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

Adrian King
H.S.
Resurveyed