

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0442/2021/HR
DATE : 24-May-21
WIP : 28404

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 25/5/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS FU ZHI JUN
ADDRESS : BLK 609 YISHUN STREET 61
#08-241
SINGAPORE 760609
TELEPHONE : HP +65 91540508
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070149506
VEHICLE NO : **SMV 7627 B**
MODEL CODE : A4 2.0 TFSI S TRONIC
MODEL YEAR : 20/10/2020
ENGINE NO : DEM 025290
CHASSIS NO : WAUZZZF48MA001132
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 21-May-21
PLACE OF ACCIDENT : NEAR OPP KHATIB MRT BUS STOP (59049)

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMV 7627 B

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	x
2	TO REMOVE AND TRANSFER LHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 350.00	280
3	TO REMOVE AND REINSTALL DASHBOARD ASSY AND CENTRE CONSOLE TO FACILITATE THE RENEWAL OF LHS A-PILLAR AND LHS SILL PANEL.	S/N \$ 3,200.00	x.
4	TO REMOVE AND REINSTALL LHS FRONT SEAT ASSY, ABCD PILLAR TRIMS, SILL TRIMS, CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS.	S/N \$ 1,800.00	x.
5	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	x.
6	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, LHS FRONT DOOR AND LHS HEADLIGHT. TO CUT OUT AND WELD LHS A-PILLAR AND LHS SILL PANEL. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	S/N \$ 5,600.00	1500.
SUB TOTAL LABOUR CHARGES		: \$ 11,780.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMV 7627 B

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, LHS FRONT DOOR, HINGES, LHS WING MIRROR COVER, DOOR ENTRANCE. LHS A-PILLAR AND LHS SILL PANEL.	\$	1800 5,300.00	3 x 550 = 1650 Mirror = 150 <u>1800</u>
8	TO RENEW LHS FRONT RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$	520.00	280
9	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$	384.00	192
TOTAL LABOUR CHARGES		:	\$ 17,984.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 7627 B

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Repair</i>	1	\$ 2,233.00	X.
2	FRONT BUMPER FIXING PARTS <i>Not New</i>	1	\$ 358.00	X
3	FRONT BUMPER SECURING STRIP <i>Not New</i>	2	\$ 71.00	X
4	FRONT BUMPER AIR GUIDE - LH <i>Not New</i>	1	\$ 44.00	X
5	FRONT BUMPER AIR GUIDE GRILLE - LH <i>Not New</i>	1	\$ 135.00	X
6	FRONT BUMPER TRIM - LH <i>Not New</i>	1	\$ 48.00	X.
7	FRONT BUMPER GUIDE SECTION - LH <i>Not New</i>	1	\$ 36.00	X
8	FRONT FENDER - LH <i>Dented</i>	1	\$ 1,092.00	✓
9	FRONT FENDER ATTACHMENT PARTS <i>Not New</i>	1	\$ 202.00	X.
10	FRONT FENDER CLOSING ELEMENT - LH ?	1	\$ 72.00	?
11	FRONT FENDER LONG BRACKET - LH ?	1	\$ 35.00	?
12	FRONT FENDER DEFORMATION BRACKET - LH ?	1	\$ 49.00	?
13	FRONT FENDER SHORT BRACKET ?	1	\$ 32.00	?
14	FRONT FENDER BRACE - LH ?	1	\$ 118.00	?
15	FRONT FENDER CLOSING ELEMENT - LH ?	1	\$ 33.00	?
16	FRONT WHEEL HOUSING LINER - LH ?	1	\$ 236.00	?
17	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>Not New</i>	1	\$ 139.00	X.
18	FRONT WHEEL SPOILER - LH	1	\$ 73.00	X
19	FRONT WHEEL SPOILER TRIM - LH <i>Not New</i>	1	\$ 31.00	X
20	HEADLIGHT COVER <i>Not New</i>	1	\$ 44.00	X
SUB TOTAL SPARE PARTS		:	\$ 5,081.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 7627 B

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	HEADLIGHT - LH <i>Not New</i>	1	\$ 7,685.00	X	
22	A/B PILLAR SECTIONAL PART - LH <i>Repair</i>	1	\$ 2,675.00	X	
23	FRONT DOOR - LH <i>Dented</i>	1	\$ 3,192.00	✓	
24	FRONT OUTER DOOR SEAL - LH <i>New</i>	1	\$ 205.00	✓	
25	FRONT DOOR BONDING AGENT ?	1	\$ 48.00	?	
26	FRONT DOOR CLEANING SOLUTION ?	1	\$ 68.00	?	
27	FRONT DOOR APPLICATOR <i>Not New</i>	1	\$ 8.00	X	
28	FRONT DOOR ATTACHMENT PARTS <i>Not New</i>	1	\$ 1,050.00	X	
29	FRONT DOOR CATCH LH ?	1	\$ 105.00	?	
30	FRONT DOOR UPPER HINGE - LH ?	1	\$ 44.00	?	
31	FRONT DOOR UPPER HINGE HALVES - LH ?	1	\$ 46.00	?	
32	FRONT DOOR LOWER HINGE - LH ?	1	\$ 47.00	?	
33	FRONT DOOR LOWER HINGE HALVES - LH ?	1	\$ 45.00	?	
34	FRONT DOOR INNER SEAL <i>Not New</i>	1	\$ 205.00	X	
35	FRONT WING MIRROR MOUNTING - LH <i>Lot</i>	1	\$ 1,089.00	✓	
36	FRONT WING MIRROR CAP - LH <i>Not New</i>	1	\$ 289.00	+	
37	FRONT WING MIRROR GLASS - LH <i>Not New</i>	1	\$ 1,229.00	X	
38	FRONT DOOR WINDOW REGULATOR - LH <i>Not New</i>	1	\$ 282.00	X	
39	FRONT DOOR WINDOW SLOT SEAL TRIM - LH <i>Not New</i>	1	\$ 307.00	+	
40	FRONT DOOR WINDOW GUIDE TRIM STRIP <i>Not New</i>	1	\$ 257.00	X	
SUB TOTAL SPARE PARTS			\$ 18,876.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 7627 B

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	FRONT A -PILLAR TRIM <i>nlc m</i>	1	\$ 228.00	<i>+</i>
42	FRONT SILL TRIM STRIP <i>nlc m</i>	1	\$ 120.00	<i>+</i>
43	FRONT ALUMINIUM RIM LH <i>ut</i>	1	\$ 1,155.00	<i>✓</i>
44	ACRYLIC SEALANT <i>2</i>	S/N	\$ 180.00	<i>+</i>
45	CAVITY WAX <i>nlc m</i>	S/N	\$ 140.00	<i>+</i>
46	STONE CHIP	S/N	\$ 180.00	<i>+</i>
47	METAL FILLER POWDER	S/N	\$ 280.00	<i>+</i>
48	SUNDRIES <i>?</i>		\$ 400.00	<i>?</i>
TOTAL SPARE PARTS		:	\$ 26,640.00	
TOTAL LABOUR CHARGES		:	\$ 17,984.00	
GRAND TOTAL		:	\$ 44,624.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :

SURVEYED DATE :

AUTHORISED DATE :

EXCESS COST :

LIABILITY :

REMARKS :

Adrian L
25/05/21.

Not Authorised, 05 Days.

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT