

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9923L**AAD2105-104***Not Authorized**Return by paint**22524.13*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model.:

Date of Accident :

Third Party Insurer :

Date of Registration:

25 MAY 2021**SHD9923L**

JTDKB3FU703093290

TOYOTA

PRIUS GEN 4

22/05/2021

ALG.

30/12/2020

PART		LIST	
1	COVER, REAR BUMPER	\$	<i>Bu</i> 485.60 ✓
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	<i>Bu</i> 332.70 ✓
1	GUARD, REAR BUMPER, CENTER	\$	<i>Bu</i> 374.50 ✓
1	COVER, REAR BUMPER, LOWER	\$	<i>Bu</i> 22.00 ✓
1	RETAINER, REAR BUMPER SIDE, LH	\$	<i>Sh</i> 132.60 X
1	RETAINER, REAR BUMPER SIDE, RH	\$	<i>Sh</i> 132.60 X
1	REFLECTOR ASSY, REFLEX, LH	\$	<i>Sh</i> 39.00 X
1	REFLECTOR ASSY, REFLEX, RH	\$	<i>Sh</i> 39.00 X
1	PANEL SUB-ASSY, BODY LOWER BACK	\$	<i>R</i> 651.00 X
1	COVER, DECK TRIM, REAR	\$	<i>Sh</i> 126.70 X
1	COVER, FLOOR UNDER, NO.2 (RH)	\$	<i>Sh</i> 241.90 X
1	COVER, FLOOR UNDER, NO.1 (LH)	\$	<i>Sh</i> 175.10 X
1	COVER, REAR FLOOR (CTR)	\$	<i>Sh</i> 229.90 X
1	LENS & BODY, REAR COMBINATION LAMP, RH	\$	<i>Sh</i> 339.60 X
1	LENS & BODY, REAR COMBINATION LAMP, NO.2 RH	\$	<i>Sh</i> 261.00 X
1	LAMP ASSY, REAR, LH	\$	<i>Sh</i> 293.60 X
1	LAMP ASSY, REAR, RH	\$	<i>Sh</i> 293.60 X
1	PANEL SUB-ASSY, BACK DOOR	\$	<i>R</i> 1,147.80 X
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	\$	<i>cm</i> 913.60 ✓
1	STAY ASSY, BACK DOOR, LH	\$	<i>Sh</i> 242.50 X
1	STAY ASSY, BACK DOOR, RH	\$	<i>Sh</i> 242.50 X
1	HINGE ASSY, BACK DOOR, LH	\$	<i>R</i> 61.00 X
1	HINGE ASSY, BACK DOOR, RH	\$	<i>R</i> 61.00 X
1	ORNAMENT SUB-ASSY, BACK DOOR	\$	<i>Ne</i> 47.90 ✓
1	PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2	\$	<i>Ne</i> 54.60 ✓
1	PLATE, BACK DOOR NAME, NO.1	\$	<i>Ne</i> 54.60 ✓

Trans-cab Auto Services Pte Ltd**AAD2105-104**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9923L

1 BOARD ASSY, BACK DOOR TRIM

		<i>Sm</i> 259.2 <i>X</i>
TOTAL	\$	7,255.10
25%	\$	1,813.78
	\$	5,441.33

Special Nett

1SET PARKING AID

\$ *Sm* 700.00 *X*

1SET REAR BUMPER CLIP

\$ *na* 85.00 *30sm*

1 REAR NUMBER PLATE WITH MOULDING

\$ *Sm* 200.00 *X*

1 REAR FLOOR UNDERCOVER CLIP

\$ *na* 180.00 *X*

1 REAR SPOILER CLIP

\$ *na* 70.00 *X*

1 BUMPER CENTRE GUARD CLIP

\$ *na* 80.00 *X*

1 REAR BUMPER PROTECTOR

\$ *na* 180.00 *X*

1 REAR BUMPER RETAINER CLIP

\$ *na* 75.00 *X*

1 BOOT STICKER TRANSCAB

\$ *na* 100.00 *30sm*

1 BOOT STICKER 65553333

\$ *na* 100.00 *30sm*

2 WINDSCREEN SEALANT

\$ *na* 150.00 *X*

1 WINDSCREEN MOULDING

\$ *na* 200.00 *X*

1 WINDSCREEN INNER SPONGE SEAL

\$ *na* 130.00 *X***TOTAL \$ 1,570.00****TOTAL PARTS \$ 7,011.33****LABOUR**

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ *na* 240.00 *X*

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ *na* 380.00 *X*

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ *200l* 1,600.00

Trans-cab Auto Services Pte Ltd**AAD2105-104**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9923LTo transfer of rear end panel fittings, attachment to
facilitate bodywork repair.\$ *nn* 380.00 *X*

Putty And Spray Painting Of The Affected Portion.

\$ 1,600.00 *440*

To Remove And Refit Rear Big & Small W/Screen Glass

To Facilitate Bodywork Repair.

\$ *nn* 300.00 *X*

To reinstall rear bumper parking sensor.

\$ 170.00 *50*

To Check Electrical Lighting Concerned.

\$ 170.00 *10***TOTAL \$ 4,840.00****Over All Total \$ 11,851.33****(PART-BY-PART) Repair Days***10 Days**2 1/2 days***LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: