

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

LKK/AN Adnan

TEE CHIN HOCK
BLK 601 JURONG WEST ST 62 #04-173
SINGAPORE 640601

Contact : 97569822

TPAXA

Xiao Tony

ESTIMATE

Repair Code : CLM15249

Date in : 25/05/2021

Vehicle Num. : SMT829S

Model : TOYOTA NOAH HYBRID 1.8X CVT

Chassis/Eng# : ZWR800425901/ZZR2G23612

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR AIRCON COOLING UNIT ASSY <i>Cracked</i>	1	2521.00	2280 2,521.00
REAR BUMPER <i>Distorted</i>	1	972.25	✓ 972.25
REAR BUMPER BRACKET L/R <i>RH Dented</i>	2	172.25	70 344.50
REAR BUMPER REFLECTOR L/R <i>cracked</i>	2	59.80	✓ 119.60
REAR BUMPER RH END SEAL COVER <i>sehd</i>	1	109.30	✓ 109.30
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	171.70	120 343.40
REAR BUMPER TOW HOOK COVER <i>new</i>	1	42.10	X 42.10
REAR BUMPER UPPER GARNISH BRACKET L/R <i>new</i>	2	185.10	X 370.20
REAR BUMPER UPPER GARNISH L/R <i>RH torn</i>	2	372.80	372.80 745.60
REAR CARRIER JACK BRACKET <i>Dented</i>	1	57.30	✓ 57.30
REAR END PANEL <i>Dented</i>	1	781.90	683 781.90
REAR END PANEL ANTENNA SENSOR <i>Damaged</i>	1	72.00	✓ 72.00
REAR END PANEL INNER TOP GARNISH <i>sehd</i>	1	375.85	288 375.85
REAR END PANEL SIDE PANEL RUBBER STOPPER <i>new</i>	2	43.90	X 87.80
REAR FENDER INNER TRIM GARNISH L/R <i>Deformed</i>	2	781.90	✓ 1,563.80
REAR FLOOR PANEL <i>Rep's</i>	1	698.70	X 698.70
REAR FLOOR PANEL JACK BRACKET <i>new</i>	1	110.00	X 110.00
REAR FLOOR PANEL JACK CROSS BRACKET <i>new</i>	1	61.60	X 61.60

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

TEE CHIN HOCK

BLK 601 JURONG WEST ST 62 #04-173

SINGAPORE 640601

Contact : 97569822

ESTIMATE

Repair Code : CLM15249

Date in : 25/05/2021

Vehicle Num. : SMT829S

Model : TOYOTA NOAH HYBRID 1.8X CVT

Chassis/Eng# : ZWR800425901/2ZR2G23612

REAR FLOOR PANEL TRIM CARPET	<i>NE new</i>	1	581.90	X	581.90
REAR FLOOR PANEL UPPER DECK BOARD COVER	<i>Deformed</i>	1	1105.50	<i>845</i> 1,105.50	
REAR JACK BRACKET TRIM COVER	<i>Deformed</i>	1	129.10	✓	129.10
REAR RH TAILLAMP	<i>cracked</i>	1	731.35	✓	731.35
REAR TAILGATE	<i>Distorted</i>	1	1815.85	<i>1712</i> 1,815.85	
REAR TAILGATE 'HYBRID SYNERGY DRIVE' EMBLEM	<i>new</i>	1	50.00	✓	50.00
REAR TAILGATE DAMPER L/R	<i>NE new</i>	2	371.85	X	743.70
REAR TAILGATE GUIDE RUBBER STOPPER L/R	<i>new</i>	2	43.70	X	87.40
REAR TAILGATE INNER PULL GARNISH	<i>NE new</i>	1	33.50	X	33.50
REAR TAILGATE INNER TRIM GARNISH	<i>cracked</i>	1	570.30	✓	570.30
REAR TAILGATE MECHANISM LOCK	<i>Jammed</i>	1	581.90	<i>420</i> 581.90	
REAR TAILGATE MECHANISM LOCK STRIKER	<i>NE new</i>	1	39.00	✓	39.00
REAR TAILGATE OUTER CHROME LOGO	<i>NE new</i>	1	69.50	✓	69.50
REAR TAILGATE OUTER CHROME MOULDING	<i>cracked</i>	1	848.00	<i>582</i> 848.00	
REAR TAILGATE SIDE RUBBER STOPPER L/R	<i>Damaged</i>	2	17.60	✓	35.20
REAR TAILGATE WEATHER STRIP	<i>nt</i>	1	374.70	✓	374.70
REAR TAILGATE WINDSCREEN MOULDING L/R	<i>new</i>	2	175.45	✓	350.90
SLIDING DOOR RAIL COVER L/R	<i>cracked</i>	2	459.25	✓	918.50

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

TEE CHIN HOCK

BLK 601 JURONG WEST ST 62 #04-173

SINGAPORE 640601

Contact : 97569822

ESTIMATE

Repair Code : CLM15249

Date in : 25/05/2021

Vehicle Num. : SMT829S

Model : TOYOTA NOAH HYBRID 1.8X CVT

Chassis/Eng# : ZWR800425901/2ZR2G23612

			Subtotal before discount	18,443.20
Percentage discount	25%	13872.45		4,610.80
		10404.33	Sub-total 1	13,832.40
REAR BUMPER CLIPS - SET	new	1	50.00	30 50.00
REAR BUMPER REVERSE SENSOR - SET	Damaged	1	250.00	200 250.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	new	1	30.00	10 30.00
REAR FENDER INNER TRIM GARNISH L/R - SET	new	2	50.00	60 100.00
REAR NUMBER PLATE	3 NP	1	25.00	X 25.00
REAR NUMBER PLATE HOLDER	new	1	50.00	X 50.00
REAR TAILGATE INNER TRIM GARNISH CLIPS - SET	new	1	80.00	30 80.00
REAR TAILGATE OUTER CHROME MOULDING CLIPS	new	1	50.00	20 50.00
REAR TAILGATE WINDSCREEN GLASS SEALANT	new	1	60.00	✓ 60.00
			Subtotal before discount	695.00
Percentage discount	0%			0.00
			Sub-total 2	695.00
			Parts-total	14,527.40

LABOUR

To remove, change air con parts, vacuums, refill air con gas.

To reset system after repair works

100 150.00

X 200.00

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

TEE CHIN HOCK

BLK 601 JURONG WEST ST 62 #04-173

SINGAPORE 640601

Contact : 97569822

ESTIMATE

Repair Code : CLM15249

Date in : 25/05/2021

Vehicle Num. : SMT829S

Model : TOYOTA NOAH HYBRID 1.8X CVT

Chassis/Eng# : ZWR800425901/2ZR2G23612

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.	✓ 50.00
To remove, reinstall tailgate windscreen	120 150.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	80 140.00
To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.	1000 700 1,300.00
To remove and reinstall exhaust pipe.	X 100.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	2310 1100 1000 1,600.00
To apply anti-rust chemical on repaired and replaced panel.	60 100.00
Labour Total	3,790.00
Parts & Labour Total	18,317.40

*** This is a computer-generated document which requires no signature.***

page 4

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 1324338

H/S: 10.5K

07 Days.

10.5K