

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

Lfk Adm

ANDREW LEE CHEE WEI
 BLK 308A PUNGGOL WALK #10-428
 SINGAPORE 821308

Contact : 93833899

TP Budget Direct

Xiao Chan Repair Code : CLM16820

ESTIMATE

Date in : 02/06/2021

Vehicle Num. : SLX5497Z

Model : NISSAN QASHQAI 1.2 DIG-T CVT

Chassis/Eng# : SJNFEAJ11U2217271/HRA2584468A

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT LH DOOR <i>Dented</i>	1	1269.00	✓ 1,269.00
FRONT LH DOOR BLACK TAPE <i>Neu</i>	1	59.00	✓ 59.00
FRONT LH DOOR CHECKER <i>He m</i>	1	67.00	✗ 67.00
FRONT LH DOOR FRAME OUTER CHROME RIVET <i>He m</i>	10	6.00	✗ 60.00
FRONT LH DOOR HINGE (LOWER) <i>He m</i>	1	79.00	✗ 79.00
FRONT LH DOOR PROTECTOR <i>lit</i>	1	371.00	✓ 371.00
FRONT LH DOOR WEATHER STRIP <i>He m</i>	1	177.00	✗ 177.00
FRONT LH FENDER <i>He m</i>	1	715.00	✗ 715.00
FRONT LH FENDER ARCH GARNISH <i>lit</i>	1	517.00	✗ 517.00
Subtotal before discount			3,314.00
Percentage discount 10%			331.40
Sub-total 1			2,982.60
FRONT LH DOOR PROTECTOR CLIPS - SET <i>He m</i>	1	40.00	20 ✓ 40.00
FRONT LH FENDER ARCH GARNISH CLIPS - SET <i>He m</i>	1	40.00	20 ✓ 40.00
Subtotal before discount			80.00
Percentage discount 0%			0.00
Sub-total 2			80.00
Parts-total			3,062.60

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

ANDREW LEE CHEE WEI
BLK 308A PUNGGOL WALK #10-428
SINGAPORE 821308

Contact : 93833899

ESTIMATE

Repair Code : CLM16820
Date in : 02/06/2021
Vehicle Num. : SLX5497Z
Model : NISSAN QASHQAI 1.2 DIG-T CVT
Chassis/Eng# : SJNFEAJ11U2217271/HRA2584468A

LABOUR

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total

1,220.00

Parts & Labour Total

4,282.60

✓ 60.00
200 ✓ 600.00
S10 250 500.00
X 60.00

total: 2513.80
H/S: 2K ✓
02 Days.

*** This is a computer-generated document which requires no signature.***

page 2

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: