



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16

AIG BUILDING

SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 20/05/2021

ESTIMATE

NO : QUOT202105-000070(00)

DATE : 28/05/2021

POLICY NO : 999995580

VEH REG NO : SLK2008R

MAKE/MODEL : MERCEDES BENZ GLC300
4MATIC (R18 LED)

CHASSIS NO : W1N2539842F855100

ENGINE NO : 26492080086791

REG. DATE : 2021

Estimate Repair Cost to Vehicle No : SLK2008R

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Stepboard garnish - RH	1	1,280.00	1,280.00 ✓
2 Stepboard inner carrier- RH	1	360.00	360.00 ?
3 Stepboard insert - RH	1	280.00	280.00 ?
4 Stepboard top chrome - RH	1	455.00	455.00 ✓
5 Stepboard nubbed insert - RH (Front)	1	30.00	30.00 ?
6 Stepboard nubbed insert - RH (centre)	1	40.00	40.00 ?
7 Stepboard nubbed insert - RH (Rear)	1	32.00	32.00 ?
8 Stepboard clips - RH	16	9.00	144.00 ✓
			2,621.00
		Add 10%	262.10
			2,883.10
LABOUR			
9 Labour charges to remove & refit above parts	1	800.00	800.00 200
			800.00
		TOTAL	S\$ 3,683.10
		ADD GST @ 7%	257.82
		GRAND TOTAL	S\$ 3,940.92

SINGAPORE DOLLAR THREE THOUSAND NINE HUNDRED FORTY AND CENTS NINETY-TWO ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

FOR TONG LUCK AUTO PTE LTD