

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

8023E

Vehicle No: **SJQ8032Z**
 Model and make: Kia Cerato
 Chassis No: KNAFH221295036543

Qty Spare Parts**List price (\$)**

1	Bonnet lock	\$	78.00	NDX
1	Front bumper RH side retainer	\$	✓ 21.00	NECV
1	Front bumper LH side retainer	\$	✓ 21.00	
1	Front bumper reinforcement	\$	✓ 178.00	BT ✓
1	Front bumper inner sponge	\$	85.00	NSX
1	Front bumper RH fog lamp	\$	✓ 168.00	BR ✓
1	Front bumper LH fog lamp	\$	168.00	NDX
1	Front bumper lower under cover	\$	✓ 66.00	BR ✓
1	RH headlamp assy	\$	454.80	545.00 BR ✓
1	RH headlamp lower bracket	\$		24.00 NDX
1	LH headlamp assy	\$	454.80	545.00 BR ✓
1	LH headlamp lower bracket	\$		24.00 NDX
1	Support panel	\$	438.00	536.00 BT ✓
1	Aircon condenser	\$	694.00	788.00 BT ✓
1	Radiator assy	\$	646.00	718.00 BT ✓
1	Radiator fan motor	\$		373.00
1	Radiator fan blade	\$		87.00
1	Radiator fan cowling	\$		165.00

\$ 3141.60 4,470.00
 -10% \$ 314.16 447.00
 \$ 2827.44 4,023.00

Qty Spare Parts**Special Nett (\$)**

1	Carbon fibre bonnet	\$	NDX	1,200.00 BR ✓
1	Front fibre bumper	\$	745.20	950.00 BR ✓
1set	Front fibre bumper clips	\$	30.00	100.00 NECV ✓
1	Front fibre bumper centre lower wire mesh	\$	120.00	280.00 DIS ✓
1	Front fibre bumper centre upper wire mesh	\$		80.00 NDX
1	Front fibre bumper sticker	\$	40.00	120.00 NECV ✓
1	Front number plate	\$	50.00	80.00 MIS ✓
1	Radiator coolant	\$	40.00	70.00 NECV ✓

Labour and painting

Labour charges to remove, check, replace and reinstall damages bodyparts.
To panel beating, cut / weld and re-align all affected panels

\$ 600.00 ~~1,000.00~~ ✓

Spray painting on affected panels

\$ 250.00 ~~800.00~~ ✓

Check wiring and lighting system

\$ ~~80.00~~ NIX

Apply rust coating on affected areas

\$ ~~80.00~~ NIX

Remove and replace aircon condenser and pipes. To refill aircon gas

\$ 120.00 ~~220.00~~ ✓

Remove and replace radiator assy, fan assy and hoses. To refill radiator coolant

\$ 100.00 ~~200.00~~ ✓

Total: \$ 1070.00 9,283.00

Survey
28/5/2021
TGLim Lim,
1645 hrs

Resurvey
31/5/2021
Terim Lim
1335 hrs

Lump sum repair
Repair days 5

Parts 2,827.44
SN 1,025.20
Labour 1,070.00

4,922.64

@ 20% 984.53

3,938.11

L/S 3,950/2

TGLim Lim
5/7/2021

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: