



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMY 3708L

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|--|----------------------|---------------------------|-------------------|
| <u>REPLACEMENT OF PARTS</u> | | | | |
| 1 | REAR DOOR RH (CONSISTENT) | TO REPAIR SEE LABOUR | 2,930.00 | - |
| 1 | REAR DOOR WINDOW MOULDING RH (CONSISTENT) | NOT NECESSARY | 340.00 | - |
| 1 | REAR DOOR BLACK STICKER RH (CONSISTENT) | NOT NECESSARY | 199.00 | - |
| 1 | REAR DOOR HANDLE RH (CONSISTENT) | NOT NECESSARY | 194.00 | - |
| 1 | REAR DOOR LOCK RH (CONSISTENT) | NOT NECESSARY | 452.00 | - |
| 1 | REAR DOOR WEATHER STRIP INNER RH (CONSISTENT) | NOT NECESSARY | 499.00 | - |
| 1 | REAR DOOR WEATHER STRIP OUTER RH (CONSISTENT) | NOT NECESSARY | 495.00 | - |
| 1 | REAR DOOR INNER TRIM BOARD RH (CONSISTENT) | NOT NECESSARY | 1,701.00 | - |
| 1 | REAR DOOR WINDOW MOTOR RH (CONSISTENT) | NOT NECESSARY | 1,182.00 | - |
| 1 | REAR DOOR WINDOW REGULATOR RH (CONSISTENT) | NOT NECESSARY | 679.00 | - |
| 1 | REAR DOOR LOWER GARNISH RH (CONSISTENT) | NOT NECESSARY | 1,018.00 | - |
| 1 | REAR DOOR ARC GARNISH RH (CONSISTENT) | NOT NECESSARY | 501.00 | - |
| 1 | ROCKER PANEL RH (CONSISTENT) | NOT NECESSARY | 1,192.00 | - |
| | LESS 25% DISCOUNT | | -2,845.50 | - |
| | | | 8,536.50 | - |
| <u>SPECIAL NETT ITEMS</u> | | | | |
| 1 | REAR DOOR INNER TRIM CLIPS (SN) (CONSISTENT) | NOT NECESSARY | 50.00 | - |
| 1 | REAR DOOR LOWER GARNISH CLIPS (SN) (CONSISTENT) | NOT NECESSARY | 50.00 | - |
| 1 | REAR DOOR ARC GARNISH CLIPS (SN) (CONSISTENT) | NOT NECESSARY | 80.00 | - |
| | | | 180.00 | - |
| <u>LABOUR</u> | | | | |
| | TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS. | NOT NECESSARY | 200.00 | - |
| | TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS.INCLUSIVE OF THE REPAIR OF REAR DOOR RH. | | 1,000.00 | 200.00 |
| | TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS. | | 1,000.00 | 200.00 |
| | TO TUFF COAT DAMAGED AREAS . | NOT NECESSARY | 100.00 | - |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|--|---------------|---------------------------|-------------------|
| | TO RNR REAR DOOR MECHANISM TO FACILITATE REPAIRS. | NOT NECESSARY | 250.00 | - |
| | TO CHECK & REFIX ALL ELECTRICAL WIRINGS. | NOT NECESSARY | 200.00 | - |
| | TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS ,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS. | NOT NECESSARY | 300.00 | - |
| | | | 3,050.00 | 400.00 |
| GRAND TOTAL | | | 11,766.50 | 400.00 |
| RECOMMENDED COST OF REPAIRS | | | | 400.00 |

Report Ref No. CC4/ASM21006212/Dpa3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.