



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:CHAN KIAN CHUAN			Ref: CC4/ASM21006212/Dpa3q2 Date: 20/04/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHD 7190Y	Veh. Inspected	SMY 3708L
	Policy No.	P2419138	Coverage (\$)	0.00
	Claim No.	S1M03ABE	Excess (\$)	0.00
	Assign From		Assign Date	28/05/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA YARIS CROSS	c.c	1490
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	MXPB102003472	Colour	BLUE
	Odometer	13051 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/65 R16	DUNLOP	5 mm
	L/H Front Tyre	205/65 R16	DUNLOP	5 mm
	R/H Rear Tyre	205/65 R16	DUNLOP	5 mm
	L/H Rear Tyre	205/65 R16	DUNLOP	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	18/05/2021	Inspection Date	03/06/2021
	Survey held at	JWG INTERNATIONAL PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A #03-08 AMK AUTOPOINT SINGAPORE 568047		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	