



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2207471

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 02/12/2022
Reference CC6/CTI21006215/Apa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SML 2291X
Insured Veh. GBK 2845J
Claim No. SNM21D203018/C03
Policy No. DMCVSNA00059492101
Accident Date 25/05/2021
Inspection Date 27/05/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref:	CC6/CTI21006215/Apa3q2
3 ANSON ROAD #16-00			Date:	02/12/2022
SPRINGLEAF TOWERSINGAPORE 079909			Code:	CTI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBK 2845J	Veh. Inspected	SML 2291X	
Policy No.	DMCVSNA00059492101	Coverage (\$)	0.00	
Claim No.	SNM21D203018/C03	Excess (\$)	0.00	
Assign From		Assign Date	27/05/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1797	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	ZVW506130782	Colour	BLACK	
Odometer	218704 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	RAPID	6 mm	
L/H Front Tyre	195/65 R15	RAPID	6 mm	
R/H Rear Tyre	195/65 R15	RAPID	6 mm	
L/H Rear Tyre	195/65 R15	RAPID	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/05/2021	Inspection Date	27/05/2021	
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SML 2291X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DISTORTED	1,533.50	695.00
2	FRONT BUMPER SIDE RETAINER @\$62.40	N/S DAMAGED	124.80	62.40
1	FRONT BUMPER LOGO	NECESSARY	90.00	90.00
1	FRONT BUMPER TOWING COVER	DISTORTED	110.00	33.00
1	FRONT BUMPER CENTRE GRILLE	CRACKED	481.20	356.00
1	FRONT BUMPER LOWER GRILLE	CRACKED	580.00	286.00
1	FRONT BUMPER DAY LIGHT	CRACKED	588.90	588.90
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	488.70	-
2	FRONT BUMPER REINFORCEMENT BRACKET @\$270.30	NOT NECESSARY	540.60	-
1	FRONT BUMPER REINFORCEMENT SPONGE	CRACKED	155.20	155.20
1	FRONT BUMPER NUMBER PLATE HOLDER	CRACKED	130.00	130.00
1	HEADLAMP	CRACKED	2,355.60	2,355.60
1	HEADLAMP LOWER BRACKET	NOT NECESSARY	80.00	-
	LESS 25% DISCOUNT		-1,814.63	-1,188.03
			5,443.87	3,564.07
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN)	DISTORTED	50.00	50.00
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	20.00	20.00
1	SET HEADLAMP CLIPS (SN)	NECESSARY	20.00	20.00
			90.00	90.00
	<u>LABOUR</u>			
	PANEL BEATING ,REMOVAL AND REPLACING PARTS .		1,000.00	300.00
	TO SPRAY PAINT AFFECTED AREA .		1,000.00	200.00
	TUFF COAT.	NOT NECESSARY	250.00	-
	WIRING CHECK.		180.00	30.00
			2,430.00	530.00
	GRAND TOTAL		7,963.87	4,184.07



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,300.00
---	--	--	-----------------

Report Ref No. CC6/CTI21006215/Apa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SML 2291X

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SML 2291X

RE-INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

