

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: CHINA	DATE	: 25/05/2021
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SML2291X		
MODEL	: TOYOTA PRIUS ALPHA		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>	DATE : 25/05/2021 TIME : 1345HRS		
THIRD PARTY REQUESTOR / CONTACT	: JACK LI		

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Distorted</i>	1	\$ 1,533.50	\$ 1,533.50
2	FRONT BUMPER SIDE RETAINER <i>LH 2nd</i>	2	\$ 62.40	\$ 124.80
3	FRONT BUMPER LOGO <i>NEC</i>	1	\$ 90.00	\$ 90.00
4	FRONT BUMPER TOWING COVER <i>Distorted</i>	1	\$ 110.00	\$ 110.00
5	FRONT BUMPER CENTRE GRILLE <i>Cracked</i>	1	\$ 481.20	\$ 481.20
6	FRONT BUMPER LOWER GRILLE <i>Cracked</i>	1	\$ 580.00	\$ 580.00
7	FRONT BUMPER DAY LIGHT <i>Cracked</i>	1	\$ 588.90	\$ 588.90
8	FRONT BUMPER REINFORCEMENT <i>NEC</i>	1	\$ 488.70	\$ 488.70
9	FRONT BUMPER REINFORCEMENT BRACKET <i>NEC</i>	2	\$ 270.30	\$ 540.60
10	FRONT BUMPER REINFORCEMENT SPONGE <i>Cracked</i>	1	\$ 155.20	\$ 155.20
11	FRONT BUMPER NUMBER PLATE HOLDER <i>Cracked</i>	1	\$ 130.00	\$ 130.00
12	HEADLAMP <i>Cracked</i>	1	\$ 2,355.60	\$ 2,355.60
13	HEADLAMP LOWER BRACKET <i>NEC</i>	1	\$ 80.00	\$ 80.00

TOTAL PRICE \$ 7,258.50

LESS 25% \$ 1,814.63

SUB TOTAL PRICE \$ 5,443.88

4452.10

3229.97

695

62.40

23

356

286

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE <i>Disturbed</i>	1	\$ 50.00	\$ 50.00 ✓
2	FRONT BUMPER CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00 ✓
3	HEADLAMP CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00 ✓

17 TOTAL \$ 90.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,000.00	<i>300</i>	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,000.00	<i>200</i>	
3	TUFF COAT	\$ 250.00	<i>x</i>	
4	WIRING CHECK	\$ 180.00	<i>30</i>	

TOTAL

\$2,430.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 5,533.88
 TOTAL LABOUR COST : \$ 2,430.00
 TOTAL REPAIR COST : \$ 7,963.88

APPROVED DETAILS

SURVEYOR :
 CONTACT NO :
 PART BY PART / LUMP SUM :
 NO OF DAYS :

FAX :

*Adrian Lj**2/s 27/05/21**03 Days**Total 3.3K**4/s 3.3K*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: