

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21006217/KRS3Q2
Date: 11/11/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100473635
Claimant Vehicle No :	SDL8800U	Insured Vehicle No :	SFH7333E
Date of Loss:	12/05/2021	Nature of Claim:	TP
		Claim No:	8029543638SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDL8800U	Engine No:	MR20889993B
Make & Model:	NISSAN X-TRAIL, 2.0 CVT (A)	Chassis No:	JN1JANT32Z0002437
Reg. Date:	29/08/2016 (Man. Year: 2016)	Odometer:	55407 km
Colour:	Metallic Grey		
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/60 R18	Rear Tyre Size:	225/60 R18
Front Left Side:	Dunlop 3 mm	Rear Left Side:	Kinforest 8 mm
Front Right Side:	Dunlop 3 mm	Rear Right Side:	Kinforest 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	598.05	566.37	31.68	5.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	630.00	420.00	210.00	33.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,228.05	986.37	241.68	19.68
Approved Total (Overridden) (S\$)		800.00		

(S\$)	1,228.05	800.00	428.05	34.86
+ GST 7.00/7.00% (S\$)	85.96	56.00	29.96	34.85
Nett Amount (S\$)	1,314.01	856.00	458.01	34.86
+ Loss of Use (4.0 x S\$80.00/day) (S\$)		320.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,183.45		
Global Sum Settlement (S\$)		1,150.00		

INSPECTION

Date of Assignment: 28/05/2021

Date Inspected: 31/05/2021

Inspected At:

Kum Chew Motor Workshop (160 Sin Ming) (HQ)
 160 Sin Ming Drive, #05-08 Sin Ming Autocity
 Singapore 575722

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Mtg Cracked	594.10 FN	*594.10 FN
2	1		*FRT BUMPER RETAINER	N/S Distorted	70.40 FN	*35.20 FN
F=Franchise part. N=NettItemDisc.						
Sub Total (S\$)					664.50	629.30
- Nett Item Discount on N Items 10.00/10.00% (S\$)					66.45	62.93
Total Parts (S\$)					598.05	566.37

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PULL KNOCK ON FRT ACCIDENT PORTION & CHARGE THE ABOVE ARTS	New	280.00	200.00
2	TO SPRAY & PAINT ON FRT ACCIDENT PORTION	New	350.00	220.00
Gross Labour Cost (S\$)			630.00	420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >