

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 06398

Vehicle Insured : SHD2013J

Accident Date : 23-May-2021

Date : 28-May-2021

Our Ref : 021080 (III) / CHAN

PAGE : 1

CHIP HONG FARM PRODUCT
14 WOODLANDS TERRACE
Singapore 738439

*Not Notified
C/Pg 8
Missing After Paving*

ESTIMATED COST OF REPAIR FOR MIT.CANTER FEB21EA21131 YK999P

2 days

- 1 pc Rear license plate lamp
- 1 pc N/s taillamp
- 1 pc N/s taillamp bracket

PL 145.10 X
BR 275.10 —
B 155.70 —

575.90

Less 25% : 143.98

- 1 pc Rear bumper
- 2 pcs Rear bumper bracket
- 1 pc Rear chassis frame ctr member
- 1 pc Rear no.plate

@ S\$220.00

B 431.92
BT 10.1 450.00 sn —
440.00 sn —
R 250.00 sn X
B 30.00 sn
15.5
200.00 *1501*

To putty and spray replaced parts

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

4001
600.00

Total : S\$ 2,401.92

Singapore Dollars Two Thousand Four Hundred and
One and Cents Ninety Two Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: